

# IMX8X\_1N95W

## Mask Set Errata



# Mask Set Errata for Mask 1N95W

## Revision History

This report applies to mask 1N95W for these products:

- Contact your NXP representative for orderable part number information.

**Table 1. Revision History**

Revision	Date	Significant Changes
3.1	3/2023	The following errata were revised. <ul style="list-style-type: none"> <li>• ERR051393</li> </ul>
3	11/2022	The following errata were added. <ul style="list-style-type: none"> <li>• ERR051393</li> <li>• ERR051407</li> <li>• ERR051182</li> <li>• ERR051198</li> </ul>
2	9/2021	The following errata were added. <ul style="list-style-type: none"> <li>• ERR050537</li> <li>• ERR051041</li> <li>• ERR050341</li> <li>• ERR050340</li> <li>• ERR050102</li> <li>• ERR050246</li> </ul> The following errata were revised. <ul style="list-style-type: none"> <li>• ERR050395</li> </ul>
1.1	5/2020	The following errata were removed. <ul style="list-style-type: none"> <li>• ERR011439</li> </ul> The following errata were added. <ul style="list-style-type: none"> <li>• ERR011418</li> </ul>
1	4/2020	The following errata were removed. <ul style="list-style-type: none"> <li>• ERR011193</li> </ul> The following errata were added. <ul style="list-style-type: none"> <li>• ERR050395</li> <li>• ERR050145</li> <li>• ERR010527</li> <li>• ERR011370</li> </ul> The following errata were revised.

*Table continues on the next page...*

Table 1. Revision History (continued)

Revision	Date	Significant Changes
		<ul style="list-style-type: none"> <li>• ERR010946</li> <li>• ERR010944</li> <li>• ERR050068</li> <li>• ERR050066</li> <li>• ERR050125</li> <li>• ERR010945</li> <li>• ERR010947</li> </ul>
0	5/2019	Initial Revision

## Errata and Information Summary

Table 2. Errata and Information Summary

Erratum ID	Erratum Title
<a href="#">ERR050061</a>	ANALOG: DPLL loses lock under corner conditions
<a href="#">ERR050055</a>	ANALOG: DRC temperature sensor causes coupling errors
<a href="#">ERR051393</a>	Arm/Cortex-A core memory corruption
<a href="#">ERR050068</a>	AUDIO: Incorrect 24 MHz clock source at Audio Clock Mux input
<a href="#">ERR050059</a>	DC: Display write back function is not functional
<a href="#">ERR050060</a>	DC: PRG on the fly bypass switch issue
<a href="#">ERR050125</a>	DRAM: Controller automatic derating logic may not work as intended when the LPDDR4 memory temperature is above 85C at initialization
<a href="#">ERR010947</a>	DRAM: DQS/DQSN glitch suppression resistors must be enabled during read-leveling
<a href="#">ERR050054</a>	DRAM: Extra boot time is required with DDR3L ECC
<a href="#">ERR010944</a>	DRAM: In LPDDR4 mode, tMPCWR timing violation in incremental DQS2DQ Training
<a href="#">ERR010946</a>	DRAM: In LPDDR4 mode: Auto refresh must be disabled during DQS2DQ training
<a href="#">ERR050341</a>	DRAM: LPDDR4 VREF training may result in a non-optimal value
<a href="#">ERR050102</a>	DRAM: Periodic hardware based DQS2DQ calibration is not supported
<a href="#">ERR010945</a>	DRAM: PUB does not program LPDDR4 DRAM DDRPHY_MR22 prior to running DRAM ZQ calibration
<a href="#">ERR050340</a>	DRAM: The LPDDR4 DRAM initialization may experience large training time variations or stall when Read Data Bus Inversion (DBI) bit deskew training is enabled
<a href="#">ERR010948</a>	DRAM: Timing Violation from Read/Write to MRW in LPDDR4 mode
<a href="#">ERR050395</a>	ENET: Ethernet RX hang when receiving traffic through multiple queues
<a href="#">ERR011543</a>	FlexCAN: Nominal Phase SJW incorrectly applied at CRC Delimiter

*Table continues on the next page...*

Table 2. Errata and Information Summary (continued)

Erratum ID	Erratum Title
<a href="#">ERR050246</a>	FlexCAN: Receive Message Buffers may have its Code Field corrupted if the Receive FIFO function is used
<a href="#">ERR050537</a>	FlexSPI: Read timing sequence mismatches with several existing SPI NOR devices in dual, quad, and octal modes
<a href="#">ERR050057</a>	GPU: OpenCV and Vulkan conformance issue
<a href="#">ERR050067</a>	ISI: Adjacent processing pipelines within the ISI sub-system can experience loss of data
<a href="#">ERR050066</a>	ISI: Data overflows occur when input streams exceed AXI transaction frequency
<a href="#">ERR050058</a>	ISI: Incomplete frames when using virtual channels 1, 2, 3
<a href="#">ERR050145</a>	ISI: Memory overwrite occurring outside of allocated buffer space corrupting system memory
<a href="#">ERR051182</a>	ISI: U and V colors are reversed when horizontal flip is enabled in ISI configuration
<a href="#">ERR050135</a>	JPEG DECODER: multi-frame jpeg bitstream may not be correctly decoded when there is a small size frame inside
<a href="#">ERR051041</a>	LPIT: CVAL cannot be read correctly during timer running
<a href="#">ERR010527</a>	LPUART: Setting and immediately clearing SBK bit can result in transmission of two break characters
<a href="#">ERR011418</a>	MIPI DSI: Incorrect CRC and payload corruption reported with DCS long write command
<a href="#">ERR010930</a>	PCIE: EOM single point sample error/valid result is not correct
<a href="#">ERR011370</a>	PCIE: EP, PM_PME: L1 Exit Does Not Occur when PME Service Timeout Mechanism Expires
<a href="#">ERR011194</a>	PCIE: Plesiochronous loopback is not functional in PCIe Gen3
<a href="#">ERR051198</a>	PWM: PWM output may not function correctly if the FIFO is empty when a new SAR value is programmed
<a href="#">ERR050108</a>	ROM: eMMC/SD boot failure due to ROM code timeout under certain conditions
<a href="#">ERR050052</a>	ROM: NAND boot fails when image header points to an unprogrammed block
<a href="#">ERR050053</a>	ROM: USB HID device cannot be re-enumerated successfully after an unplug/plug USB cable operation
<a href="#">ERR050056</a>	SNVS: LDO startup is too slow
<a href="#">ERR050141</a>	USB2: Endpoint conflict issue in device mode
<a href="#">ERR050147</a>	USB3: Multiple DMA write transfer complete interrupts are generated before final write access handshake to the AXI bus
<a href="#">ERR050115</a>	USB3: Port Configuration Response is not compliant with the USB compliance TD 7.17 test case
<a href="#">ERR050148</a>	USB3: Race condition possible during software update to TRB in the system memory and DMA reads of same TRB
<a href="#">ERR050149</a>	USB3: TRB OUT endpoints transfer blockage and performance delays
<a href="#">ERR051407</a>	USB3: USB full speed mode may fail to work

# Known Errata

## ERR050061: ANALOG: DPLL loses lock under corner conditions

### Description

At cold temperatures, the DPLL does not lock for some parts at the extreme edge of the supply voltage tolerance.

### Workaround

The DPLL is sensitive to noise on its VDD supply, in general this is VDD\_MAIN, particularly at low temperature (< -20 degrees Celsius).

Numerous SCU related workarounds have been applied to reduce this sensitivity, however the issue remains.

The recommended workaround is close monitoring of the decoupling capacitors used on the power supply design, to ensure close proximity and a low impedance path to the regulator, as defined in the Hardware Development Guide (HDG).

Validation must include board testing at low temperature to check for any power supply sensitivity concerns.

## ERR050055: ANALOG: DRC temperature sensor causes coupling errors

### Description

DRC temperature sensor turning on and off in its normal operation couples and corrupts other analog blocks through top level metal coupling of the SoC. This causes symptoms such as variation in the DDR clock.

### Workaround

Disable DRC temperature sensor and only use the SCU temperature sensor. Little variation is seen between the readings of these 2 temperature sensors. Margin for Overheat shutdown is still sufficient to avoid damage.

## ERR051393: Arm/Cortex-A core memory corruption

### Description

A race condition in the Cortex-A CPU subsystem during initialization can cause memory setup values to be incorrectly applied to some Cortex-A cluster internal memories.

This may lead to memory corruption on some devices.

### Workaround

An SCU firmware revision implementing SCF-838 is required to modify the Cortex-A CPU subsystem initialization sequence to avoid the race condition. Updates have been integrated to Linux BSP release starting from L5.10.35.

## ERR050068: AUDIO: Incorrect 24 MHz clock source at Audio Clock Mux input

### Description

The DSC of the Audio subsystem / Audio DMA provides two 24 MHz clock sources.

One comes directly from the 24 MHz oscillator ("24\_MHz\_functional") and the other goes through SW gating used during the Reset sequence ("24\_MHz\_rst\_clk").

This second 24 MHz source is currently connected to the Audio Clock Mux (ACM) input and can be selected as the functional clock for the Audio GPT. The DSC reset clock is enabled and disabled during reset sequences, which would impact the modules using

that clock through the ACM. Note that a reset sequence can take place (e.g. for the HIFI) while audio blocks are operational. The "24\_MHz\_functional" must be used.

Only the GPT are impacted by this incorrect connection.

#### Workaround

Do NOT select the 24 MHz clock source from the ACM's (audio clock mux) GPT0...5 external clock generator. Instead, select the 24 MHz clock source available from the GPT's internal clock multiplexer, which comes from the correct source. That is to say, within the GPT Control Register (CR), CLKSRC[8:6] must use "101b - Crystal oscillator as the Reference Clock (ipg\_clk\_24M)", and avoid use of the "011b - External Clock".

### ERR050059: DC: Display write back function is not functional

#### Description

The mechanism to enable an output stream to a display and also to be copied into memory using one of the internal camera streams is not functional due to the pixel link receiver address being incorrectly tied-off.

#### Workaround

The display controller signature unit (CRC) can be used to check for display changes.

### ERR050060: DC: PRG on the fly bypass switch issue

#### Description

When the display controller switches the DPR/PRG from bypass to non-bypass on the fly, it causes a sync error. A screen artifact (3-4 lines of the overlay) can be seen at the top of the overlay. The bypass to non-bypass on the fly switch can occur when the overlay pixel format changes from DPR/PRG unsupported to supported.

#### Workaround

Careful timing of the overlay change can hide this problem. Following the sequence "overlay OFF – 1 frame – overlay ON" can also hide the problem. Because this workaround requires a deterministic handling of interrupts, a non-realtime OS, such as Linux, cannot guarantee the timing of the overlay change.

### ERR050125: DRAM: Controller automatic derating logic may not work as intended when the LPDDR4 memory temperature is above 85C at initialization

#### Description

LPDDR4 memories require periodic refreshes to maintain memory contents. Per the JEDEC specification JESD209-4 the memory refresh rate needs to increase and timings de-rated as the memory operational temperature exceeds vendor-defined temperature thresholds. The LPDDR4 Mode Register 4 (MR4) contains temperature/refresh rate information and a Temperature Update Flag (TUF).

An issue exists with the automatic derating logic of the DDR controller that only samples the LPDDR4 MR4 register when the Temperature Update Flag (TUF) field (MR4[7] ) is 1'b1. If the LPDDR4 memory is initialized and starts operation above 85°C (MR4[2:0] > 3'b011), the MR4 Temperature Update Flag (TUF) will not set. The DDR Controller will therefore not automatically adjust the memory refresh rate or de-rate memory timings based on the LPDDR4 memory temperature. This may result in the controller incorrectly setting the refresh period, potentially causing the LPDDR4 memory losing data contents and leading to possible data integrity issues above 85°C. The actual memory temperature threshold values may vary depending on memory vendors.

If the LPDDR4 memory temperature remains below 85°C at initialization (Consumer-grade memory devices), then the derating logic works as intended, automatically adjusting the memory refresh period and memory timing during the entire system operation. The issue does not occur in this specific scenario since derating is not required.

This erratum does not impact other SoC supported DDR memory interfaces such as DDR4 or DDR3L.

#### Workaround

The software workaround for LPDDR4 based systems is to check the memory temperature via the MR4 and determine if it is above 85°C at initialization. If the temperature is below 85 then automatic temperature derating logic is left enabled (default setting), otherwise the derating logic is disabled and software should manually adjust the memory refresh rate and memory timings. Once the memory temperature is below 85C (MR4[2:0] == 3'b011), the software should readjust the memory refresh rate and memory timings to nominal settings and then re-enable the automatic derating logic.

The software workaround has been integrated into the BSP GA release : (imx\_4.14.98\_2.0.0\_p1 (SCFW v1.2.1))

### ERR010947: DRAM: DQS/DQSN glitch suppression resistors must be enabled during read-leveling

#### Description

By default DQS/DQSN glitch suppression resistors are disabled. When external DQS/DQSn are not driven to valid differential states, the DQS cell's core-side outputs become unknown. This causes errors in the read-leveling gate training.

#### Workaround

Enable the strongest 355 ohm glitch suppression resistors during gate training. Scripts provided by NXP's DRAM RPA (Register Programming Aid) implement the required workaround through DDRPHY\_DX8SLbDQCTL register.

### ERR050054: DRAM: Extra boot time is required with DDR3L ECC

#### Description

For DDR3L with ECC, due to design limitations and ECC scrub requirements, the SCU must initialize the entire memory for ECC before beginning to load the M4 image. This requires up to 300 msecs extra.

#### Workaround

The future planned fix will initialize only a small region of RAM, reduce the impact on boot time.

### ERR010944: DRAM: In LPDDR4 mode, tMPCWR timing violation in incremental DQS2DQ Training

#### Description

In LPDDR4 mode with incremental DQS2DQ Training enabled and speed grade > 2133 Mbps, the hardware incremental dqs2dq training routine performs Power Down (PD) Entry-Exit Cycle to reset the MPC WR-RD FIFO pointers in the DRAM. The PUB sends the MPC WRFIFO command after waiting for tXP from PD Exit. However, JEDEC specification requires waiting an additional tMPCWR after tXP timing. This extra tMPCWR timing is not handled by the PUB Training algorithm, resulting in a violation of tMPCWR JEDEC parameter.

#### Workaround

Do not run incremental DQS2DQ Training of the PHY in LPDDR4 mode.

## ERR010946: DRAM: In LPDDR4 mode: Auto refresh must be disabled during DQS2DQ training

### Description

If auto refresh is enabled during DQS2DQ training, a JEDEC Specification violation may occur. Auto refresh must be disabled during DQS2DQ training, which is performed during initial power-up (cold boot).

### Workaround

For initial power-up (cold boot), disable auto refresh during DQS2DQ training. For self-refresh (warm boot), do not run DQS2DQ training. Restore the saved register values prior to self-refresh entry. Scripts provided by NXP's DRAM RPA (Register Programming Aid) implement the required workaround.

## ERR050341: DRAM: LPDDR4 VREF training may result in a non-optimal value

### Description

During LPDDR4 initialization, when performing LPDDR4 VREF training (through DDRPHY\_PIR[VREF]), a discrepancy may be observed between the training-generated DDRPHY\_MR14 value and an actual signal-measured VREF\_DQ value such that the "trained" DDRPHY\_MR14 value may not result in the most optimal VREF\_DQ setting. However, the discrepancy is minimal such that no DRAM data failures have occurred due to this.

### Workaround

A software workaround has been included in the SCU firmware (SCFW) since version 1.4.0. The software workaround has been included in the MX8QXP DDR Register Programming Aid (RPA) since RPA version 14.

## ERR050102: DRAM: Periodic hardware based DQS2DQ calibration is not supported

### Description

If periodic hardware based DQS2DQ calibration is enabled, the resultant latency introduced can cause underrun conditions, or worst case a lock-up, in some of the key sub-systems, such as the display and imaging interfaces, impacting their performance capabilities.

### Workaround

Currently DQS2DQ calibration only takes place on power up and when resuming from low power modes. To date no failures or stability issues have been observed across the full process, voltage and temperature ranges.

## ERR010945: DRAM: PUB does not program LPDDR4 DRAM DDRPHY\_MR22 prior to running DRAM ZQ calibration

### Description

When the PHY Utility Block (PUB) initializes the DRAM, the DDRPHY\_MR22 is programmed after ZQ Calibration. This may result in incorrect ZQ calibration results on the LPDDR4 DRAM side, because DDRPHY\_MR22[CODT] works as the controller On Die Termination (ODT) replica during the Pull-Up calibration. Therefore the expected controller ODT must be programmed into DDRPHY\_MR22 prior to the DRAM ZQ calibration.

### Workaround

Run DRAM Initialization twice. Scripts provided by NXP's DRAM RPA (Register Programming Aid) implement the required workaround.



## ERR050340: DRAM: The LPDDR4 DRAM initialization may experience large training time variations or stall when Read Data Bus Inversion (DBI) bit deskew training is enabled

### Description

Read DBI bit deskew training is an extension of the Read bit deskew training. When performing LPDDR4 Read bit deskew training (through the DDRPHY\_PIR register), the following issues may be encountered:

- When Read DBI deskew training is enabled (DDRPHY\_DTCCR0.DTRDBITR = 2'bx1), there is a possibility to observe large training time variations or even a stall
- When Read DBI deskew training is disabled (DDRPHY\_DTCCR0.DTRDBITR = 2'bx0), incorrect values are programmed in DDRPHY\_DXnBDLR5 (i.e. the DM Read BDL) after Read bit deskew training is completed

### Workaround

A software workaround has been included in the SCU firmware (SCFW) since version 1.3.0. The software workaround has been included in the MX8QXP DDR Register Programming Aid (RPA) since RPA version 13.

## ERR010948: DRAM: Timing Violation from Read/Write to MRW in LPDDR4 mode

### Description

When software sends a MRW command in parallel with a Read/Write transaction, the Read/Write command can be followed by the MRW command, which can result in the following timing violations:

1. RD to MRW
2. RDA to MRW
3. WRA/MWRA to MRW

This can occur only in LPDDR4 mode. When the memory clock frequency is lower than 450 MHz, then one of above 3 violations may occur, when the memory clock frequency is NOT lower than 450 MHz, then above item 1 or item 2 violation may occur.

The above timing constraints were introduced in the LPDDR4 specification JESD209-4A.

### Workaround

MRW commands sends in parallel with a Read/Write transaction must follow a specific sequence.

## ERR050395: ENET: Ethernet RX hang when receiving traffic through multiple queues

### Description

Two or more applications are enabled to share the same Ethernet module by using different queues. At least 2 queues are configured to receive packets, with flushing enabled (RX\_FLUSHx). When queues become full, packets are normally flushed, but under certain conditions of traffic, a lock-up of the Rx path can happen instead. When this occurs, the buffer descriptor for the last received packet contains an incorrect packet size (equal to the maximum buffer size). Packets cannot be received anymore, but the TX path remains unaffected. To recover the RX path, the ENET hardware block must be reset and re-configured.

### Workaround

Unless the use case demands it, disable flushing to ensure the problem does not happen.

Or if reset is acceptable:

To recover the RX path, the ENET hardware block must be reset and re-configured

## ERR011543: FlexCAN: Nominal Phase SJW incorrectly applied at CRC Delimiter

### Description

During the reception of a CAN-FD frame when the Bit Rate Switch (BRS) is enabled, the Synchronization Jump Width (SJW) for the CRC Delimiter bit is incorrectly defined by the Nominal Phase SJW. The CAN specification stipulates that the CRC Delimiter bit should have a SJW set by the Data Phase SJW.

When a resynchronization event is triggered for the CRC delimiter bit (recessive in correct operation), the sample point will be adjusted by an amount as defined by the Nominal Phase SJW rather than the specified Data Phase SJW. This may result in the incorrect detection of a dominant bit leading to a CAN error frame. However, as the CRC delimiter bit position will only apply the SJW upon the detection of an unexpected dominant bit on the CAN bus, an error frame is already likely. For the case the SJW is applied at the CRC delimiter and a recessive bit is not detected, the receiving node will issue an error frame.

The CAN protocol is designed to handle resynchronization errors and hence the CAN bus will recover from the insertion of the incorrect SJW at the CRC delimiter. Upon detecting the error frame the transmitting node will re-transmit the frame.

The following FlexCAN configurations are not affected:

- Classical CAN frames (CAN 2.0B)
- CAN FD frames with bit rate switch disabled (BRS = 0)
- CAN FD frames with Nominal Phase SJW equal to Data Phase SJW
- CAN FD transmissions

Configuration for the FlexCAN:

- Nominal Phase SJW is configured by the Resync Jump Width bit in the CAN Control Register 1 (CAN\_CTRL1[RJW]) or by the Extended Resync Jump Width bit in the CAN Bit Timing Register (CAN\_CBT[ERJW])
- Data Phase SJW is configured by the Fast Resync Jump Width bit in the CAN FD Bit Timing Register (CAN\_FDCBT[FRJW])

### Workaround

The robustness of the CAN protocol ensures that the receiver automatically recovers from the application of the incorrect SJW. The CAN protocol is designed to recover from resynchronization errors and hence any frame that is not correctly received will be re-sent by the transmitting node.

## ERR050246: FlexCAN: Receive Message Buffers may have its Code Field corrupted if the Receive FIFO function is used

### Description

If the Code Field of a Receive Message Buffer is corrupted it may deactivate the Message Buffer, so it is unable to receive new messages. It may also turn a Receive Message Buffer into any type of Message Buffer as defined in the Message buffer structure section in the device documentation.

The Code Field of the FlexCAN Receive Message Buffers (MB) may get corrupted if the following sequence occurs.

- 1- A message is received and transferred to an MB (i.e. MBx)
- 2- MBx is locked by software for more than 20 CAN bit times (time determines the probability of erratum to manifest).
- 3- SMB0 (Serial Message Buffer 0) receives a message (i.e. message1) intended for MBx, but destination is locked by the software (as depicted in point 2 above) and therefore NOT transferred to MBx.
- 4- A subsequent incoming message (i.e. message2) is being loaded into SMB1 (as SMB0 is full) and is evaluated by the FlexCAN hardware as being for the FIFO.
- 5- During the message2, the MBx is unlocked. Then, the content of SMB0 is transferred to MBx and the CODE field is updated with an incorrect value.

The problem does not occur in cases when only Rx FIFO or only a dedicated MB is used (i.e. either RX MB or Rx FIFO is used). The problem also does not occur when the Enhanced Rx FIFO and dedicated MB are used in the same application. The problem only occurs if the FlexCAN is programmed to receive in the Legacy FIFO and dedicated MB at the same application.

### Workaround

This defect only applies if the Receive FIFO (Legacy Rx FIFO) is used. This feature is enabled by RFEN bit in the Module Control Register (MCR). If the Rx FIFO is not used, the Receive Message Buffer Code Field is not corrupted.

If available on the device, use the enhanced Rx FIFO feature instead of the Legacy Rx FIFO. The Enhanced Rx FIFO is enabled by the ERFEN bit in the Enhanced Rx FIFO Control Register (ERFCR).

The defect does not occur if the Receive Message Buffer lock time is less than or equal to the time equivalent to 20 x CAN bit time.

The recommended way for the CPU to service (read) the frame received in a mailbox is by the following procedure:

1. Read the Control and Status word of that mailbox.
2. Check if the BUSY bit is deasserted, indicating that the mailbox is not locked. Repeat step 1) while it is asserted.
3. Read the contents of the mailbox.
4. Clear the proper flag in the IFLAG register.
5. Read the Free Running Timer register (TIMER) to unlock the mailbox

In order to guarantee that this procedure occurs in less than 20 CAN bit times, the MB receive handling process in software (step 1 to step 5 above) should be performed as a 'critical code section' (interrupts disabled before execution) and should ensure that the MB receive handling occurs in a deterministic number of cycles.

## ERR050537: FlexSPI: Read timing sequence mismatches with several existing SPI NOR devices in dual, quad, and octal modes

### Description

The FlexSPI controller expects every read command has at least one latency cycle between address phase and data phase to account for turnaround time on the IO bus. In multiple IO modes such as dual, quad, and octal modes, the FlexSPI controller inserts one additional clock cycle following the address (or command modifier) phase in order to prevent contention on bidirectional IO pins.

It will cause drive conflict if the SPI NOR device's timing sequence does not contain dummy cycles after the command/address cycles. Such drive conflict might result in reading wrong data value. The problem usually happens when reading a SPI slave's register space.

### Workaround

For FlexSPI memory device that supports multi IO Read command with zero latency cycle between address phase and data phase, use single line mode for read command, or use different data line to issue commands and read data.

The official NXP BSP release uses a signal line (1S-1S-1S) mode, but not multiple IO modes when access FlexSPI device registers.

## ERR050057: GPU: OpenCV and Vulkan conformance issue

### Description

GPU may hang when running OpenCV or Vulkan conformance tests under corner conditions.

### Workaround

Software workaround has been integrated into L4.14 BSP release and later release. This workaround has a small performance impact <1% during OpenCV or Vulkan tests.

## ERR050067: ISI: Adjacent processing pipelines within the ISI sub-system can experience loss of data

### Description

Using adjacent channels where one channel's line ends when the next channel's line begins (common in virtual channel functionality) can cause the second channel to skip a line every 8 or 16 lines.

Using adjacent channels can also effect the width and format of the line by creating a final write that does not fill a 128 byte buffer.

### Workaround

For virtual channel applications the pipeline order can be adjusted to avoid adjacent channel assignments, for example, VC 0, 1, 2, and 3 assigned to pipelines 0, 2, 1, 3.

## ERR050066: ISI: Data overflows occur when input streams exceed AXI transaction frequency

### Description

The Image Sensing Interface (ISI) has a short elasticity buffer relative to the length of a line. The buffer can be as few as 85 pixels or as many as 512 pixels depending on the output format. Most RGB formats have 128 pixels. Because of the short buffer, if there is any delay in latency, then an overflow can occur. The possibility of overflow increases when the number of active channels increases.

In addition, memory reads and the last line of a scaling process consume data as fast as possible (instead of at the rate of the incoming pixel stream), therefore, the output buffer fills faster and requires even lower latency to process the data.

### Workaround

The design target was intended to support up to a single 8 Mpixel (4K) stream at 30 fps, or multiple streams up to the equivalent data rate. However, combinations of sensors which add up to less than 2Mpixel are supported with current design. That's to say, if 1 sensor is used, 2Mpixels stream can be supported; if 2 sensors are used, 1Mpixels of each stream can be supported; and so on.

In the case of scaling, the last line of each frame must be cropped and discarded.

To reduce overflow possibility, one possibly way is to lower ISI clock which help slow down the data to output buffer.

## ERR050058: ISI: Incomplete frames when using virtual channels 1, 2, 3

### Description

Except for virtual channel 0, virtual channels 1, 2, and 3 do not have proper VSYNC timing from MIPI CSI2 when different cameras are multiplexed together. As a result, frames stored in memory can be corrupted due to missing last lines.

### Workaround

Virtual channels 1, 2, and 3 do not work normally for multiplexed cameras. Only single camera operation is supported by the MIPI CSI2 interface.

## ERR050145: ISI: Memory overwrite occurring outside of allocated buffer space corrupting system memory

### Description

Under marginal timing conditions, when an incomplete frame is received, resulting in an early or late VSYNCH error, it is possible for the ISI to overwrite system memory outside its allocated buffer space, resulting in unpredictable behavior.

### Workaround

To prevent this, the xRDC can be programmed to grant write access to the ISI only within its allocated frame buffer space. User applications must ensure the SCFW creates an ISI domain containing the ISI itself and its frame buffers, which will prevent overwrites into system memory. The ISI can generate an interrupt to indicate an exception has occurred, if required.

## ERR051182: ISI: U and V colors are reversed when horizontal flip is enabled in ISI configuration

### Description

When ISI horizontal flip is enabled in YUYV mode, colors are wrong because U and V are reversed.

### Workaround

Do not use ISI horizontal flip. If horizontal flip is required, use sensor or G2D library to perform flip.

## ERR050135: JPEG DECODER: multi-frame jpeg bitstream may not be correctly decoded when there is a small size frame inside

### Description

When the JPEG decoded frame with a resolution that is no larger than 64x 64 and it is followed by a next decoded frame with a larger resolution, then this next decoded frame may be corrupted.

### Workaround

The decoded image resolution should be larger than 64x 64.

## ERR051041: LPIT: CVAL cannot be read correctly during timer running

### Description

The LPIT implements a functional clock domain for the counter and a bus clock domain for the register interface. The CVAL register increments on each clock cycle of the functional clock domain. Reading the register value happens on the bus clock domain. As these clock domains are not synchronous, there is a possibility that the register is read whilst the counter value is updating. This can lead to reading incorrect values as some bits of the counter may have settled whilst others are still transitioning to the new state.

### Workaround

There should be no need to read the timer value since the timer is normally used to generate a periodic interrupt. However, if the timer value needs to be read, software can read the register more than once until the value matches the previous value. This ensures that the read operation did not coincide with the timer update and the value read is the actual timer value.

## ERR010527: LPUART: Setting and immediately clearing SBK bit can result in transmission of two break characters

### Description

When the LPUART transmitter is idle (LPUART\_STAT[TC]=1), two break characters may be sent when using LPUART\_CTRL[SBK] to send one break character. Even when LPUART\_CTRL[SBK] is set to 1 and cleared (set to 0) immediately.

### Workaround

To queue a single break character via the transmit FIFO, set LPUART\_DATA[FRETSC]=1 with data bits LPUART\_DATA[T9:T0]=0.

## ERR011418: MIPI DSI: Incorrect CRC and payload corruption reported with DCS long write command

### Description

When the DSI packet payload[23:8] is equal to 0x0, either an incorrect CRC is generated or an extra two bytes of incorrect CRC values at 0xFF are sent erroneously corrupting the payload. The issue only happens under low-power mode transmit.

### Workaround

Avoid software with a packet payload[23:8] equal to 0x0 or else use high-speed mode to send commands.

## ERR010930: PCIE: EOM single point sample error/valid result is not correct

### Description

There is an eye monitor in the SerDes analysis which can monitor the following:

- a. Error and valid bits of a certain duration
- b. Eye width
- c. Eye height
- d. Eye area

However, there is a design issue with item (a) causing incorrect error/valid bit results.

### Workaround

Customers must not use the error/valid count results to check the eye quality. Instead, use the eye width, eye height, or eye area.

## ERR011370: PCIE: EP, PM\_PME: L1 Exit Does Not Occur when PME Service Timeout Mechanism Expires

### Description

Impacted Configuration(s): Upstream Port configurations:

device\_type =4'b0000, located at PCIEX1\_CTRL0, address 0x5f140000, bit[27:24]

Defect Summary:

When a function issues a PM\_PME Message, it sets the PME\_Status bit. If the Downstream port has not cleared the PME\_Status bit within 100ms, a PME Service timeout occurs.

At this point, the Upstream port must resend the PM\_PME message.

In the current implementation of the controller, the PME Service timeout does not trigger an exit from L1 to resend the PM\_PME message.

System Usage Scenario:

Upstream ports using a wake-up mechanism followed by a power management event (PME) message.

Consequence(s):

The defect has the following effect:

The PME service routine cannot make forward progress until the PM\_PME message is resent.

#### Workaround

Poll the PME\_Status bit after sending the PME message to exit L1 state. If this bit remains 1 for 100ms or more, SW must re-toggle bit 8 "APPS\_PM\_XMT\_PME" of HSIO GPR register "PCIEX1\_CTRL2", address 0x5f140008.

## ERR011194: PCIe: Plesiochronous loopback is not functional in PCIe Gen3

### Description

Customers should be using mesochronous loopback when sending arbitrary bit streams.

Plesiochronous loopback: Is loopback from Rx back to Tx after the PCIe elastic buffer function in the PCS.

The intent of this reverse loopback scheme is to send arbitrary bit-streams through the elastic FIFO on the Rx side of the PCS and back through the Tx side of the PCS into the PMA. However, this does not work at Gen3 speed. This mode is not practical because the entire PCS PCIe pipeline is designed for protocol-dependent data, and requires many bypass paths to enable arbitrary bit streams through it. Moreover, there is no way to support elasticity when the bit-stream is protocol-agnostic, rendering the elastic FIFO useless.

Mesochronous (meso) loopback: Is loopback from Rx back to Tx before any elastic buffer, hence requiring 0ppm frequency difference between TxClk and RxClk, and requires TxClk and RxClk to be phase-adjusted using an automatic CDR skip-bit routine (as described in the PUG). Meso loopback assumes that the intersection set of the setup+hold margin for all 20 bits in the Rx to Tx STA path has a large open window. The SDC constraints were originally intended to contain max\_delay and min\_delay constraints to ensure this, but customers may not have optimized the window. Historically, mesochronous mode rarely worked at the highest protocol speeds due to this dependency on customer's timing optimization.

### Workaround

Customers must use meso loopback when sending arbitrary bit streams.

## ERR051198: PWM: PWM output may not function correctly if the FIFO is empty when a new SAR value is programmed

### Description

When the PWM FIFO is empty, a new value programmed to the PWM Sample register (PWM\_PWMSAR) will be directly applied even if the current timer period has not expired.

If the new SAMPLE value programmed in the PWM\_PWMSAR register is less than the previous value, and the PWM counter register (PWM\_PWMCNR) that contains the current COUNT value is greater than the new programmed SAMPLE value, the current period will not flip the level. This may result in an output pulse with a duty cycle of 100%.

### Workaround

Program the current SAMPLE value in the PWM\_PWMSAR register before updating the new duty cycle to the SAMPLE value in the PWM\_PWMSAR register. This will ensure that the new SAMPLE value is modified during a non-empty FIFO, and can be successfully updated after the period expires.

## ERR050108: ROM: eMMC/SD boot failure due to ROM code timeout under certain conditions

### Description

This issue is related to boot from eMMC or SD devices.

On power-up, a boot monitor timer is initialized. On a successful boot, SECO firmware is loaded and run from the boot device—that is, eMMC or SD, which, after loading and verifying SCU firmware (SCFW), disables the timer. When a successful boot requires more than 300 msecs, a timeout occurs that is considered a boot failure, and therefore generates a warm reset, which results in a looping boot failure.

Typically, the initialization time for most eMMC/SD devices is about 100 to 200 msecs, however, the eMMC/SD specification allows up to 1 second for this initialization time.

Any eMMC/SD device that exceeds the timeout to initialization will fail to boot. Sudden power loss or power cycle stress testing to eMMC/SD devices can cause data corruption, which can force the eMMC/SD device to run an internal data check on the next power up, which results in a longer initialization time, forcing a timeout and a looping boot failure.

### Workaround

Generally reducing eMMC/SD initialization time under 300 msecs is the most effective way to avoid this looping boot failure.

For the data corruption case, change the boot mode to serial download mode then load and run an image via USB. This image can initialize the eMMC/SD device and exit out of the internal data check state.

In future silicon releases, ROM will consider this case and wait 1 second to avoid the boot failure.

## ERR050052: ROM: NAND boot fails when image header points to an unprogrammed block

### Description

ROM first reads the Image Container Set 0 header, and then the Image Container Set 1 header, unless the secondary boot has been disabled by a fuse, in which case the Set 1 header will not be read. ROM will then select the header with the newest software version for primary boot and the oldest one for secondary boot.

For NAND boot, the block where the Image Container Set 0 is programmed is specified by fuses. If the specified block has been erased or has random data on it, the NAND read API returns a failure. In this case, ROM will attempt to read from the block with the Image Container Set 1 header programming, which is also specified by fuses.

However, there is a bug in the ROM code. It will not read data from the block with the Image Container Set 1 header, and instead continues to read data from the block with the Image Container Set 0 header. However, because this block has not been programmed boot failure occurs, even if there is a valid Image Container Set 1 header available.

### Workaround

Avoid upgrading Image Container Set 0. Only upgrade Image Container Set 1 if the boot image needs upgraded. Per detailed description, ROM always tries to read both image container sets and selects the one with the newest software version to boot.

## ERR050053: ROM: USB HID device cannot be re-enumerated successfully after an unplug/plug USB cable operation

### Description

The USB HID device enumerates successfully on the Host side when booting from serial download mode. However, after disconnecting the USB cable and re-connecting the cable again, the USB HID device will not re-enumerate on Host side because ROM incorrectly resets the USB.



### Workaround

Reset the device, or power down and re-power on the device.

## ERR050056: SNVS: LDO startup is too slow

### Description

SNVS startup on LDO is too slow at low temperature with VDD\_SNVS less than 2.8V. This issue may cause some parts to take longer to startup due to boot retry in SCU. The boot time to M4 operation may increase from <50ms to around 80ms because of the re-boot attempts.

### Workaround

The workaround is to ensure that voltage is maintained at, or above, 2.8 volts at low temperature.

## ERR050141: USB2: Endpoint conflict issue in device mode

### Description

An endpoint conflict occurs when the USB is working in device mode and an isochronous IN endpoint exists.

When the endpointA IN direction is an isochronous IN endpoint, and the host sends an IN token to endpointA on another device, then the OUT transaction may be missed regardless the OUT endpoint number. Generally, this occurs when the device is connected to the host through a hub and other devices are connected to the same hub.

The affected OUT endpoint can be either control, bulk, isochronous, or an interrupt endpoint.

After the OUT endpoint is primed, if an IN token to the same endpoint number on another device is received, then the OUT endpoint may be unprimed (Cannot be detected by SW), which causes this endpoint to no longer respond to the host OUT token, and thus, no corresponding interrupt occurs.

### Workaround

Do not connect to a hub in the case when ISO IN endpoint(s) is used. When the hub(s) must be connected in this scenario, the endpoint number(s) of the ISO IN endpoint(s) should be different from the endpoint number(s) of any type of IN endpoint(s) used in any other device(s) connected to the same host.

## ERR050147: USB3: Multiple DMA write transfer complete interrupts are generated before final write access handshake to the AXI bus

### Description

In USB device mode and Multiple DMA transfers mode, the DMA write-transfer-complete-interrupt is generated multiple clock cycles after the final DMA write access on the AXI bus. The transfer does not wait for completion of the system memory write access handshake.

Delay between the last DMA write access and the DMA interrupt request is determined by an internal operation of the DMA and lasts longer than 50ns. The current DMA interrupt request delay is shorter after DMA write access. Within the interrupt handler, software checks the interrupt source to determine which source introduces the additional delay. During these checks, software has the opportunity to access the system memory data before the DMA write is complete.

This issue may be critical for AXI interconnects that use buffering for write accesses. For these systems, READ access to the system memory may be executed before the WRITE access is complete to the same location even if the WRITE access was requested much earlier than read access.

### Workaround

Using Singular DMA transfer mode can avoid this issue, by setting DSING to 1 and set DMULT to 0 in register USB\_CONF.

## ERR050115: USB3: Port Configuration Response is not compliant with the USB compliance TD 7.17 test case

### Description

USB 3.0 Compliance TD 7.17 test case is used to verify that a downstream PUT will go to SS.Inactive if tPortConfiguration expires, and an upstream PUT will go to SS.Disabled if tPortConfiguration expires. However, this test case fails because the port configuration response is not compliant with the TD 7.17 test case.

This requirement is not present in the USB 3.0 specification, however, the USB 3.0 compliance TD 7.17 test case requires it. This test does not affect user applications and it does not affect USB 3.0 function.

### Workaround

To pass the USB compliance test waive the TD 7.17 tPortConfiguration test.

## ERR050148: USB3: Race condition possible during software update to TRB in the system memory and DMA reads of same TRB

### Description

Transfer Ring Block (TRB) data structure is larger than 64-bit and therefore requires two separate read accesses on a 64-bit data bus. Because of race conditions between software updates to TRB and DMA reads of the TRB, it is possible that DMA read access may be interleaved with the software write access to the same TRB. The race condition might cause TRB content read by DMA to be inconsistent leading to data corruption during the USB transfer.

This situation can occur in USB device mode.

Critical race condition scenario:

Initial assumption: TRB ownership (cycle bit) is set to software and software is expected to update TRB sequence of events.

1. DMA reads first part of TRB that stores pointer to the USB data buffer.
2. Software writes first part of the TRB and sets new value of the pointer.
3. Software writes second part of the TRB that stores TRB ownership bit (cycle bit) and sets ownership to DMA.
4. DMA reads second part of the TRB and determines that ownership is set to DMA and begins processing data buffer using incorrect pointer that has been fetched during step 1.

### Workaround

Recommend software driver workaround:

Software checks DMA enqueue and dequeue pointers to determine status of the DMA ring. If the DMA is near the end of the TRB ring the software postpones the update of the ownership bit in the system memory. Software waits until DMA stops and reports the end of the transfer ring by indicating a "descriptor missing" interrupt. The ownership (cycle) bit is updated by software when the DMA is stopped.

Limitations of the Software workaround:

There is a potential performance impact although none observed in real applications.

## ERR050149: USB3: TRB OUT endpoints transfer blockage and performance delays

### Description

During USB device mode, the on-chip buffer for OUT endpoints is implemented as a FIFO queue for all USB OUT packets.

All configured and enabled Device OUT endpoints are ready to receive OUT data packets when the Device FIFO queue is available whether or not the TRB ring is prepared by software and whether the DMA is ready to read OUT packets.

When an OUT packet is received but the DMA is not prepared for transfer (TRB is missing) the DMA generates a "descriptor missing" interrupt to notify software that the transfer ring for DMA should be prepared.

Linux Class driver cannot guarantee creation of the TRB in response to "descriptor missing" interrupt.

### Workaround

Recommend software driver workaround:

In response to the "descriptor missing" interrupt the software driver prepares the local buffer and enables DMA to receive data from the OUT FIFO to the local buffer in the system memory.

Limitations of the software workaround:

- The local buffer created by the software driver may overflow when a USB Class Application in Linux does not receive data for an extended time.
- The "Descriptor missing" interrupt service impacts application performance (particularly ISO transfers) especially when the "descriptor missing" interrupt is serviced with extended delays.

## ERR051407: USB3: USB full speed mode may fail to work

### Description

USB3 module supports USB3 .0 PHY and USB2.0 PHY. Very limited parts may fail to work on full speed mode (both host and device modes) for USB3 port due to higher threshold in full speed receiver of USB2.0 PHY. One example failure symptom is, the enumeration is failed when connecting full speed USB mouse to USB3 port, especially under high temperature.

### Workaround

The recommended workaround is to configure threshold voltage value of single ended receiver by setting USB2.0 PHY register AFE\_RX\_REG5[2:0] to 3'b101 (Register Address is 0x5B198048). The workaround has been integrated to Linux BSP release starting from L5.10.9\_1.0.0.

# Legal information

## Definitions

**Draft** — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

## Disclaimers

**Limited warranty and liability** — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

**Right to make changes** — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Suitability for use** — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

**Applications** — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

**Terms and conditions of commercial sale** — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at <http://www.nxp.com/profile/terms>, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

**Suitability for use in automotive applications** — This NXP product has been qualified for use in automotive applications. If this product is used by customer in the development of, or for incorporation into, products or services (a) used in safety critical applications or (b) in which failure could lead to death, personal injury, or severe physical or environmental damage (such products and services hereinafter referred to as "Critical Applications"), then customer makes the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, safety, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP. As such, customer assumes all risk related to use of any products in Critical Applications and NXP and its suppliers shall not be liable for any such use by customer. Accordingly, customer will indemnify and hold NXP harmless from any claims, liabilities, damages and associated costs and expenses (including attorneys' fees) that NXP may incur related to customer's incorporation of any product in a Critical Application.

**Export control** — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

**Translations** — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.

**Security** — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately.

Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at [PSIRT@nxp.com](mailto:PSIRT@nxp.com)) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

## Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

**NXP** — wordmark and logo are trademarks of NXP B.V.

---

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

---

© NXP B.V. 2023.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: 3/2023

Document identifier: IMX8X\_1N95W