

ERRATA SHEET

Date: 2008 April 8
Document Release: Version 1.5
Device Affected: LPC2364

This errata sheet describes both the functional problems and any deviations from the electrical specifications known at the release date of this document.

Each deviation is assigned a number and its history is tracked in a table at the end of the document.

2008 April 8

Document revision history

Rev	Date	Description
1.5	April 8 2008	1. Added Vbat.1
1.4	September 21 2007	1. Added Rev B 2. Removed Rev A from ESD.1. ESD.1 does not appear in Rev A. It was accidentally listed in version 1.3
1.3	July 20 2007	1. Added Ethernet.3 2. Added Deep Power Down Mode.1 3. Updated Flash.1 4. Updated Ethernet.1
1.2	June 7 2006	1. Added Rev A 2. Added Flash.1, MAM.1 and CAN.1
1.1	March 22 2007	1. Corrected the value of M in PLL.1 2. Updated ESD.1 3. Added core.1
1.0	November 14 2006	First version

Identification

The typical LPC2364 devices have the following top-side marking:

LPC2364xxx

xxxxxxx

xxYYWW R[x]

The last/second to last letter in the third line (field 'R') will identify the device revision. This Errata Sheet covers the following revisions of the LPC2364:

Revision Identifier (R)	Comment
'-'	Initial device revision
'A'	Second device revision
'B'	Third device revision

Field 'YY' states the year the device was manufactured. Field 'WW' states the week the device was manufactured during that year.

Errata Overview - Functional Problems

Functional Problem	Short Description	Device Revision the problem occurs in
ADC.1	ADDRx read conflicts with hardware setting of DONE bit	-
Ethernet.1	Setting up the Ethernet interface in RMII mode	-
Ethernet.2	Ethernet SRAM disabled	-
Ethernet.3	RxDescriptor number cannot be greater than 4	-
I ² S.1	I ² S DMA can stall	-
PLL.1	PLL output is limited to 290 MHz	-
SRAM.1	16 kB SRAM can not be used for code execution	-
USB.1	USB_NEED_CLK is always asserted	-
USB.2	U1CONNECT is not functional	-
USB.3	V _{BUS} status input is not functional	-
WDT.1	Accessing non-Watchdog APB registers in the middle of the feed sequence causes a reset	-
Core.1	Incorrect update of the Abort Link register in Thumb state	-, A, B
Flash.1	Operating speed out of on-chip flash is restricted	-, A
MAM.1	Code execution failure can occur with MAM Mode 2	-, A
CAN.1	Data overrun condition can lock the CAN controller	-, A, B
Deep Power Down.1	Deep Power Down mode is not functional	-, A, B
Vbat.1	Increased power consumption on Vbat when Vbat is powered before the 3.3 V supply used by rest of device	-, A, B

Errata Overview - AC/DC Deviations

AC/DC Deviation	Short Description	Errata occurs in device revision
ESD.1	2 kV ESD requirements are not met on the RTCX1 pin	-

Errata Notes

Note	Short Description
NA	NA

Functional Problems of LPC2364

ADC.1: ADDR_x read conflicts with hardware setting of the DONE bit

Introduction: The LPC2364 has a 10-bit ADC, which can be used to measure analog signals and convert the signals into a 10-bit digital result. There are eight A/D channels and each channel has its own individual A/D Data Register (ADDR₀ to ADDR₇). The A/D Data Register holds the result when an A/D conversion is complete, and also includes the flags that indicate when a conversion has been completed (DONE bit) and when a conversion overrun has occurred. The DONE bit is cleared when the respective A/D Data Register is read.

Problem: If a software read of ADDR_x conflicts with the hardware setting of the DONE bit in the same register (once a conversion is completed) then the DONE bit gets cleared automatically, thereby clearing the indication that a conversion was completed.

Workarounds: For software controlled mode or burst mode with only one channel selected, the DONE bit in the A/D Global Data Register (located at 0xE003 4004) can be used instead of the individual ADDR_x result register with no impact on performance.

For burst mode with multiple channels selected, the DONE bit together with the CHN field in the A/D Global Data Register can be used with some impact on throughput.

Ethernet.1: Setting up the Ethernet interface in RMII mode

Introduction: The LPC2468 has an Ethernet interface, which can be interfaced with an off-chip PHY using the RMII interface.

Problem: The default configuration of the device does not enable the RMII interface.

Workaround: To use the Ethernet interface in RMII mode write a 1 to bit 12 (P1.16) in PINSEL2 register (located at 0xE002 C008). This workaround only applies for Rev '-' devices and does not apply for Rev 'A' and newer devices. In order to have both Rev '-' and other revisions coexist in the same piece of software, the MAC module ID can be used to identify the part and determine if port pin P1.6 needs to be set or not.

Here are the steps (along with some sample code) to initialize the MAC based on the module ID:

1. In master header file ILPC24xx.h, make sure Module ID is defined (Please note, this ID register is not documented in the User's Manual).

```
#define MAC_BASE_ADDR          0xFFE00000
#define MAC_MODULEID (*(volatile unsigned long *) (MAC_BASE_ADDR +
0xFFC)) /* Module ID reg (RO) */
```

2. In the beginning of the MAC initialization file, add below definition:

```
#define OLD_EMAC_MODULE_ID    ((0x3902 << 16) | 0x2000)
```

3. In MAC initialization routine, right after setting the EMAC clock in the PCONP register, add a few lines as below:

```
/* Turn on the ethernet MAC clock in PCONP, bit 30 */
regVal = PCONP;
regVal |= PCONP_EMAC_CLOCK;
PCONP = regVal;
```

```
/*-----
```

```

* Write to PINSEL2/3 to select the PHY functions on P1[17:0]
* P1.6, ENET-TX_CLK, has to be set for Rev '-' devices and it
* must not be set for Rev 'A' and newer devices
*-----*/
regVal = MAC_MODULEID;
if ( regVal == OLD_EMAC_MODULE_ID )
    {
        /* On Rev. '-', MAC_MODULEID should be equal to
        OLD_EMAC_MODULE_ID, P1.6 should be set. */
        PINSEL2 = 0x50151105;
        /* selects P1[0,1,4,6,8,9,10,14,15] */
    }
else
    {
        /* on rev. 'A', MAC_MODULEID should not equal to
        OLD_EMAC_MODULE_ID, P1.6 should not be set. */
        PINSEL2 = 0x50150105;
        /* selects P1[0,1,4,8,9,10,14,15] */
    }
PINSEL3 = 0x00000005; /* selects P1[17:16] */

```

Ethernet.2: Ethernet SRAM disabled

Introduction: The LPC2364 has an Ethernet interface, which has a dedicated 16 kB SRAM.

Problem: When the Ethernet block is disabled (in the PCONP register located at 0xE01F C0C4), the Ethernet SRAM is also disabled.

Workaround: Enable the Ethernet block by setting the PCENET bit (bit no 30) in the PCONP register. The Ethernet SRAM is now enabled.

Ethernet.3 Receive Status registers will not function correctly if RxDescriptor number is greater than 4

Introduction: The Receive number of Descriptors register (RxDescriptor-0xFFE0 0110) defines the number of descriptors in the Descriptor array. Each receive descriptor element in the Descriptor array has an associated status field which consists of the HashCRC word and Status Information word.

Problem: The status words are updated incorrectly if the number of Descriptors set in the Receive number of Descriptors register is greater than or equal to 5.

Workaround: Define 4 or less in the Receive number of Descriptors register.

I²S.1: I²S DMA interface is non-operational

Introduction: The LPC2364 has an I²S interface, which can be used for audio devices. The I²S interface was initially designed to operate with the general purpose DMA controller.

Problem: The DMA controller cannot access the I²S interface.

Workaround: No known workaround.

PLL.1: PLL output (F_{CCO}) is limited to 290 MHz

Introduction: The PLL input, in the range of 32 KHz to 50 MHz, may initially be divided down by a value “N”, which may be in the range of 1 to 256. Following the PLL input divider is the PLL multiplier. This can multiply the input divider output through the use of a Current Controlled Oscillator (CCO) by a value “M”, in the range of 1 through 32768. The resulting frequency, F_{CCO} must be in the range of 275 MHz to 550 MHz. This frequency can be divided down (using the Clock Divider registers) to get the desired clock frequencies for the core and peripherals.

Problem: The maximum output of the CCO within the PLL block is limited to 290 MHz.

Workaround: Care should be taken while programming the PLL so that F_{CCO} resides in the desired range. The suggested setting is to use a 12 MHz external crystal. Use a PLL divider (N) of 1 and PLL multiplier (M) of 12. Putting the values in the equation:

$$F_{CCO} = (2 \times M \times F_{IN}) / N$$

$$F_{CCO} = 288 \text{ MHz}$$

The CPU Clock Configuration register (located at 0xE01F C104) can then be used to divide this frequency by 4 to produce the maximum CPU speed of 72 MHz (except on Rev ‘-’ and Rev ‘A’, see Flash.1).

SRAM.1: 16 kB SRAM cannot be used for code execution

Introduction: The LPC2364 has 16 kB of SRAM on the AHB2 bus, which would generally be used by the Ethernet block.

Problem: The 16 kB of SRAM can only be used as data RAM. Code can not be executed from this memory.

Workaround: No known workaround.

USB.1: USB_NEED_CLK is always asserted

Introduction: The USB_NEED_CLK signal is used to facilitate going into and waking up from chip Power Down mode. USB_NEED_CLK is asserted if any of the bits of the USBClkSt register are asserted.

Problem: The USB_NEED_CLK bit of the USBIntSt register (located at 0xE01F C1C0) is always asserted, preventing the chip from entering Power Down mode when the USBWAKE bit is set in the INTWAKE register (located at 0xE01F C144).

Workaround: After setting the PCUSB bit in PCONP (located at 0xE01F C0C4), write 0x1 to address 0xFFE0C008. The USB_NEED_CLK signal will now function correctly. Writing to address 0xFFE0C008 only needs to be done once after each chip reset.

USB.2: U1CONNECT signal is not functional

Introduction: U1CONNECT Signal (alternate function of P2.9) is part of the SoftConnect USB feature, which is used to switch an external 1.5 KΩ resistor under the software control.

Problem: The USB U1CONNECT alternate function does not work as expected.

Workaround: Configure P2.9 as a GPIO pin, and use it to enable the pull-up resistor on the U1D+ pin.

USB.3: V_{BUS} status input is not functional

Introduction: The V_{BUS} signal indicates the presence of USB bus power.

Problem: The V_{BUS} status input is not functional.

Workaround: Configure P1.30 as a GPIO pin, and poll it to determine when V_{BUS} goes to 0, signalling a disconnect event.

WDT.1: Accessing non-Watchdog APB registers in the middle of the feed sequence causes a reset.

Introduction: The Watchdog timer can reset the microcontroller within a reasonable amount of time if it enters an erroneous state.

Problem: After writing 0xAA to WDFEED, any APB register access other than writing 0x55 to WDFEED may cause an immediate reset.

Workaround: Avoid APB accesses in the middle of the feed sequence. This implies that interrupts and the GPDMA should be disabled while feeding the Watchdog.

Core.1 Incorrect update of the Abort Link register in Thumb state

Introduction: If the processor is in Thumb state and executing the code sequence STR, STMIA or PUSH followed by a PC relative load, and the STR, STMIA or PUSH is aborted, the PC is saved to the abort link register.

Problem: In this situation the PC is saved to the abort link register in word resolution, instead of half-word resolution.

Conditions:

The processor must be in Thumb state, and the following sequence must occur:

<any instruction>

<STR, STMIA, PUSH> <---- data abort on this instruction

LDR rn, [pc,#offset]

In this case the PC is saved to the link register R14_abt in only word resolution, not half-word resolution. The effect is that the link register holds an address that could be #2 less than it should be, so any abort handler could return to one instruction earlier than intended.

Work around: In a system that does not use Thumb state, there will be no problem.

In a system that uses Thumb state but does not use data aborts, or does not try to use data aborts in a recoverable manner, there will be no problem.

Otherwise the workaround is to ensure that a STR, STMIA or PUSH cannot precede a PC-relative load. One method for this is to add a NOP before any PC-relative load instruction. However this is would have to be done manually.

Flash.1 Operating speed out of on-chip Flash is restricted

Introduction: The operating speed of this device out of internal Flash/ SRAM is specified at 72MHz.

Problem: Code execution from internal Flash is restricted depending upon the device revision:

1. Rev 'A' devices: Code execution from internal flash is restricted to a maximum of 60MHz.

For example, use a PLL output frequency of $F_{cco}=360\text{MHz}$ and divide it by 6 (CCLKSEL=5) to generate 60MHz CPU clock (Do not use even values for CCLKSEL).

2. Rev '-' devices: Code execution from internal flash is restricted to a maximum of 60MHz also.

However, this device revision has one more restriction in terms of the PLL output frequency (F_{cco} - Please refer to PLL.1 above). F_{cco} is limited to 290MHz.

Considering the same example in PLL.1 (Input crystal-12MHz, $N=1$, $M=12$): $F_{cco} = 288\text{ MHz}$

The CPU Clock Configuration register (located at 0xE01F C104) can then be used to divide this frequency by 6 (CCLKSEL=5) to achieve 48MHz. Since this register only accepts odd values for CCLKSEL, a division by 5 (CCLKSEL=4) is not a valid option.

In both the above revisions, code can still execute out of SRAM at up to 72 MHz.

Work around: None.

MAM.1: Under certain conditions in MAM Mode 2 code execution out of internal Flash can fail.

Introduction: The MAM block maximizes the performance of the ARM processor when it is running code in Flash memory. It includes three 128-bit buffers called the Prefetch Buffer, the Branch Trail Buffer and the data buffer. It can operate in 3 modes; Mode 0 (MAM off), Mode 1 (MAM partially enabled) and Mode 2 (MAM fully enabled).

Problem: Under certain conditions when the MAM is fully enabled (Mode 2) code execution from internal Flash can fail. The conditions under which the problem can occur is dependent on the code itself along with its positioning within the Flash memory.

Workaround: If the above problem is encountered then Mode 2 should not be used. Instead, partially enable the MAM using Mode 1.

CAN.1: Data Overrun condition can lock the CAN controller

Introduction: Each CAN controller provides a double Receive Buffer (RBX) per CAN channel to store incoming messages until they are processed by the CPU. Software task should read and save received data as soon as a message reception is signaled.

In cases, where both receive buffers are filled and the contents are not read before the third message comes in, a CAN Data Overrun situation is signaled. This condition is signaled via the Status register and the Data Overrun Interrupt (if enabled).

Problem: In a Data Overrun condition, the CAN controller is locked from further message reception.

Workaround:

1. Recovering from this situation is only possible with a soft reset to the CAN controller.
2. If software cannot read all messages in time before a third message comes in, it is recommend to change the acceptance filtering by adding further acceptance filter group(s) for messages, which are normally rejected. With this approach, the third incoming message is accepted and the Data Overrun condition is avoided. These additional messages are received with the corresponding group index number can be easily identified and rejected by software.

Deep Power Down Mode.1: Deep Power Down mode is not functional

Introduction: Deep Power Down mode is like Power Down mode, but the on-chip regulator that supplies power to internal logic is also shut off. This produces the lowest possible power consumption without actually removing power from the entire chip.

Problem: The power consumption in Deep Power Down mode does not meet the specifications.

Workaround: None.

Vbat.1: Increased power consumption on Vbat when Vbat is powered before the 3.3 V supply used by rest of the device.

Introduction: The device has a Vbat pin which provides power only to the RTC and Battery RAM. Vbat can be connected to a battery or the same 3.3 V supply used by rest of the device (VDD(3V3) pin,

VDD(DCDC)(3V3) pin).

Problem: If Vbat is powered before the 3.3 V supply, Vbat is unable to source the start-up current required for the Battery RAM. Therefore, power consumption on the Vbat pin will be high and will remain high until 3.3 V supply is powered up. Once 3.3 V supply is powered up, power consumption on the Vbat pin will reduce to normal and subsequent power cycle on the 3.3 V supply will not cause an increased power consumption on the Vbat pin.

Workaround: Provide 3.3 V supply used by rest of the device first and then provide Vbat voltage.

AC/DC Deviations

ESD.1: The LPC2364 does not meet the 2 kV ESD requirements on the RTCX1 pin

Introduction: The LPC2364 is rated for 2 kV ESD. The RTCX1 pin is the input pin for the RTC oscillator circuit.

Problem: The LPC2364 does not meet the required 2 kV ESD specified.

Workarounds: Observe proper ESD handling precautions for the RTCX1 pin.