

# ERRATA SHEET

**Date:** 2009 August 11  
**Document Release:** Version 1.1  
**Device Affected:** LPC2888/01

This errata sheet describes both the functional problems and any deviations from the electrical specifications known at the release date of this document.

Each deviation is assigned a number and its history is tracked in a table at the end of the document.

2009 August 11

**Document revision history**

Rev	Date	Description
1.1	August 11, 2009	Added ESD.1
1.0	May 23, 2008	First version

## Identification

The typical LPC2888/01 devices have the following top-side marking:

LPC2888xxx  
/01  
xxxxxxx  
xxYYWW R

The last letter in the third line (field 'R') will identify the device revision. This Errata Sheet covers the following revisions of the LPC2888/01:

Revision Identifier (R)	Comment
'(blank)'	Initial device revision

Field 'YY' states the year the device was manufactured. Field 'WW' states the week the device was manufactured during that year.

**Errata Overview - Functional Problems**

Functional Problem	Short Description	Device Revision the problem occurs in
Core.1	Thumb code execution is not possible from on-chip 1MB Flash	'(blank)'

**Errata Overview - AC/DC Deviations**

AC/DC Deviation	Short Description	Device Revision the deviation occurs in
ESD.1	ESD weakness on the $V_{DD(DADC1V8)}$ , $DCDC\_V_{DDO(1V8)}$ , $V_{DD1(FLASH1V8)}$ , $V_{DD2(USB1V8)}$ , SCL, D0/P[0], DP and LD1/P4[5] pins.	'(blank)'

**Errata Notes**

Note	Short Description
NA	NA

## Functional Problems of LPC2888/01

### **Core.1: Thumb code execution is not possible from on-chip 1MB Flash**

Introduction: The LPC2888/01 has an ARMTDMI core and it supports the Thumb Instruction set.

Problem: Thumb code cannot execute from on-chip Flash and if attempted, there will be a data abort exception.

Workaround: No known workaround. Only ARM code execution is possible from the on-chip Flash.

## AC/DC Deviations of the LPC2888/01

**ESD.1: ESD weakness on the  $V_{DD(DADC1V8)}$ ,  $DCDC\_V_{DDO(1V8)}$ ,  $V_{DD1(FLASH1V8)}$ ,  $V_{DD2(USB1V8)}$ , SCL, D0 P[0], DP and LD1/P4[5] pins.**

Introduction: The LPC2888/01 is rated for 2kV ESD HBM specification.

Problem: The LPC2888/01 does not meet the 2kV ESD HBM requirements on the  $V_{DD(DADC1V8)}$ ,  $DCDC\_V_{DDO(1V8)}$ ,  $V_{DD1(FLASH1V8)}$ ,  $V_{DD2(USB1V8)}$ , SCL, D0/P[0], DP and LD1/P4[5] pins.

Workarounds: Observe proper ESD handling precautions on these pins.