

# ES\_P89LPC9151

Errata sheet P89LPC9151

Rev. 01 — 5 February 2010

Errata sheet

## Document information

Info	Content
<b>Keywords</b>	P89LPC9151 errata
<b>Abstract</b>	<p>This errata sheet describes both the known functional problems and any deviations from the electrical specifications known at the release date of this document.</p> <p>Each deviation is assigned a number and its history is tracked in a table at the end of the document.</p>



**Revision history**

Rev	Date	Description
01	20100205	Added ADC.1

**Contact information**

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

## 1. Product identification

The P89LPC9151 devices typically have the following top-side marking:

```
P89LPC9151 x x
xxxxxxx xx
xxYYWW R
```

The last letter in the last line (field 'R') will identify the device revision. This Errata Sheet covers the following revisions of the P89LPC9151:

**Table 1. Device revision table**

Revision identifier (R)	Revision description
'.'	Initial device revision

Field 'YY' states the year the device was manufactured. Field 'WW' states the week the device was manufactured during that year.

## 2. Errata overview

**Table 2. Functional problems table**

Functional problems	Short description	Revision identifier	Detailed description
ADC.1	Single step mode multi channel boundary interrupt	'.'	<a href="#">Section 3.1 on page 4</a>

**Table 3. AC/DC deviations table**

AC/DC deviations	Short description	Revision identifier	Detailed description
n/a	n/a	n/a	n/a

### 3. Functional problems detail

---

#### 3.1 ADC.1: Single Step mode multi channel boundary interrupt

**Introduction:**

The ADC on the P89LPC9151 is an Analog to Digital converter with 8 bits of resolution. The ADC has features such as a Single Step mode where the ADC will step through the selected channels on each ADC start condition.

**Problem:**

When the ADC is in Single Step mode with more than 1 channel selected, and a boundary interrupt occurs to any of the lower selected channel-bits, a write to the ADMODA register to clear the BNDI bit before all the selected channels are converted will reset the channel selection counter and the ADC will go back and wait at the lowest selected channel for the next conversion. This applies to ADC1 on the P89LPC9151.

**Work-around:**

1. Clear the lower channel bits including the boundary interrupted channel in ADCINS register before the next start request.
2. Use the default boundary channel, not clear BNDI bit until all channels are converted.

### 4. AC/DC deviations detail

---

#### 4.1 No known errata

## 5. Legal information

### 5.1 Definitions

**Draft** — The document is a draft version only. The content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included herein and shall have no liability for the consequences of use of such information.

### 5.2 Disclaimers

**Limited warranty and liability** — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the *Terms and conditions of commercial sale* of NXP Semiconductors.

**Right to make changes** — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Suitability for use** — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in medical, military, aircraft, space or life support equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors accepts no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

**Applications** — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on a weakness or default in the customer application/use or the application/use of customer's third party customer(s) (hereinafter both referred to as "Application"). It is customer's sole responsibility to check whether the NXP Semiconductors product is suitable and fit for the Application planned. Customer has to do all necessary testing for the Application in order to avoid a default of the Application and the product. NXP Semiconductors does not accept any liability in this respect.

**Export control** — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from national authorities.

### 5.3 Trademarks

Notice: All referenced brands, product names, service names and trademarks are the property of their respective owners.

## 6. Contents

---

<b>1</b>	<b>Product identification</b> .....	<b>3</b>
<b>2</b>	<b>Errata overview</b> .....	<b>3</b>
<b>3</b>	<b>Functional problems detail</b> .....	<b>4</b>
3.1	ADC.1: Single Step mode multi channel boundary interrupt .....	4
	Introduction: .....	4
	Problem: .....	4
	Work-around: .....	4
<b>4</b>	<b>AC/DC deviations detail</b> .....	<b>4</b>
4.1	No known errata .....	4
<b>5</b>	<b>Legal information</b> .....	<b>5</b>
5.1	Definitions .....	5
5.2	Disclaimers .....	5
5.3	Trademarks .....	5
<b>6</b>	<b>Contents</b> .....	<b>6</b>

---

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

---

© NXP B.V. 2010.

All rights reserved.

For more information, please visit: <http://www.nxp.com>  
For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: 5 February 2010

Document identifier: ES\_P89LPC9151\_1