

# iMX7ULP\_1N54W

## Mask Set Errata

Rev. 1 — 9 December 2024

Errata

## 1 Mask Set Errata for Mask 1N54W

### 1.1 Revision History

This report applies to mask 1N54W for these products:

- MCIMX7U5DVP07SC
- MCIMX7U5DVK07SC
- MCIMX7U3DVK07SC

Table 1. Revision History

Revision	Release Date	Significant Changes
1	12/2024	Rev. 1, 12/2024 The following errata were added. ERR052515 Rev. 0, 06/2019 Initial Revision

### 1.2 Errata and Information Summary

Table 2. Errata and Information Summary

Erratum ID	Erratum Title
<a href="#">ERR010469</a>	ARM A7: A7 core reset as a source for the M4 core
<a href="#">ERR010472</a>	MSMC: Reset delay on A7 domain when interrupt is enabled for Core0 reset sources
<a href="#">ERR010473</a>	uSDHC: Data Timeout Counter Value may be insufficient for HS400 mode
<a href="#">ERR010740</a>	QuadSPI: Insufficient read data may be received in the RX Data Buffer register
<a href="#">ERR011097</a>	LPSPi: Command word not loaded correctly when TXMSK=1
<a href="#">ERR011372</a>	Power: High leakage current on VDD18_IOREF when VDD supplies for PORT segments are turned off in VLLS modes
<a href="#">ERR011403</a>	CA7: LLS/VLPS wakeup time is longer when PMC1_CTRL[LDOOKDIS]=0
<a href="#">ERR011424</a>	Interrupts: NMI_b not serviced by CM4 core when used as wake event from VLLS mode
<a href="#">ERR011432</a>	SNVS: TAMPER pin does not retain pull-up/down configuration in VBAT mode
<a href="#">ERR011433</a>	DAC: Transfer error generated when accessing offset addresses 0x19-0x1B
<a href="#">ERR011439</a>	MIPI DSI: Checksum is incorrect for DCS command long packet writes with zero-length data payload
<a href="#">ERR050134</a>	GPIO: GPIO pull-ups/pull-downs may become enabled during reset
<a href="#">ERR050138</a>	PMC: PMC0 PM_STAT[PMC0CURRPM] stuck at VLPR after reset in VLPS/LLS/VLLS modes
<a href="#">ERR052515</a>	FSGPIO: A parametric shift over time is observed on FSGPIO output driver when it is powered above 1.98V



## 2 Known Errata

### ERR010469: ARM A7: A7 core reset as a source for the M4 core

#### Description

The i.MX 7ULP provides the following reset options between the two ARM cores:

- 1) M4 core reset of A7 core: There is hardware capability on the SoC for the M4 core to reset the A7 core directly.
- 2) A7 core reset of M4 core: There is no hardware capability for the A7 to reset the M4 directly. This is achieved through the Messaging Unit (MU). The MU A-side Control Register field MUA\_CR[RAIE] provides a software mechanism for the M4 to detect that the A7 has been reset.

#### Workaround

The A7 reset is mapped as an interrupt to the M4 core so anytime the A7 is reset, an interrupt is triggered to the M4 core. The M4 core can then reset as required using an ISR.

### ERR010472: MSMC: Reset delay on A7 domain when interrupt is enabled for Core0 reset sources

#### Description

The Multicore System Mode Controller (MSMC) System Reset Interrupt Enable (SRIE) feature allows that some reset sources can be delayed to service an interrupt request.

For the A7 domain, this feature can be enabled for Core 0 (M4) reset sources. This can cause potential issues because when the M4 resets, the A7 domain will lose its clock references from the PLLs and will not be able to service the interrupt. Even when the M4 returns from reset, it is not guaranteed that the PLLs will relock without reconfiguration.

#### Workaround

Do not use the Core 0 reset interrupt function available to the A7 domain.

### ERR010473: uSDHC: Data Timeout Counter Value may be insufficient for HS400 mode

#### Description

When the Data Timeout Counter Value programmed in SYS\_CTRL[DTOCV] is set to the maximum value (0xF), the maximum busy timeout is  $[2^{29} * 2.5 \text{ ns}] = 1.34 \text{ s}$  because the root clock is 400 MHz for HS400 mode. For other speed modes, the maximum busy timeout time is longer because the root clock is slower.

Some eMMC datasheets show maximum busy timeout specifications of 1.6 s, so the programmable timeout in the uSDHC will not be long enough for HS400 mode.

This issue only affects HS400 mode with a 200 MHz SD clock. If the SD clock is reduced to 150 MHz, the timing requirements for 1.6 s can be met.

#### Workaround

- 1) Reduce the SD clock to 150 MHz

2) Disable hardware timeout and use a software timeout mechanism to generate a 1.6 s timeout

## **ERR010740: QuadSPI: Insufficient read data may be received in the RX Data Buffer register**

### **Description**

Data read from flash through QuadSPI using Peripheral Bus Interface (IPS) may return insufficient data in the RX Buffer Data register (QuadSPI\_RBDRn) when the read data size of a flash transaction is programmed to be greater than 32 bytes.

### **Workaround**

For data size greater than 32 bytes, program the IP data transfer size in the IP configuration register (QuadSPI\_IPCR[IDATSZ]) to be in multiples of 8 bytes.

## **ERR011097: LPSPI: Command word not loaded correctly when TXMSK=1**

### **Description**

When the Transmit Command Register is written with TCR[TXMSK]=1 and the next write to the TX FIFO is another command, then the first command may not load correctly.

### **Workaround**

When writing the Transmit Command Register with TCR[TXMSK]=1, wait for the TX FIFO to go empty (FSR[TXCOUNT] = 0) before writing another command to the Transmit Command Register.

## **ERR011372: Power: High leakage current on VDD18\_IOREF when VDD supplies for PORT segments are turned off in VLLS modes**

### **Description**

Excessive current around 370uA on VDD18\_IOREF is observed when both the M4 and A7 cores are in VLLS mode and VDD\_PTA, VDD\_PTC or VDD\_PTE are turned off.

### **Workaround**

VDD\_PTA, VDD\_PTC and VDD\_PTE should remain powered when the M4 and A7 are both in VLLS mode. The expected leakage current for keeping these supplies powered is approximately 2 uA at 3.3V.

## **ERR011403: CA7: LLS/VLPS wakeup time is longer when PMC1\_CTRL[LDOOKDIS]=0**

### **Description**

The CA7 wakeup time from LLS/VLPS is significantly longer when PMC1\_CTRL[LDOOKDIS]=0. This bitfield selects whether the PMC will check the regulated output from the LDO Regulator during a mode transition.

Approximate wakeup time from LLS when PMC1\_CTRL[LDOOKDIS]=1: 41.5 us

Approximate wakeup time from LLS when PMC1\_CTRL[LDOOKDIS]=0: 80 us

Approximate wakeup time from VLPS when PMC1\_CTRL[LDOOKDIS]=1: 23 us

Approximate wakeup time from VLPS when PMC1\_CTRL[LDOOKDIS]=0: 46 us

This issue does not affect systems designed for CA7 LDO Bypass Mode.

### Workaround

Set PMC1\_CTRL[LDOOKDIS]=1 before entering LLS/VLPS modes. This setting keeps the register asserted when returning to RUN mode. After RUN mode is reached, the register may be de-asserted.

PMC1\_CTRL[LDOOKDIS]=0 reduces the response time of the LDO voltage adjustments in RUN mode, while PMC1\_CTRL[LDOOKDIS]=1 sets a fixed timing interval for any voltage adjustment. When moving to LLS or VLPS modes, there are no side effects if PMC1\_CTRL[LDOOKDIS]=1 is used.

In CA7 LDO Bypass Mode, always set PMC1\_CTRL[LDOOKDIS]=1.

## ERR011424: Interrupts: NMI\_b not serviced by CM4 core when used as wake event from VLLS mode

### Description

When NMI\_b is used as an event to wake the CM4 core from VLLS mode, the CM4 wakeup occurs but the NMI interrupt is internally disabled when power is restored and does not get serviced by the CM4 core.

In silicon revision B1, a bit was added to SIM\_DGO\_GP11[7]. In addition to the usual selection of the NMI\_b function via IOMUXC0\_SW\_MUX\_CTL\_PAD\_PTA9, this bit must be set prior to entering CM4 VLLS mode to allow the NMI interrupt to remain active once power is restored and cleared upon exiting VLLS.

During validation of the fix of this issue on silicon revision B1, an associated issue was found. While the implementation of the SIM\_DGO\_GP11[7] bit is correct, the ROM code regarding handling of the NMI event is incorrect preventing use of NMI as a wake-up event from CM4 VLLS mode.

### Workaround

Use a wake-event other than NMI to wake the CM4 from VLLS mode.

## ERR011432: SNVS: TAMPER pin does not retain pull-up/down configuration in VBAT mode

### Description

The TAMPER pin has the capability to enable an internal pull-up or pull-down resistor. The internal pull-up / pull-down configuration is not retained when the SoC enters VBAT mode.

### Workaround

Use an external pull-up or pull-down resistor if the TAMPER function is desired during VBAT mode.

**ERR011433: DAC: Transfer error generated when accessing offset addresses 0x19-0x1B****Description**

The DAC generates a transfer error for both read and write accesses to offset addresses 0x19-0x1B. These offsets are part of the ITRM register which is 32 bits and starts at offset address 0x18. Accesses to offset address 0x18 work properly.

**Workaround**

Use only 32-bit accesses to offset address 0x18 to read/write the ITRM register.

**ERR011439: MIPI DSI: Checksum is incorrect for DCS command long packet writes with zero-length data payload****Description**

According to the MIPI DSI specification, long packets are comprised of a Packet Header and a payload of 0 to  $2^{16}-1$  bytes. For the special case of a zero-length payload, the specification requires the checksum must be set to 0xFFFF.

The MIPI DSI controller produces an incorrect checksum for DCS commands issued via long packets with zero-length payloads in DSI Low-Power mode (LP). There is no issue for similar commands issued in DSI High-Power mode (HP).

This issue should not affect normal application operation because packets with zero data length will normally be sent using the short packet format. However, because the MIPI DSI spec specifically states this behavior, MIPI DSI certification will fail with long packets of zero-length.

**Workaround**

Use short packet format to send DCS commands with zero length data payloads.

**ERR050134: GPIO: GPIO pull-ups/pull-downs may become enabled during reset****Description**

During reset, the failsafe GPIOs (Ports A, B, C, E, and F) are supposed to be in the input/H-Z state. Due to a reset issue, the GPIO buffers may come up as Hi-Z with an internal pull-up or pull-down being enabled. The issue persists until the associated internal core supply is on (VDD\_DIG0 for Ports A and B; VDD\_DIG1 for Ports C, E, and F). After the internal core supply is present, the issue is cleared and the GPIOs will behave as expected.

Ports A and B are susceptible to this issue, however it will only occur until VDD\_DIG0 is on. In this case, the GPIO issue will clear before RESET0\_b is released.

On Ports C, E, and F, the issue will persist until VDD\_DIG1 is turned on internally by the M4. Therefore, the issue will persist after RESET0\_b is released until the boot ROM process enables VDD\_DIG1 to the A7 domain.

This issue occurs only on power-on reset (POR). After the core supplies have been turned on, the issue will not occur on subsequent resets (including when the A7 exits VLLS mode).

Port D GPIOs are not affected.

## Workaround

- 1) For critical signals that must be controlled during reset, choose GPIOs on ports A, B, or D.
- 2) For critical signals on ports C, E, and F, include a strong enough pull-up or pull-down on the board to overdrive the internal pull-up or pull-down if it occurs. The internal pull-up/pull-downs may be as strong as approximately 20k ohms.

## ERR050138: PMC: PMC0 PM\_STAT[PMC0CURRPM] stuck at VLPR after reset in VLPS/LLS/VLLS modes

### Description

The Real-Time Domain PMC0 Current Power Mode status bits (PMC0 PM\_STAT[PMC0CURRPM]) become stuck indicating VLPR mode (0x3) if a reset occurs when the Real-Time Domain is in VLPS, LLS, or VLLS mode and those power modes were reached from VLPR mode (i.e. RUN -> VLPR -> VLPS/LLS/VLLS). Notice that VLLS wake-up always includes a reset regardless of the wakeup source (RESET0\_B, GPIO, NMI, etc.) so this issue is always seen after a wake-up via GPIO/NMI pin events.

### Workaround

If PMC0 PM\_STAT[PMC0CURRPM] is not used, no action is required.

If the Real-Time Domain needs to go from VLPR to one of the affected modes (i.e. VLPS/LLS/VLLS), go from VLPR to RUN first, and then go to the target mode (VLPS, LLS, or VLLS).

## ERR052515: FSGPIO: A parametric shift over time is observed on FSGPIO output driver when it is powered above 1.98V

### Description

When FSGPIO is powered above 1.98V, a parametric shift over time is observed on FSGPIO output driver, where the output low drive current (IOL) is degraded, leading to a longer fall time and output low voltage level (VOL) is increased. Analog and input functionality is not impacted.

PTA, PTC, PTE and PTF are impacted. PTB is FSGPIO, but it is powered with 1.8V mode (1.71-1.98V) only, therefore PTB is not impacted.

For new or updated designs use 1.8V mode (1.71-1.98V) for the FSGPIO power supply. For the legacy designs, refer to Technote TN00188 for IOL and fall time degradation information when operating above 1.98V. If it is determined that IO does not meet the mission profile requirement of the end application, implement the workaround.

### Workaround

The I/O power supplies, VDD\_PTA, VDD\_PTC, VDD\_PTE and VDD\_PTF should be connected to 1.8V mode (1.71-1.98V).

The voltage range is controlled by PT\*\_RANGE\_CTRL of SIM\_DGO\_GP11(Address 0x 410A3080).

00b – Continuous Mode

01b – Low Range Mode

10b – High Range Mode

Both 00b and 01b are allowed. Recommend to set the field to 01b to use low voltage range 1.8V for better delay performance and power consumption if the power supply is 1.8V.

Note these SIM\_DGO\_GP11 registers update requires the special sequence documented in the System Integration Module(SIM) chapters of iMX7ULP RM.

## Legal information

### Definitions

**Draft** — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

### Disclaimers

**Limited warranty and liability** — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

**Right to make changes** — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Suitability for use** — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

**Applications** — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

**Limiting values** — Stress above one or more limiting values (as defined in the Absolute Maximum Ratings System of IEC 60134) will cause permanent damage to the device. Limiting values are stress ratings only and (proper) operation of the device at these or any other conditions above those given in the Recommended operating conditions section (if present) or the Characteristics sections of this document is not warranted. Constant or repeated exposure to limiting values will permanently and irreversibly affect the quality and reliability of the device.

**Terms and conditions of commercial sale** — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at <https://www.nxp.com/profile/terms>, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

**No offer to sell or license** — Nothing in this document may be interpreted or construed as an offer to sell products that is open for acceptance or the grant, conveyance or implication of any license under any copyrights, patents or other industrial or intellectual property rights.

**Quick reference data** — The Quick reference data is an extract of the product data given in the Limiting values and Characteristics sections of this document, and as such is not complete, exhaustive or legally binding.

**Export control** — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

**Suitability for use in non-automotive qualified products** — Unless this document expressly states that this specific NXP Semiconductors product is automotive qualified, the product is not suitable for automotive use. It is neither qualified nor tested in accordance with automotive testing or application requirements. NXP Semiconductors accepts no liability for inclusion and/or use of non-automotive qualified products in automotive equipment or applications.

In the event that customer uses the product for design-in and use in automotive applications to automotive specifications and standards, customer (a) shall use the product without NXP Semiconductors' warranty of the product for such automotive applications, use and specifications, and (b) whenever customer uses the product for automotive applications beyond NXP Semiconductors' specifications such use shall be solely at customer's own risk, and (c) customer fully indemnifies NXP Semiconductors for any liability, damages or failed product claims resulting from customer design and use of the product for automotive applications beyond NXP Semiconductors' standard warranty and NXP Semiconductors' product specifications.

**HTML publications** — An HTML version, if available, of this document is provided as a courtesy. Definitive information is contained in the applicable document in PDF format. If there is a discrepancy between the HTML document and the PDF document, the PDF document has priority.

**Translations** — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.



**Security** — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately.

Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at [PSIRT@nxp.com](mailto:PSIRT@nxp.com)) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

**NXP B.V.** — NXP B.V. is not an operating company and it does not distribute or sell products.

## Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

**NXP** — wordmark and logo are trademarks of NXP B.V.

Contents

1 Mask Set Errata for Mask 1N54W ..... 1

1.1 Revision History ..... 1

1.2 Errata and Information Summary ..... 1

2 Known Errata ..... 2

Legal information ..... 8

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.