

Freescale Semiconductor Software Errata

Document Number: ISF95KSWER

Rev. 0, 5/2014

ISF Errata

Release 1.1 for FXLC95000

This errata sheet describes the problems known at the release date of this document.

All ISF related updates are available at freescale.com/isf





Open Issues in ISF Release 1.1 for FXLC95000						
Freescale Issue Identification Number	Headline	First Found on Release	Issue Submission Date	Resolved by Release		
ENGR00296187	Error messages generated by ISF are suppressed by the Sensor Manager. WORKAROUND: None.	ISF1P195K_1000	22 January 2014	TBD		
ENGR00308188	The sensor adapter for the FXOS8700 provides incorrect enumeration for the range. WORKAROUND: Edit C:\Program Files\Freescale\ISF_R1p1\ISF\Include\Sensors\fsl_fxos8700_i2cspi_6D_AccMag_config_types.h to correct the problem. Replace this text: typedef enum fxos8700_Range_tag { FXOS8700_RANGE_8G = 0,	ISF1P195K_1000	11 April 2014	ISF1P195K_1001		

ISF Software Errata, Rev. 0

Freescale Semiconductor, Inc.



Issues Fixed Between ISF1P01 and ISF1P1_1000						
Freescale Issue Identification Number	Description	First Found on Release	Fixed in Release	Ticket Closed Date (Submission Date)		
` ,	Update to the Software Reference Manual to notify users about a FXLC95000 hardware feature. The AFE manual trigger bit inhibits frame interrupt causing the Power Manager to spin waiting for the Start of Frame IRQ.	ISF1P0195K	ISF1P195K_1000	10 October 2013 (11 June 2013)		
ENGR00275462	Sensor Adapters were required to be in the STATE_STARTED state before unregistering callbacks from the Bus Manager. This was an unnecessary condition for unregistering callbacks and has been removed in all of the sensor adapters.	ISF1P0195K	ISF1P95K_1000	25 September 2013 (15 August 2013)		
ENGR00277198		ISF1P0195K	ISF1P95K_1000	12 September 2013 (28 August 2013)		
ENGR00296203	It is possible for an embedded application to begin sensor configuration before the ISF initialization task completes. An error message is generated but is not passed to the embedded application by the Sensor Manager.	- ISF1P0195K	ISF1P95K_1000	14 February 2014 (22 January 2014)		
	MQX 3.7 returns allocated memory to the memory pool when the allocating task is destroyed.					
	The FXOS8700 requires a 1 millisecond delay after reset which is not reflected in the FXOS8700 sensor adapter.					



How to Reach Us:

Home Page: freescale.com

Web Support:

freescale.com/support

Information in this document is provided solely to enable system and software implementers to use Freescale products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document.

Freescale reserves the right to make changes without further notice to any products herein. Freescale makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in Freescale data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. Freescale does not convey any license under its patent rights nor the rights of others. Freescale sells products pursuant to standard terms and conditions of sale, which can be found at the following address: freescale.com/salestermsandconditions.

Freescale and the Freescale logo are trademarks of Freescale Semiconductor, Inc., Reg. U.S. Pat. & Tm. Off. Xtrinsic is a trademark of Freescale Semiconductor, Inc. All other product or service names are the property of their respective owners.

© 2014 Freescale Semiconductor, Inc.

Document Number: ISF95KSWER

Rev. 0 5/2014

