

## 1 Introduction

### 1.1 Purpose

This application note introduces the major considerations required to migrate from i.MX 8X B0 to i.MX 8X C0, including i.MX 8QuadXPlus, i.MX 8DualXPlus, and i.MX 8DualX.

To distinguish between i.MX 8X B0 and i.MX8X C0 parts, users can check the last letter of the part number, which indicates the silicon reversion. For example, MiMX8QX6AVLFZAB indicates that it is i.MX 8X B0 part, while MiMX8QX6AVLFZAC indicating that it is i.MX 8X C0 part.

### 1.2 Scope

The i.MX 8X C0 fixes most of the errata that are reported on i.MX 8X B0. The major changes include:

- **Imaging/ISI:** The same functionality as B0 with optimization on the image stream flow control and performance improvement. Bug fixes to enhance the IP and system use case operating quality.
- **DRC:** Bug fixes for derating logic and shorten the ECC boot time.
- **DPLL:** Bug fixes to resolve the pll lock issue at cold temperature and some other issues. Programming sequence changed.
- **DB :** Bug fix for TDM QoS mechanism is broken when HW clock gating is enabled.
- **SCU:** Several bug fixes. Add the ability to wake up from the SNVS ON/OFF key in KS1(LLS), Improve SNVS startup time on LDO.
- **DC:** Bug fixes for PRG on the fly bypass switch issue.
- **GPU:** Fix OpenCV and Vulkan conformance issues.
- **VPU:** Enhancement for encoder and decoder using different reset signal
- **MIPI\_CSI:** Several enhancements, including align RAW8 format in MIPI\_CSI reformatter with ISI.
- **MIPI\_DSI:** Bug fixes to resolve MIPI DSI CRC issue for LP DCS long write.
- **USB:** Several bug fixes, including fix for ISO out queue issue.
- **TOP:** Several bug fixes, including fix for display write-back feature.
- **ROM:** Several bug fixes, including reset SECO timer if SD/MMC initialization takes too long.

For a detailed description of the complete change list, see Chapter 2.2 “Change list” below.

### 1.3 Audience

This document is intended for system integrators and software developers migrating from the platforms based on i.MX 8X B0 to i.MX 8X C0.

## 2 Feature Change Summary

### Contents

<b>1 Introduction.....</b>	<b>1</b>
1.1 Purpose.....	1
1.2 Scope.....	1
1.3 Audience.....	1
<b>2 Feature Change Summary.....</b>	<b>1</b>
2.1 BSP support.....	2
2.2 Change list.....	2
2.3 Software changes.....	4
2.4 Hardware changes.....	6
<b>3 Revision history.....</b>	<b>6</b>



## 2.1 BSP support

The i.MX 8X C0 is now supported by the L4.14.98\_2.3.0 BSP release.

## 2.2 Change list

This section summarizes the changes of the i.MX 8X C0 with respect to the i.MX 8X B0.

**Table 1. Changes List of i.MX 8X C0**

Subsystem	Changes/Issue fixed in C0	Related Errata/ Enhancement	SW migration impact	HW migration impact
Imaging/ISI	ISI stream flow control problem. ISI does not have any built-in mechanism for controlling the AXI transaction frequency	e50066	Driver update	None
	ISI Virtual channel issue with 4 camera, 4 cameras cannot be supported well	e50058	Driver update	None
	When ISI is programmed to do scaler on 2 adjacent channels, image on the second channel is corrupted. There are some empty lines inserted every 16 lines.	e50067	Driver update	None
DRC	DDR3 ECC boot time over 50 ms. This issue does not meet auto customer application requirement for DDR3 ECC boot.	e50054	SCFW (dcd) update	None
	Derating logic does not Consider the System Temperature when Derating is Enabled	e50125	SCFW (dcd) update	None
DPLL	At cold temperatures, the DPLL does not lock for some parts. Switch DPLL phase detector to a phase frequency hybrid structure. Saturation logic broken in DPLL integrator preventing reset and lock if saturated.	e50061	SCFW update	None
SCU	SNVS startup on LDO is too slow 1)SNVS_ANA LDO regulator fix 2) The VBAT_POR_B signal, which is the SNVS DGO domain reset, is included in the logic which provides the POR signal to the DSC.	e50056	None	None
DC	PRG on the fly bypass switch issue. De-rate the PRG AXI channel clock from 400 MHz to 375 MHz to meet the STA of the ECO.	e50060	SCFW update	None
GPU	OpenCV and Vulkan conformance issue. Modified the GPU revision number for SW identification	e50057	Driver update	None
VPU	VPU encoder and decoder use different reset signal from DSC in different power domain.	enhancement	SCFW update	None
MIPI_CSI	CSI generates the ODD/EVEN signal according to the incoming start of frame package.	enhancement	Driver update	None

*Table continues on the next page...*

**Table 1. Changes List of i.MX 8X C0 (continued)**

	Align RAW8 format in MIPI_CSI reformatter with ISI	enhancement	Driver update	None
MIPI_DSI	MIPI DSI CRC issue for LP DCS long write	e11439	None	None
Connectivity	NXP USB2 ISO OUT issue in device mode.	e50141	None	None
	USB3: Multiple DMA write transfer complete interrupts are generated before final write access handshake to the AXI bus	e50147	None	None
	USB3: TRB OUT endpoints transfer blockage and performance delays	e50149	Driver update	None
	USB3: Port Configuration Response is not compliant with the USB compliance TD 7.17 test case	e50115	None	None
Top	The impact of the temperature sensor turning on and off in its normal operation couples and corrupts other analog blocks through top-level metal coupling.	e50055	None	None
	Display write back feature is broken due to the pixel link receiver address tied-off. With this fix, application can allocate the write-back to different LVDS.	e50059	None	None
	Chip ID need to be a new value for C0 rev. by updating the JTAG ID for C0 as 0x2890201D	N/A	Driver & SCFW update	None

**Table 2. Changes List of i.MX 8X C0 ROM**

Related Errata/ Enhancement	Changes/Issue fixed in C0	SW migration impact	HW migration impact
e50108	Reset SECO timer if SD/MMC initialization taking too much time to fix boot failure issue	None	None
e50052	NAND boot fails when image header points to an unprogrammed block	None	None
e50053	USB HID device cannot be re-enumerated successfully after an unplug/plug USB cable operation	None	None
Enhancement	Support boot image provisioned by boot partitions for eMMC regular boot, no 32k gpt offset	Driver update	None
Enhancement	Using CM4 self-reset to issue warm reset instead of WDOG reset	None	None
Enhancement	Update DPLL lock sequence	None	None
N/A	Update SCU ROM version to 1.3	SCFW update	None

## 2.3 Software changes

For software changes to bring up i.MX 8X C0, the main aspects are listed below. However, the driver update for all modules in the change list is not include here. It will be included in the BSP release L4.14.98\_2.3.0.

For other unchanged parts, see i.MX 8X Linux User Guide for more details.

- SCFW

Use SCFW Porting Kit 1.3.0 and later version.

Compile the SCFW with "R=b0" option, it will dynamically supports i.MX 8X B0/C0.

- SECO FW

Use the SECO FW v2.5.4 for C0 and later version.

### NOTE

The SECO FW has two separated version for i.MX 8X B0 and C0, naming as "mx8qxb0-ahab-container.img" and "mx8qxc0-ahab-container.img", use the one for C0.

- U-boot

Two patches are needed based on L4.14.98\_2.0.0\_ga version

1. *[PATCH] MLK-22711-1 show RevC instead of Rev? at boot log*

*Add REVC informaiton.*

*Signed-off-by: Frank Li <Frank.Li@nxp.com>*

---

arch/arm/include/asm/arch-imx/cpu.h | 1 +

arch/arm/mach-imx/imx8/cpu.c | 2 ++

2 files changed, 3 insertions(+)

diff --git a/arch/arm/include/asm/arch-imx/cpu.h b/arch/arm/include/asm/arch-imx/cpu.h

index 05d48f6..ae5d02f 100644

--- a/arch/arm/include/asm/arch-imx/cpu.h

+++ b/arch/arm/include/asm/arch-imx/cpu.h

@@ -67,6 +67,7 @@

#define CHIP\_REV\_A 0x0

#define CHIP\_REV\_B 0x1

+#define CHIP\_REV\_C 0x2

#define BOARD\_REV\_1\_0 0x0

#define BOARD\_REV\_2\_0 0x1

diff --git a/arch/arm/mach-imx/imx8/cpu.c b/arch/arm/mach-imx/imx8/cpu.c

index 2f4af58..2cda814 100644

--- a/arch/arm/mach-imx/imx8/cpu.c

+++ b/arch/arm/mach-imx/imx8/cpu.c

@@ -81,6 +81,8 @@ const char \*get\_imx8\_rev(u32 rev)

return "A";

case CHIP\_REV\_B:

```

return "B";
+ case CHIP_REV_C:
+ return "C";
default:
return "?";
}
--

```

2. [PATCH] MLK-22711-2: fastboot: emmc: update bootloader to offset 0 for RevC QXP chip

ROM update emmc offset to 0.

previous B0 is 32K.

Signed-off-by: Frank Li <Frank.Li@nxp.com>

---

drivers/usb/gadget/f\_fastboot.c | 2 +-  
1 file changed, 1 insertion(+), 1 deletion(-)

diff --git a/drivers/usb/gadget/f\_fastboot.c b/drivers/usb/gadget/f\_fastboot.c

index df8b537..eb1a06d 100644

--- a/drivers/usb/gadget/f\_fastboot.c

+++ b/drivers/usb/gadget/f\_fastboot.c

@@ -797,7 +797,7 @@ static ulong bootloader\_mmc\_offset(void)

{

if (is\_imx8mq() || is\_imx8mm() || (is\_imx8() && is\_soc\_rev(CHIP\_REV\_A)))

return 0x8400;

- else if (is\_imx8qm()) {

+ else if (is\_imx8qm() || (is\_imx8qxp() && !is\_soc\_rev(CHIP\_REV\_B))) {

if (MEK\_8QM\_EMMC == fastboot\_devinfo.dev\_id)

/\* target device is eMMC boot0 partition, bootloader offset is 0x0 \*/

return 0x0;

--

- Linux Kernel

No changes base on L4.14.98\_2.0.0\_ga version

- Release

Currently i.MX 8QuadXPlus C0 BSP release L4.14.98\_2.3.0 is available under following link:

[https://www.nxp.com/webapp/Download?colCode=L4.14.98\\_2.3.0\\_MX8QXP&appType=license](https://www.nxp.com/webapp/Download?colCode=L4.14.98_2.3.0_MX8QXP&appType=license)

Find the release note under following link:

[https://www.nxp.com/webapp/Download?colCode=L4.14.98\\_2.3.0\\_LINUX\\_DOCS](https://www.nxp.com/webapp/Download?colCode=L4.14.98_2.3.0_LINUX_DOCS)

## 2.4 Hardware changes

No hardware changes for i.MX 8X C0 migration.

## 3 Revision history

Revision number	Date	Substantive changes
0	03/2020	Initial release

## ***How To Reach Us***

### **Home Page:**

[nxp.com](http://nxp.com)

### **Web Support:**

[nxp.com/support](http://nxp.com/support)

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: [nxp.com/SalesTermsandConditions](http://nxp.com/SalesTermsandConditions).

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer's applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, COOLFLUX, EMBRACE, GREENCHIP, HITAG, I2C BUS, ICODE, JCOP, LIFE VIBES, MIFARE, MIFARE CLASSIC, MIFARE DESFire, MIFARE PLUS, MIFARE FLEX, MANTIS, MIFARE ULTRALIGHT, MIFARE4MOBILE, MIGLO, NTAG, ROADLINK, SMARTLX, SMARTMX, STARPLUG, TOPFET, TRENCHMOS, UCODE, Freescale, the Freescale logo, Altivec, C-5, CodeTEST, CodeWarrior, ColdFire, ColdFire+, C-Ware, the Energy Efficient Solutions logo, Kinetis, Layerscape, MagniV, mobileGT, PEG, PowerQUICC, Processor Expert, QorIQ, QorIQ Qonverge, Ready Play, SafeAssure, the SafeAssure logo, StarCore, Symphony, VortiQa, Vybrid, Airfast, BeeKit, BeeStack, CoreNet, Flexis, MXC, Platform in a Package, QUICC Engine, SMARTMOS, Tower, TurboLink, UMEMS, EdgeScale, EdgeLock, eIQ, and Immersive3D are trademarks of NXP B.V. All other product or service names are the property of their respective owners. AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, µVision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved. Oracle and Java are registered trademarks of Oracle and/or its affiliates. The Power Architecture and Power.org word marks and the Power and Power.org logos and related marks are trademarks and service marks licensed by Power.org.

© NXP B.V. 2020.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: 5 March 2020

Document identifier: AN12770

