

# EB00875

## Considerations for Avoiding Stuck-In-Reset Scenarios Caused by Non-Correctable ECC Errors in Flash

Rev. 0 — January 2019

Engineering Bulletin

by: NXP Semiconductors

### 1 Introduction

The MPC574xB/C/G functionality is to keep the device in stuck-in-reset (SIR) mode if a non-correctable ECC error is detected within the flash regions listed:

Table 1. Flash addresses

Start Address	End Address	Size (bytes)	Description
0x00F8_C000	0x00F8_C018	28	HSM Code Flash (Sub-Region)
0x0061_0000	0x0061_0018	28	HSM Code Block 2 (Sub-Region)
0x0061_4000	0x0061_4018	28	HSM Code Block 2 (Sub-Region)
0x0062_0000	0x0062_0018	28	HSM Code Block 3 (Sub-Region)
0x0040_0200	0x0040_024F	80	Lifecycle region in UTEST
0x0040_0300	0x0040_0FFF	3328	DCF record region in UTEST

Care must be taken by the customer when erasing or programming these flash addresses so as to not cause any non-correctable ECC errors.

### 2 RESET behaviour

To check if the device is successfully leaving reset or if it is permanently SIR, the RESET line of the device must be monitored.

Table 2. MPC574xB/C/G

Package	Package Pin
100 BGA	F1
176 LQFP	29
256 BGA	K1
324 BGA	L1

An oscilloscope must be used to probe the RESET line and begin capturing the state of the pin as the device is powered on:

#### Contents

1 Introduction.....	1
2 RESET behaviour.....	1
3 Common causes of ECC errors.....	2
4 Questions for customers experiencing SIR.....	2



- On power up, if the RESET line is brought high at any point or is seen to toggle, then the device is **leaving reset**. In this case, the device can be recovered by attaching a debugger and further analysis can be performed to determine the source of the reset.
- On power up, if the RESET line is always low then the device is never leaving reset and is said to be **SIR**. In this scenario, the device can never be recovered and a debugger cannot be attached. Alternative methods of analysis must be explored.

Although there are few methods for debugging a device which is SIR, the reasons for the device demonstrating this behaviour are also few.

### 3 Common causes of ECC errors

Below is a list of the most common causes of non-correctable ECC errors, in order of most likely:

1. Unstable power supply during programming/erasing causing flash commands to be interrupted mid-execution.
2. EEPROM emulation is always prone to ECC errors. Performing EEPROM emulation in inappropriate regions of flash can cause the device to be caught in a reset escalation. Customer must keep EEPROM emulation contained within the flash regions marked for EEPROM in the reference manual. NXP also provide an [EEPROM emulation library](#).
3. Poorly written flash code by either the customer or the tool vendor which is either not using the NXP [Flash driver library](#), or is not following the same correct implementation.
4. Depending on the device & mask set, BIST can run by default on power-up. The programmer tool must wait a sufficient length of time until this BIST is complete before it begins sending flash commands.

**Table 3. Reset duration**

Device	Mask set	Reset duration
MPC5748G	1N81M (Cut 2.0)	0.4ms
	0N78S (Cut 3.0)	7.6ms
MPC5746C	1N06M (Cut 1.1)	6.2ms
	1N84S (Cut 2.1)	6.2ms

### 4 Questions for customers experiencing SIR

If device is not exiting reset, below are a set of questions which should be answered and forwarded to NXP to help find the root cause which is triggering this behaviour:

1. Which device and which mask set is being used, provide full device markings?
2. What is the behaviour of the RESET line at the moment of device power up? Low/high/toggling? (Provide scope plots)
3. Which percentage of devices are experiencing this reset issue?
4. Can the issue be recreated? If so, how?
5. Has anything changed in the customer's process that coincides with these issues occurring?
6. Is the issue being generated at run-time, or during programming of the device?
7. If during programming, which tool is being used to program the device (Lauterbach, PEmicro, Cyclone, ..)?
8. If during runtime, which piece of SW is modifying flash (Bootloader, EEPROM, and which provider?)
9. Which areas of flash are being erased ? Which flash blocks are being written ?
10. Have any of the four HSM code blocks listed in Table 1 been programmed, erased, or used for EEPROM emulation?
11. What is the Life Cycle (LC) of the device?

12. Is there an external watchdog in the system which requires servicing from the device?

## How To Reach Us

### Home Page:

[nxp.com](http://nxp.com)

### Web Support:

[nxp.com/support](http://nxp.com/support)

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: [nxp.com/SalesTermsandConditions](http://nxp.com/SalesTermsandConditions).

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer's applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, COOLFLUX, EMBRACE, GREENCHIP, HITAG, I2C BUS, ICODE, JCOP, LIFE VIBES, MIFARE, MIFARE CLASSIC, MIFARE DESFire, MIFARE PLUS, MIFARE FLEX, MANTIS, MIFARE ULTRALIGHT, MIFARE4MOBILE, MIGLO, NTAG, ROADLINK, SMARTLX, SMARTMX, STARPLUG, TOPFET, TRENCHMOS, UCODE, Freescale, the Freescale logo, AltiVec, C-5, CodeTEST, CodeWarrior, ColdFire, ColdFire+, C-Ware, the Energy Efficient Solutions logo, Kinetis, Layerscape, MagniV, mobileGT, PEG, PowerQUICC, Processor Expert, QorIQ, QorIQ Qonverge, Ready Play, SafeAssure, the SafeAssure logo, StarCore, Symphony, VortiQa, Vybrid, Airfast, BeeKit, BeeStack, CoreNet, Flexis, MXC, Platform in a Package, QUICC Engine, SMARTMOS, Tower, TurboLink, and UMEMS are trademarks of NXP B.V. All other product or service names are the property of their respective owners. AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamiQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro,  $\mu$ Vision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved. Oracle and Java are registered trademarks of Oracle and/or its affiliates. The Power Architecture and Power.org word marks and the Power and Power.org logos and related marks are trademarks and service marks licensed by Power.org.

© NXP B.V. 2019.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: January 2019

Document identifier: EB00875

