

# ERRATA SHEET

**Date:** 2005 Apr 04  
**Document Release:** Version 1.0  
**Device Affected:** P89LPC938

This errata sheet describes both the functional deviations and any deviations from the electrical specifications known at the release date of this document.

Each deviation is assigned a number and its history is tracked in a table at the end of the document.

2005 Apr 04

**Identification:**

The typical P89LPC938 devices have the following top-side marking:

P89LPC938x x  
xxxxxxx xx  
xxYYWW R

The last letter in the third line (field 'R') will identify the device revision. This Errata Sheet covers the following revisions of the P89LPC938:

Revision Identifier (R)	Comment
'A'	Initial device revision

Field 'YY' states the year the device was manufactured. Field 'WW' states the week the device was manufactured during that year.

**Errata Overview - Functional Problems**

Functional Problem	Short Description	fixed in revision	added
EEPROM.1	EEPROM lock-up on power up	none	v1.0
DIVM.1	Using DIVM in power-down mode	none	v1.0

**Errata Overview - AC/DC Deviations**

AC/DC Deviation	Short Description	fixed in revision	added
-	-	-	-

**Errata Notes**

Note	Short Description	added
V <sub>DD</sub> .1	V <sub>DD</sub> Power cycling	v1.0
IRC.1	Internal RC oscillator accuracy	v1.0

## Functional Deviations of P89LPC938

### EEPROM.1: EEPROM lock-up on power up

**Introduction:** The LPC938 has onboard data EEPROM, which allows to store non volatile data bytes on the LPC938 that will hold their value when the power is not applied to the LPC938.

**Problem:** With a slow rising VDD slower than 10ms there is a chance that the EEPROM circuitry will lock up, and incorrect data will be read out.

The EEPROM itself still has the correct data.

**Workaround:** The data EEPROM can be unlocked by a dummy write cycle. The following function shows a dummy write cycle.

```
void dummywrite(void)
{
    DEECON &= 0x0E;           // EEPROM write mode
    DEEDAT = 0x5A;           // dummy data
    DEEADR = 0x00;           // dummy write address 0x000
    while(!(DEECON&0x80))    // wait till interrupt flag is set
    {
    }
}
```

### DIVM.1: Using DIVM in power-down mode

**Introduction:** The LPC938 has a DIVM register that can be used to divide the cclk down. Using DIVM can greatly reduce power when in active mode.

**Problem:** When DIVM is used in active mode and power-down mode is then entered the LPC938 can not be waken up from power down mode.

**Workaround:** Before entering powerdown mode set DIVM back to 0x00. This way the LPC938 will be operating full speed for one instruction before entering power-down mode. After the LPC938 has been waken up DIVM can be set back to its original value.

---

## **Electrical and Timing Specification Deviations of P89LPC938**

**No known errata**

## Errata Notes

### **V<sub>DD</sub>.1: V<sub>DD</sub> Power cycling**

To generate a proper Power-On-Reset (POR), V<sub>DD</sub> must have dropped below 0.2V before being powered back up. Power-cycling without V<sub>DD</sub> having dropped below 0.2V may result in incorrect Program Counter values.

Please also see the V<sub>POR</sub> specification in LPC938 Datasheet, DC electrical characteristics. Section 8.15 (Reset) states that during a power cycle, V<sub>DD</sub> must fall below V<sub>POR</sub>.

### **IRC.1: Internal RC oscillator accuracy**

To be able to guarantee the Internal RC oscillator accuracy over the full operating range the V<sub>DD</sub> supply has to be decoupled sufficiently. Sufficient decoupling is dependant on the noise level in the application, typically a 1uF should be sufficient for most applications.

Noise on the V<sub>DD</sub> supply pins can cause the Internal RC oscillator to go slightly outside of the specified range.