

# MPC567xK\_0N66N\_0N72D

## Mask Set Errata

Rev. 3 — 27 November 2024

Errata

## 1 Mask Set Errata for Mask 0N66N\_0N72D

### 1.1 Revision History

This report applies to mask 0N66N\_0N72D for these products:

- MPC567xK

Table 1. Revision History

Revision	Release Date	Significant Changes
3	11/2024	The following errata were added. <ul style="list-style-type: none"><li>• ERR051698</li><li>• ERR008970</li><li>• ERR050782</li><li>• ERR009764</li><li>• ERR009976</li><li>• ERR010755</li><li>• ERR009658</li><li>• ERR009928</li><li>• ERR008933</li><li>• ERR008951</li></ul> The following errata were revised. <ul style="list-style-type: none"><li>• ERR007394</li></ul>
31MAR2016	4/2016	The following errata were added. <ul style="list-style-type: none"><li>• ERR003416</li></ul>
15JUL2015	7/2015	Initial Revision

### 1.2 Errata and Information Summary

Table 2. Errata and Information Summary

Erratum ID	Erratum Title
<a href="#">ERR003416</a>	DMA: Improper operation when used with Cache Coherency Unit.
<a href="#">ERR003866</a>	ADC Self Test algorithm S0 result can be incorrect at low temperature
<a href="#">ERR004396</a>	e200z7: Erroneous Address Fetch
<a href="#">ERR005008</a>	PMC: Potential stuck in reset condition if certain pins are pulled up too hard during power up.
<a href="#">ERR005569</a>	ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain
<a href="#">ERR006967</a>	eDMA: Possible misbehavior of a preempted channel when using continuous link mode
<a href="#">ERR007394</a>	MC_ME: Incorrect mode may be entered on low-power mode exit.
<a href="#">ERR007589</a>	LINFlexD: Spurious timeout error when switching from UART to LIN mode or when resetting LINTCSR[MODE] bit in LIN mode



Table 2. Errata and Information Summary...continued

Erratum ID	Erratum Title
<a href="#">ERR007877</a>	FlexPWM: do not enable the fault filter
<a href="#">ERR008770</a>	FlexRAY: Missing TX frames on Channel B when in dual channel mode and Channel A is disabled
<a href="#">ERR008933</a>	LINFlexD: Inconsistent sync field may cause an incorrect baud rate and the Sync Field Error Flag may not be set
<a href="#">ERR008951</a>	I2C: Attempting a start cycle while the bus is busy may generate a short clock pulse
<a href="#">ERR008970</a>	LINFlexD: Spurious bit error in extended frame mode may cause an incorrect Idle State
<a href="#">ERR009658</a>	SPI: Inconsistent loading of shift register data into the receive FIFO following an overflow event
<a href="#">ERR009764</a>	SARADC : DMA interface limitation depending on PBRIDGE/SARADC clock ratio
<a href="#">ERR009928</a>	FlexPWM: Half cycle automatic fault clearing does not work in PWM submodule 0 under some conditions
<a href="#">ERR009976</a>	DSPI: Incorrect data received by master with Modified transfer format enabled when using Continuous serial communication clock mode
<a href="#">ERR010755</a>	DSPI: Transmit and Receive FIFO fill flags in status register is not cleared when DMA is improperly configured
<a href="#">ERR050782</a>	e200: Time Base TBU register contains wrong value during TBL rollover
<a href="#">ERR051698</a>	CTU : Double buffer reload mechanism is blocked when master reload pulse is not generated by Software

## 2 Known Errata

### ERR003416: DMA: Improper operation when used with Cache Coherency Unit.

#### Description

When the Cache Coherency Unit (CCU) is enabled to monitor DMA writes, the DMA can occasionally apply an extra destination offset (doff) to the destination address (daddr) in the Transfer Control Descriptor of a channel. This causes the DMA to write outside the bounds defined by the application in the TCD structure.

#### Workaround

Disable write monitoring of the DMA channels and either inhibit caching for regions of memory shared between the DMA and CPU cores or handle coherency manually in software. The CCU may still be enabled to manage cache coherency for memory shared between the two CPU cores only.

Alternatively, if it is possible to reprogram the TCD with no destination offset (doff=0) then the extra offset will have no effect when the error occurs. If the TCD can be re-defined such that each minor loop consists only of a single data transfer (nBytes = dSize) then destination offset can be set to zero and minor loop offset (mloff) used instead to advance the destination address. This requires enabling Minor Loop Mapping for all channels by setting `DMA_x_MCR[EMLM] = 1`. TCDs not writing to coherent memory are unaffected by this mode provided their minor loop byte counts (nBytes) are not greater than or equal to 1 GB (The minor loop mapping mode uses the two high order bits of the nBytes field to enable source and/or destination minor loop offset).

### ERR003866: ADC Self Test algorithm S0 result can be incorrect at low temperature

#### Description

The ADC Self Test algorithm S step 0 (S0) measures ADC Vbandgap / VDD\_HV\_ADR. In the case where the S0 step occurs after the ADC has sampled and converted a value close to VDD\_HV\_ADR at low temperature (for example -40C) in some process corners the sampling time (specified by INPSAMP\_S) of 80h is not long enough to allow the correct ADC sampling capacitor settling. This may lead to an incorrect converted value.

The Band Gap in the above specified condition is slow in discharging the sampling capacitor when the previous sampled voltage is much larger than the Band Gap output voltage (nominally 1.2V). The larger the voltage sampled before S0, the slower is the settling.

This issue can also affect S1 algorithm results since  $S1 = VDD\_HV\_ADV / Vbandgap$ .

#### Workaround

To eliminate the problem it is mandatory to:

- (a) increase the sampling time for S supply self test (INSAMP\_S) from 80h to FFh and
- (b) insert a sacrificial ADC conversion immediately before the S supply self test.

The user software must insert a single-shot S algorithm Step 0 conversion (also called sacrificial S0 conversion) before the normal S supply self test to achieve accurate sample capacitor settling. The user software must prohibit any other conversions between the sacrificial S0 conversion and normal S0 conversion of the S supply self test.

**ERR004396: e200z7: Erroneous Address Fetch****Description**

Under certain conditions, if a static branch prediction and a dynamic return prediction (which uses the subroutine return address stack) occur simultaneously in the Branch Target Buffer (BTB), the e200z7 core can issue an errant fetch address to the memory system (instruction fetched from wrong address).

This can only happen when the static branch prediction is "taken" but the branch actually resolves to "not taken". If the branch resolves to taken, correct fetching occurs for this branch path and no issue is seen.

If Branch Unit Control and Status Register (BUCSR) Branch Prediction Control Static (BPRED) = 0b00, 0b01, or 0b10, then static branch prediction is configured as "taken". The issue can occur with these settings.

If BUSCR[BPRED] = 0b11, then static branch prediction is configured as "not taken". The issue does not occur with this setting.

**Workaround**

To prevent the issue from occurring, configure static branch prediction to "not taken" by setting the Branch Unit Control and Status Register (BUCSR) Branch Prediction Control Static (BPRED) to 0b11.

**ERR005008: PMC: Potential stuck in reset condition if certain pins are pulled up too hard during power up.****Description**

If the below identified pins are pulled high either with a direct short or with too small a resistance during power up, a stuck in reset condition can occur due to a failure to deassert internal LVDs on the 3.3V rail or the 1.2V rail. This affects both internal and external regulation modes of the PMC. There is no issue if the pins are no connects/floating or pulled low with any resistor value.

The pins affected are:

Pin 1: ETIMER1\_ETC5/SIUL\_GPIO78/SIUL\_EIRQ26 (Y15 for 473 BGA, P13 for 257 BGA)

Pin 2: ETIMER1\_ETC3/SIUL\_GPIO92/CTU1\_EXT\_IN/MC\_RGM\_FAB/SIUL\_EIRQ30 (Y11 for 473 BGA, P8 for 257 BGA)

Pin 3: ETIMER1\_ETC4/SIUL\_GPIO93/CTU1\_EXT\_TGR/SIUL\_EIRQ31 (Y16 for 473 BGA, P12 for 257 BGA)

**Workaround**

1. If pins 1 or 3 need to be pulled high during power up, a 20 K ohm resistor or greater must be installed between each pin and the voltage source.
2. If the serial boot option is needed :
  - a) If entering during power up, a 20 K ohm 1% resistor must be installed between Pin 2 (the MC\_RGM\_FAB pin) and the voltage source and the ambient temperature is between -40C and 80C.
  - b) If entering after reset deassertion, the following sequence can be used from -40C to 125C.
    - i. Power up device with Pin 2 (MC\_RGM\_FAB pin) low.
    - ii. Verify device is out of reset.
    - iii. Pull FAB pin up to Vih level. This will be achieved with a resistance value less than 18 K ohm.

iv. Assert and deassert RESET\_B either through a hardware induced pin toggle or a software induced destructive or functional reset using the ME module.

## **ERR005569: ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain**

### **Description**

If One shot mode is configured in the Main Configuration Register ( $MCR[MODE] = 0$ ) the chained channels are automatically enabled in the Normal Conversion Mask Register 0 (NCMR0). If the programmer initiates a new chain normal conversion, by setting  $MCR[NSTART] = 0x1$ , before the previous chain conversion finishes, the new chained normal conversion will not follow the requested sequence of converted channels.

For example, if a chained normal conversion sequence includes three channels in following sequence: channel0, channel1 and channel2, the conversion sequence is started by  $MCR[NSTART] = 0x1$ . The software re-starts the next conversion sequence when  $MCR[NSTART]$  is set to 0x1 just before the current conversion sequence finishes.

The conversion sequence should be: channel0, channel1, channel2, channel0, channel1, channel2.

However, the conversion sequence observed will be: channel0, channel1, channel2, channel1, channel1, channel2. Channel0 is replaced by channel1 in the second chain conversion and channel1 is converted twice.

### **Workaround**

Ensure a new conversion sequence is not started when a current conversion is ongoing. This can be ensured by issuing the new conversion setting  $MCR[NSTART]$  only when  $MSR[NSTART] = 0$ .

Note:  $MSR[NSTART]$  indicates the present status of conversion.  $MSR[NSTART] = 1$  means that a conversion is ongoing and  $MSR[NSTART] = 0$  means that the previous conversion is finished.

## **ERR006967: eDMA: Possible misbehavior of a preempted channel when using continuous link mode**

### **Description**

When using Direct Memory Access (DMA) continuous link mode Control Register Continuous Link Mode ( $DMA\_CR[CLM] = 1$ ) with a high priority channel linking to itself, if the high priority channel preempts a lower priority channel on the cycle before its last read/write sequence, the counters for the preempted channel (the lower priority channel) are corrupted. When the preempted channel is restored, it continues to transfer data past its "done" point (that is the byte transfer counter wraps past zero and it transfers more data than indicated by the byte transfer count (NBYTES)) instead of performing a single read/write sequence and retiring.

The preempting channel (the higher priority channel) will execute as expected.

### **Workaround**

Disable continuous link mode ( $DMA\_CR[CLM]=0$ ) if a high priority channel is using minor loop channel linking to itself and preemption is enabled. The second activation of the preempting channel will experience the normal startup latency (one read/write sequence + startup) instead of the shortened latency (startup only) provided by continuous link mode.

**ERR007394: MC\_ME: Incorrect mode may be entered on low-power mode exit.****Description**

For the case when the Mode Entry (MC\_ME) module is transitioning from a run mode (RUN0/1/2/3) to a low power mode (HALT/STOP/STANDBY\*) if a wake-up or interrupt is detected one clock cycle after the second write to the Mode Control (ME\_MCTL) register, the MC\_ME will exit to the mode previous to the run mode that initiated the low power mode transition.

Example correct operation DRUN->RUN1-> RUN3->STOP->RUN3

Example failing operation DRUN->RUN1-> RUN3->STOP->RUN1

Note STANDBY mode is not available on all MPC56xx microcontrollers

**Workaround**

To ensure the application software returns to the run mode (RUN0/1/2/3) prior to the low power mode (HALT/STOP/STANDBY\*) it is required that the RUNx mode prior to the low power mode is entered twice.

The following example code shows RUN3 mode entry prior to a low power mode transition.

```
ME.MCTL.R = 0x70005AF0; /* Enter RUN3 Mode & Key */
ME.MCTL.R = 0x7000A50F; /* Enter RUN3 Mode & Inverted Key */
while (ME.GS.B.S_MTRANS) {} /* Wait for RUN3 mode transition to complete */
ME.MCTL.R = 0x70005AF0; /* Enter RUN3 Mode & Key */
ME.MCTL.R = 0x7000A50F; /* Enter RUN3 Mode & Inverted Key */
while (ME.GS.B.S_MTRANS) {} /* Wait for RUN3 mode transition to complete */
/* Now that run mode has been entered twice can enter low power mode */
/* (HALT/STOP/STANDBY*) when desired. */
```

**ERR007589: LINFlexD: Spurious timeout error when switching from UART to LIN mode or when resetting LINTCSR[MODE] bit in LIN mode****Description**

If the LINFlexD module is enabled in Universal Asynchronous Receiver/Transmitter (UART) mode and the value of the MODE bit of the LIN Timeout Control Status register (LINTCSR) is 0 (default value after reset), any activity on the transmit or receive pins will cause an unwanted change in the value of the 8-bit field Output Compare Value 2 (OC2) of the LIN Output Compare register (LINOOCR).

If the LINFlexD module is enabled in LIN mode and the value of the MODE bit of the LIN Timeout Control Status register (LINTCSR) is changed from '1' to '0', then the old value of the Output Compare Value 1 (OC1) and Output Compare Value 2 (OC2) of the LIN Output Compare register (LINOOCR) is retained.

As a consequence, if the module is reconfigured from UART to Local Interconnect Network (LIN) mode, or LINTCSR MODE bit is changed from '1' to '0', an incorrect timeout exception is generated when the LIN communication starts.

## Workaround

If the LINFlexD module needs to be switched from UART mode to LIN mode, before writing UARTCR[UART] to 1, ensure that the LINTCSR[MODE] is first set to 1.

If the LINFlexD module is in LIN mode and LINTCSR[MODE] needs to be switched from 1 to 0 in between frames, the LINOCR must be set to 0xFFFF by software.

## ERR007877: FlexPWM: do not enable the fault filter

### Description

Operation of the fault pin filter of the Flexible Pulse Width Modulation (FLEX\_PWM) may be inconsistent if the Fault Filter is enabled, by setting the Filter Period greater than zero in the Fault Filter register (FFILT[FILT\_PER] > 0). The fault filter flag may be set even though the pulse is shorter than the filter time.

### Workaround

Do not enable the PWM fault pin filters. Disable the fault pin filters by setting the Fault Filter Period to 0 in the Fault Filter Register (FFILT[FILT\_PER] = 0).

## ERR008770: FlexRAY: Missing TX frames on Channel B when in dual channel mode and Channel A is disabled

### Description

If the FlexRay module is configured in Dual Channel mode, by clearing the Single Channel Device Mode bit (SCM) of the Module Control register (FR\_MCR[SCM]=0), and Channel A is disabled, by clearing the Channel A Enable bit (FR\_MCR[CHA]=0) and Channel B is enabled, by setting the Channel B enable bit (FR\_MCR[CHB]=1), there will be a missing transmit (TX) frame in adjacent minislots (even/odd combinations in Dynamic Segment) on Channel B for certain communication cycles. Which channel handles the Dynamic Segment or Static Segment TX message buffers (MBs) is controlled by the Channel Assignment bits (CHA, CHB) of the Message Buffer Cycle Counter Filter Register (FR\_MBCCFRn). The internal Static Segment boundary indicator actually only uses the Channel A slot counter to identify the Static Segment boundary even if the module configures the Static Segment to Channel B (FR\_MBCCFRn[CHA]=0 and FR\_MBCCFRn[CHB]=1). This results in the Buffer Control Unit waiting for a corresponding data acknowledge signal for minislot:N in the Dynamic Segment and misses the required TX frame transmission within the immediate next minislot:N+1.

### Workaround

1. Configure the FlexRay module in Single Channel mode (FR\_MCR[SCM]=1) and enable Channel B (FR\_MCR[CHB]=1) and disable Channel A (FR\_MCR[CHA]=0). In this mode the internal Channel A behaves as FlexRay Channel B. Note that in this mode only the internal channel A and the FlexRay Port A is used. So externally you must connect to FlexRay Port A.

2. Enable both Channel A and Channel B when in Dual Channel mode (FR\_MCR[CHA]=1 and FR\_MCR[CHB]=1). This will allow all configured TX frames to be transmitted correctly on Channel B.

## ERR008933: LINFlexD: Inconsistent sync field may cause an incorrect baud rate and the Sync Field Error Flag may not be set

### Description

When the LINFlexD module is configured as follows:

1. LIN (Local Interconnect Network) slave mode is enabled by clearing the Master Mode Enable bit in the LIN Control Register 1 (LINC1R1[MME] = 0b0)
2. Auto synchronization is enabled by setting LIN Auto Synchronization Enable (LINC1R1[LASE] = 0b1)

The LINFlexD module may automatically synchronize to an incorrect baud rate without setting the Sync Field Error Flag in the LIN Error Status register (LINESR[SFEF]) in case Sync Field value is not equal to 0x55, as per the Local Interconnect Network (LIN) specification.

The auto synchronization is only required when the baud-rate in the slave node can not be programmed directly in software and the slave node must synchronize to the master node baud rate.

### Workaround

There are 2 possible workarounds.

Workaround 1:

When the LIN time-out counter is configured in LIN Mode by clearing the MODE bit of the LIN Time-Out Control Status register (LINTCSR[MODE]= 0x0):

1. Set the LIN state Interrupt enable bit in the LIN Interrupt Enable register (LINIER[LSIE] = 0b1)
2. When the Data Reception Completed Flag is asserted in the LIN Status Register (LINSR[DRF] = 0b1) read the LIN State field (LINSR[LINS])
3. If LINSR[LINS]= 0b0101, read the Counter Value field of the LIN Time-Out Control Status register (LINTCSR[CNT]), otherwise repeat step 2
4. If LINTCSR[CNT] is greater than 0xA, discard the frame.

When the LIN Time-out counter is configured in Output Compare Mode by setting the LINTCSR[MODE] bit:

1. Set the LIN State Interrupt Enable bit in the LIN Interrupt Enable register (LINIER[LSIE])
2. When the Data Reception Completed flag bit is asserted in the LIN Status Register (LINSR[DRF] = 0b1), read the LINSR[LINS] field
3. If LINSR[LINS]= 0b0101, store LINTCSR[CNT] value in a variable (ValueA), otherwise repeat step 2
4. Clear LINSR[DRF] flag by writing LINSR[LINS] field with 0xF
5. Wait for LINSR[DRF] to become asserted again and read LINSR[LINS] field
6. If LINSR[LINS] = 0b0101, store LINTCSR[CNT] value in a variable (ValueB), else repeat step 4
7. If ValueB - ValueA is greater than 0xA, discard the frame

Workaround 2:

Do not use the auto synchronization feature (disable with LINC1R1[LASE] = 0b0) in LIN slave mode.

## ERR008951: I2C: Attempting a start cycle while the bus is busy may generate a short clock pulse

### Description

When the I2C (Inter-Integrated Circuit) is operating in a multi-master network and a start cycle is attempted by the I2C device when the bus is busy, the attempting master will lose arbitration as expected but a short extra clock cycle is generated in the bus. After losing arbitration, the master switches to slave mode but it does not detect the short clock pulse. The acknowledge signal is expected at the ninth clock by the current bus master but it is not sent as expected due to the undetected short clock pulse.

### Workaround

Software must ensure that the I2C BUS is idle by checking the bus busy bit in the I2C Bus Status Register (I2C\_IBSR.IBB) before switching to master mode and attempting a Start cycle.

## ERR008970: LINFlexD: Spurious bit error in extended frame mode may cause an incorrect Idle State

### Description

The LINFlexD module may set a spurious Bit Error Flag (BEF) in the LIN Error Status Register (LINESR), when the LINFlexD module is configured as follows:

- Data Size greater than eight data bytes (extended frames) by configuring the Data Field Length (DFL) bitfield in the Buffer Identifier Register (BIDR) with a value greater than seven (eight data bytes)
- Bit error is able to reset the LIN state machine by setting Idle on Bit Error (IOBE) bit in the LIN Control Register 2 (LINC2)

As consequence, the state machine may go to the Idle State when the LINFlexD module tries the transmission of the next eight bytes, after the first ones have been successfully transmitted and Data Buffer Empty Flag (DBEF) was set in the LIN Status Register (LINSR).

### Workaround

Do not use the extended frame mode by configuring Data Field Length (DFL) bit-field with a value less than eight in the Buffer Identifier Register (BIDR) ( $BIDR[DFL] < 8$ )

## ERR009658: SPI: Inconsistent loading of shift register data into the receive FIFO following an overflow event

### Description

In the Serial Peripheral Interface (SPI) module, when both the receive FIFO and shift register are full (Receive FIFO Overflow Flag bit in Status Register is set ( $SR[RFOF] = 0b1$ )) and then the Clear Rx FIFO bit in Module Configuration Register (MCR [CLR\_RXF]) is asserted to clear the receive FIFO, shift register data is sometimes loaded into the receive FIFO after the clear operation completes.

## Workaround

1. Avoid a receive FIFO overflow condition (SR[RFOF] should never be 0b1). To do this, monitor the RX FIFO Counter field of the Status Register (SR[RXCTR]) which indicates the number of entries in receive FIFO and clear before the counter equals the FIFO depth.
2. Alternatively, after every receive FIFO clear operation (MCR[CLR\_RXF] = 0b1) following a receive FIFO overflow (SR[RFOF] = 0b1) scenario, perform a single read from receive FIFO and discard the read data.

## ERR009764: SARADC : DMA interface limitation depending on PBRIDGE/SARADC clock ratio

### Description

The Successive Approximation Register Analog-to-Digital Converter (SARADC) modules can trigger a Direct Memory Access (DMA) request through the DMA Enable (DMAE) register interface.

When the SARADC clock (SAR\_CLK) frequency is slower than half of the peripheral bridge (PBRIDGEx\_CLK) clock frequency, the SARADC may trigger a spurious transfer request to the DMA module after the completion of a first valid transfer.

### Workaround

Setting the DMA clear sequence enable (DCLR) bit in the DMAE register (DMAE[DCLR] = 1) forces the clearing of the DMA request on read access to the data register and therefore prevents the spurious DMA transfer request.

In case the Internal Channel Data Registers (ICDRn) are only accessed through DMA module (i.e. there are no bus accesses to ICDRn registers triggered by other than DMA bus master when the DMAE[DMAEN] bit is set), it is possible to configure DMAE[DCLR] bit to '1'. This will clear DMA transfer request on the first DMA read access, ensuring both that DMA triggered transfer will complete successfully and that no other spurious DMA request will be triggered.

This work-around can be applied when any of below condition can be met:

- frequency ratio PBRIDGEx\_CLK/SAR\_CLK  $\leq$  8/3
- PBRIDGEx\_CLK is 40MHz and SAR\_CLK  $\geq$  14MHz

## ERR009928: FlexPWM: Half cycle automatic fault clearing does not work in PWM submodule 0 under some conditions

### Description

When

- a) the EXT\_SYNC signal is selected to cause initialization by setting the Submodule 0 Control 2 Register FlexPWM\_SUB0\_CTRL2[INIT\_SEL] = 11 and
  - b) a specific FAULTx input is associated with the submodule 0 outputs using the Submodule 0 Fault Disable Mapping Register (FlexPWM\_SUB0\_DISMAP) and
  - c) the respective bit for that FAULTx is 0 in the FFULL bitfield of the Fault Status Register FlexPWM\_FSTS and
  - d) the respective bit for that FAULTx is 1 in the FAUTO bitfield of the Fault Control Register FlexPWM\_FCTRL,
- then the PWM outputs of submodule 0 will only be re-enabled at the cycle boundary (full cycle) and will not be re-enabled at the cycle midpoint (half cycle).

## Workaround

When the EXT\_SYNC signal is used to cause initialization in submodule 0 and the submodule 0 PWM outputs are disabled by a specific FAULTx input, use full cycle automatic fault clearing for the specific FAULTx input by setting the corresponding bit of the Fault Status Register FlexPWM\_FSTS[FFULL] to 1.

## ERR009976: DSPI: Incorrect data received by master with Modified transfer format enabled when using Continuous serial communication clock mode

### Description

When the Deserial Serial Peripheral Interface (DSPI) module is configured as follows:

1. Master mode is enabled (Master/Slave Mode Select bit in Module Configuration Register is set (DSPI\_MCR [MSTR] = 0b1))
2. Modified transfer format is enabled (Modified Transfer Format Enable bit in Module Configuration Register is set (DSPI\_MCR [MTFE] = 0b1))
3. Continuous serial communication clock mode is enabled (Continuous SCK Enable bit in Module Configuration Register is set (DSPI\_MCR [CONT\_SCKE] = 0b1))

In this configuration if the frame size of the current frame is greater than the frame size of the next received frame, corrupt frames are received in two scenarios:

- a) Continuous Peripheral Chip Select Enable bit in PUSH TX FIFO Register is set (DSPI\_PUSHR [CONT] = 0b1)
- b) DSPI\_PUSHR [CONT] = 0b0 and lower significant bit of the frame is transferred first (LSB first bit in Clock and Transfer Attributes Register is set (DSPI\_CTAR [LSBFE] = 0b1))

### Workaround

To receive correct frames:

- a) When DSPI\_PUSHR [CONT] = 0b1, configure the frame size of the current frame less than or equal to the frame size of the next frame (for all frames).
- b) When DSPI\_PUSHR [CONT] = 0b0, configure DSPI\_CTAR [LSBFE] = 0b0. Alternatively, configure the frame size of the current frame less than or equal to the frame size of the next frame (for all frames).

Make sure that for all received frames, the bits are read equal to their respective frame sizes and any extra bits during POP operation are masked.

## ERR010755: DSPI: Transmit and Receive FIFO fill flags in status register is not cleared when DMA is improperly configured

### Description

The Deserial/Serial Peripheral Interface Transmit and Receive First In/First Out (FIFO) buffers can request additional information to be transferred via the Direct Memory Access (DMA) module when either the Transmit or Receive FIFO Fill/Drain Flags are set in the DSPI Status Register (SR[TFFF/RDFD]). However, the Transmit Fill Flag indicates that at least 1 location each (2 bytes each) in the Transmit and Command FIFOs is available to be written. It does not indicate that the FIFO is empty. Similarly, Receive FIFO fill flag only indicates at least 1 location (2 bytes) of the FIFO is available to be read. It does not indicate that the FIFO is full. If the DMA is configured to transfer more than 1 FIFO location size of data, the FIFO Fill/Drain Flags may not be properly

cleared indicating that the FIFO is not full even when the FIFO is actually full (for Transmit FIFO) and not empty when the FIFO is actually empty (for Receive FIFO).

### Workaround

Properly configure the DMA to fill/drain only 2 bytes to Transmit, Command and Receive FIFOs. Use the DMA loop to transfer more data if needed.

## ERR050782: e200: Time Base TBU register contains wrong value during TBL rollover

### Description

The e200 Time Base (TB) facility is a 64-bit structure provided for maintaining the time of day and operating interval timers. The TB consists of two 32-bit registers - time base upper (TBU) and time base lower (TBL). TBU and TBL are concatenated to provide a long-period 64-bit counter. TBL increments until its value becomes 0xFFFF\_FFFF. The intended behavior is that at the next increment when the TBL value becomes 0x0000\_0000 that the TBU value is incremented. But the actual behavior is that after the TBL value becomes 0x0000\_0000, the TBU value will not increment until the transition of the TBL value to 0x0000\_0001.

### Workaround

Software will need to take care about the wrong TBU value during TBL rollover. Use the following sequence for reading TBU and TBL values:

loop:

```
mfscr r12, TBL
```

```
mfscr r3, TBU
```

```
mfscr r4, TBL
```

```
cmpl r4,r12
```

```
se_blt loop
```

## ERR051698: CTU : Double buffer reload mechanism is blocked when master reload pulse is not generated by Software

### Description

CTU operates on two clock domains. The Bus Interface Clock (BIC) domain, used for SW communication and the Module Clock (MC) domain, used for its own functionality. The FGRE bit of CR register is set with first write into double buffered registers in BIC domain and the synchronization logic propagates this set bit into the MC domain. FGRE bit is cleared in both domains when the MR occurs and FGRE bit is equal to GRE bit in the MC domain. Double buffered registers are reloaded only when MR occurs and FGRE and GRE bit are set in the MC domain. But when the MR occurs at the same time as FGRE bit set, generated by first double buffered register write, is propagated into the MC domain the FGRE bits are cleared in both.

Two possible cases can happen:

- 1) In case of updating one double buffered register the reload doesn't occur and the CR register is kept in 0x2 value which blocks further double buffered register update.
- 2) In case of updating more than one double buffered register the reload doesn't occur and the CR register is kept in 0xA when the delay between first and second double buffered register write is less than the synchronization propagation time which blocks further register update.

## Workaround

1) Generate the Master reload pulse by SW (by setting the bit CR[MRS\_SG] after setting GRE at the end of update sequence )

2) Master reload pulse is not generated by SW and one double buffered register to be updated:

The register needs to be written twice with the delay between the writes longer than synchronization propagation time.

3) Master reload pulse is not generated by SW and more than one double buffered register to be updated:

The delay between write to first and second double buffered register needs to be longer than synchronization propagation time.

Synchronization propagation time =  $(6 \cdot \text{BIC})$  cycles +  $(5 \cdot \text{MC})$  cycles, where BIC is Bus Interface Clock period and MC is Module Clock period.

## Legal information

### Definitions

**Draft** — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

### Disclaimers

**Limited warranty and liability** — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

**Right to make changes** — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Applications** — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

**Limiting values** — Stress above one or more limiting values (as defined in the Absolute Maximum Ratings System of IEC 60134) will cause permanent damage to the device. Limiting values are stress ratings only and (proper) operation of the device at these or any other conditions above those given in the Recommended operating conditions section (if present) or the Characteristics sections of this document is not warranted. Constant or repeated exposure to limiting values will permanently and irreversibly affect the quality and reliability of the device.

**Terms and conditions of commercial sale** — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at <https://www.nxp.com/profile/terms>, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

**No offer to sell or license** — Nothing in this document may be interpreted or construed as an offer to sell products that is open for acceptance or the grant, conveyance or implication of any license under any copyrights, patents or other industrial or intellectual property rights.

**Suitability for use in automotive applications** — This NXP product has been qualified for use in automotive applications. If this product is used by customer in the development of, or for incorporation into, products or services (a) used in safety critical applications or (b) in which failure could lead to death, personal injury, or severe physical or environmental damage (such products and services hereinafter referred to as "Critical Applications"), then customer makes the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, safety, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP. As such, customer assumes all risk related to use of any products in Critical Applications and NXP and its suppliers shall not be liable for any such use by customer. Accordingly, customer will indemnify and hold NXP harmless from any claims, liabilities, damages and associated costs and expenses (including attorneys' fees) that NXP may incur related to customer's incorporation of any product in a Critical Application.

**Quick reference data** — The Quick reference data is an extract of the product data given in the Limiting values and Characteristics sections of this document, and as such is not complete, exhaustive or legally binding.

**Export control** — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.

**HTML publications** — An HTML version, if available, of this document is provided as a courtesy. Definitive information is contained in the applicable document in PDF format. If there is a discrepancy between the HTML document and the PDF document, the PDF document has priority.

**Translations** — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.

**Security** — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately. Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at [PSIRT@nxp.com](mailto:PSIRT@nxp.com)) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

**NXP B.V.** — NXP B.V. is not an operating company and it does not distribute or sell products.

## Trademarks

**NXP** — wordmark and logo are trademarks of NXP B.V.

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

Contents

1 Mask Set Errata for Mask 0N66N\_0N72D ..... 1  
1.1 Revision History ..... 1  
1.2 Errata and Information Summary ..... 1  
2 Known Errata ..... 3  
Legal information ..... 14

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

© November 2024 NXP B.V.

All rights reserved.

For more information, please visit: <https://www.nxp.com>

[Document feedback](#)

Date of release: 27 November 2024

Document identifier: MPC567XK\_0N66N\_0N72D