

Mask Set Errata

MSE08AZ32_1H56A
12/2002

Mask Set Errata for
MC68HC08AZ32,
Mask 1H56A



Introduction

This mask set errata applies to this MC68HC08AZ32 MCU mask set:

- 1H56A

MCU Device Mask Set Identification

The mask set is identified by a 5-character code consisting of a version number, a letter, two numerical digits, and a letter, for example 1H56A. All standard devices are marked with a mask set number and a date code.

MCU Device Date Codes

Device markings indicate the week of manufacture and the mask set used. The date is coded as four numerical digits where the first two digits indicate the year and the last two digits indicate the work week. For instance, the date code "0201" indicates the first week of the year 2002.

MCU Device Part Number Prefixes

Some MCU samples and devices are marked with an SC, PC, or XC prefix. An SC prefix denotes special/custom device. A PC prefix indicates a prototype device which has undergone basic testing only. An XC prefix denotes that the device is tested but is not fully characterized or qualified over the full range of normal manufacturing process variations. After full characterization and qualification, devices will be marked with the MC or SC prefix.

Serial Peripheral Interface (SPI)

SE11-SPI

Clearing the SPE bit to disable the SPI can cause an error when transmitting in slave mode. In this situation, a race condition occurs, allowing an invalid mode fault to occur.

Mode faults occur on the SPI when the slave select (\overline{SS}) pin is toggled during a transmission. Mode faults also occur if \overline{SS} is selected and then unselected before SPSCCK returns to its idle level after the shift of the eighth data bit when CPHA = 0 while in slave mode.

When the SPI is disabled, the special port function associated with \overline{SS} is also disabled and returns to a logic 1. In slave mode, \overline{SS} must remain a logic 0 during a transmission. Thus, disabling the SPI causes the \overline{SS} signal to go high internally, which sets up a race for the port logic to send in a logic 1 and the SPI to shut down mode fault detection internally.

Workaround

This condition can be avoided easily in software if mode faults are disabled by clearing the MODFEN bit of the SPSCR register before disabling the SPI in slave mode.

Timer Interface Module (TIM)

SE12-TIMA_AND_TIMB

When the toggle on overflow (TOV) bit is set, writing to a TCHxH register at the point of an overflow inhibits the associated pin from toggling until the TCHxL register is written. The pin then toggles at the next overflow. Even though a toggle can be completely missed, the TOF flag will be set and an interrupt can be generated. The only way to inhibit a toggle on overflow and set the TOF bit is to write to the TMODH register until the TMODL register is written. Similarly, in buffered PWM mode, writing to the inactive registers (TCH0H:L, TCH2H:L, TCH4H:L) at this overflow point produces the same problem. Writing to the odd channels (TCH1H:L, TCH3H:L, TCH5H:L) produces no faults.

Workaround:

Avoid this problem by using the overflow routine instead of writing to inactive channel registers within the output compare routine. Each output compare event occurs as a result of the last channel register written to prior to the last overflow.

Make sure that both odd and even timer channel registers are initialized. Write to the odd channels last, because the active channel register on startup is the even channel. If the inactive channel register is not written to last, then the next

PWM pulse width will be exactly the same as the first, reflecting the value written to the even channel register.

MSCAN Module

SE13-MSCAN

In an ‘almost overrun’ condition, the MSCAN receive buffer can contain an incorrect message. The following sequence will cause the receive buffer to have an incorrect message. The message will be a shifted image of the true message:

1. Both foreground & background receive buffers are filled but have not yet been released by software.
2. The MSCAN begins to transmit message ‘M’
3. Software releases one or both receive buffers by clearing RXF bits
4. The MSCAN loses arbitration on the CAN bus while transmitting ‘M’
5. The next bits seen on the bus after clearing RXF will be interpreted as the beginning of the ID field. This ‘shifted’ ID happens to pass the filter configuration programmed into MSCAN

Workaround

The receive driver software must process the incoming stream of messages fast enough to never have the MSCAN enter the state with both buffers filled (almost overrun). When overrun occurs (OVRIF=1), the MSCAN receive queue must be initialized by asserting/deasserting SFTRES. If the software is designed such that it can cope with maximum CAN throughput, this case will never occur.

Stop I_{DD}

SE14-STOP_IDD

Variable Stop I_{DD} currents in Stop Mode may be seen. This is due to a floating node within the A/D converter module. The effect of this floating node is that the total Stop I_{DD} current exceeds the published value of 150µA for LVI disabled over the temperature range –40°C to +125°C after a number of seconds. Typical values seen are between 150µA and 350µA. However, in the case of the LVI being enabled, the specification of 600µA over the temperature range –40°C to +125°C is not exceeded.

Typical data across full temp range worst case supply voltage for samples from 3 wafer lots:

–40°C to 85°C

Mean Stop I_{DD} 123μA
 STD Dev 107μA
 Mean +3 sigma 553μA
 Max recorded value 559μA
 Specification 600μA

-40°C to 125°C

Mean Stop I_{DD} 268μA
 STD Dev 126μA
 Mean +3 sigma 646μA
 Max recorded value 559μA
 Specification 600μA

SIM (System Integration Module)

SE15-SIM

An illegal address reset is generated when data is accessed in an unimplemented address using indexed addressing mode instructions and PUL/PSH.

This is treated as an internal reset and the RESET pin is driven low for 32 clock cycles.

ROM Security — 1H56A and 0J66D

SE16-ROM

The ROM security feature is not offered on the 68HC08AZ/AB ROM device because the operation of security in monitor mode does not match that of other HC08 family members.

MSCAN Extended ID Rejected if STUFF Bit Between ID16 and ID15

SE17-MSCAN

For 32-bit and 16-bit identifier acceptance modes, an extended ID CAN frame with a stuff bit between ID16 and ID15 can be erroneously rejected, depending on IDAR0, IDAR1, and IDMR1.

Extended IDs (ID28-ID0) which generate a stuff bit between ID16 and ID15:

Table 1.

IDAR0	IDAR1	IDAR2	IDAR3
*****	***1111x	xxxxxxxxx	xxxxxxxxx

where x = 0 or 1 (don't care)
 * = pattern for ID28 to ID18 (see following).

Affected extended IDs (ID28 - ID18) patterns:

- a) xxxxxxxxxx01 exceptions: 0000000001
 01111100001
 xxxx1000001 **except** 11111000001
- b) xxxxxx100000 exception: 01111100000
- c) xxxx01111111 exception: 00000111111
- d) x0111110000
- e) 10000000000
- f) 11111111111
- g) 10000011111

When an affected ID is received, an incorrect value is compared to the 2nd byte of the filter (IDAR1 and IDAR5, plus IDAR3 and IDAR7 in 16-bit mode). This incorrect value is the shift register contents before ID15 is shifted in (i.e. right shifted by 1).

Workaround

If the problematic IDs cannot be avoided, the workaround is to mask certain bits with IDMR1 (and IDMR5, plus IDMR3 and IDMR7 in 16-bit mode).

Example 1: to receive the message IDs

xxxx xxxx x011 111x xxxx xxxx xxxx xxxx

IDMR1 etc. must be 111x xxx1, i.e. ID20,19,18,15 must be masked.

Example 2: to receive the message IDs

xxxx 0111 1111 111x xxxx xxxx xxxx xxxx

IDMR1 etc. must be 1xxx xxx1, i.e. ID20 and ID15 must be masked.

In general, using IDMR1 etc. 1111 xxx1, i.e. masking ID20,19,18,SRR,15, hides the problem.

HOW TO REACH US:**USA/EUROPE/LOCATIONS NOT LISTED:**

Motorola Literature Distribution;
P.O. Box 5405, Denver, Colorado 80217
1-303-675-2140 or 1-800-441-2447

JAPAN:

Motorola Japan Ltd.; SPS, Technical Information Center,
3-20-1, Minami-Azabu Minato-ku, Tokyo 106-8573 Japan
81-3-3440-3569

ASIA/PACIFIC:

Motorola Semiconductors H.K. Ltd.;
Silicon Harbour Centre, 2 Dai King Street,
Tai Po Industrial Estate, Tai Po, N.T., Hong Kong
852-26668334

TECHNICAL INFORMATION CENTER:

1-800-521-6274

HOME PAGE:

<http://www.motorola.com/semiconductors>

Information in this document is provided solely to enable system and software implementers to use Motorola products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits or integrated circuits based on the information in this document.

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part.



Motorola and the Stylized M Logo are registered in the U.S. Patent and Trademark Office. digital dna is a trademark of Motorola, Inc. All other product or service names are the property of their respective owners. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

© Motorola, Inc. 2002