

---

## Mask Set Errata for Mask 0M84P

### Introduction

This report applies to mask 0M84P for these products:

- MC9S08MP16
- MC9S08MP12

### MCU Device Mask Set Identification

The mask set is identified by a 5-character code consisting of a version number, a letter, two numerical digits, and a letter, for example 0J27F. All standard devices are marked with a mask set number and a date code.

### MCU Device Date Codes

Device markings indicate the week of manufacture and the mask set used. The date is coded as four numerical digits where the first two digits indicate the year and the last two digits indicate the work week. For instance, the date code "0301" indicates the first week of the year 2003.

### MCU Device Part Number Prefixes

Some MCU samples and devices are marked with an SC, PC, or XC prefix. An SC prefix denotes special/custom device. A PC prefix indicates a prototype device which has undergone basic testing only. An XC prefix denotes that the device is tested but is not fully characterized or qualified over the full range of normal manufacturing process variations. After full characterization and qualification, devices will be marked with the MC or SC prefix.

### SE164-HSCMP1-OUTPUT-DELAY: HSCMP1 Output Delay

<b>Errata type:</b>	Silicon
<b>Affected component:</b>	PMC
<b>Description:</b>	The output from HSCMP1 will be delayed much longer than the specification allows (up to 4 ms) if both the COP and the internal 1 kHz clock are disabled.

**Workaround:** Enable the COP or the 1 kHz internal clock to enable the current reference that drives the HSCMP1 and eliminates the issue.

## SE161-FTM: FTM Coherency Issues in MP16 Flextimer Module (FTM)

**Errata type:** Silicon

**Affected component:** FTM

**Description:** The coherency mechanism on the timer was compromised due to a clock integration issue on this device.

Flextimer IP was integrated in MP16 in an unusual way to meet an extended input filter performance requirement. A faster clock (core\_clk) was used in place of the originally intended IP design clock, ipg\_clk (half core\_clk frequency). As a consequence, the signals that go in and out of the IP see/generate non-standard timing, and the higher clock makes IP logic to work faster. Although the interface timing was adapted by integration, one unexpected IP internal window allowed a premature contents change in 16-bit data reads, breaking the data coherency mechanism. Below are the 2 different ways when such bug will manifest.

There are two cases discussed in this errata:

- Cases 1 — 16-bit coherency mechanism of direct counter read is not operational.
- Cases 2 — Read of Input Capture 16-bit register when a capture override occurs.

**Workaround:** **Case 1: 16-bit coherency mechanism of direct counter read is not operational.**

### Description

Reading the 16-bit counter will return the free running value instead of the intended 16-bit coherency latch.

A potential issue occurs when there is a transition in the 16-bit while the 2-byte read is in course. In that case, the first byte read will extract data from one 16-bit value and the second byte will extract from the transitioned 16-bit value. This effect is specially seen in High byte transitions.

### Example

0x02FF byte H reads 0x02.

0x0300 byte L reads 0x00 => Result is 0x0200, while coherency would read 0x02FF - delta -0xFF

Reading L first (0xFF) then H next (0x03) would result 0x03FF - again far from 0x02FF - delta +0x100

### Workaround

This workaround assumes that the application allows enough time to read the H byte twice without transitioning the counter H byte. Ideally, the twice reads of H should occur as close as possible to each other - disabling interrupts between reads is recommended. The twice H byte read speed will define the maximum FTM frequency with respect to bus clock.

1. Read H and L bytes.
2. Read H byte again.
3. If H did not change, then HL bytes of Step 1 are correct.
4. If H changed, then read HL bytes again and done.

## Case 2: Read of Input Capture 16-bit register when a capture override occurs.

### Description

Reading the 16-bit Input Capture register will return an incorrect value if a new capture occurs between the first and second bytes read.

### Example

Example of overriding Input Capture events:

Event Input Capture value: 0xAABB .

Read H byte : 0xAA .

New event occurs Input Capture value updated: 0xEEFF. Read L byte: 0xFF > should have read 0xBB => Result 0xA AFF - with correct coherency should be 0xAABB

Same Input Capture events, now reading L first:

Event Input Capture value: 0xAABB .

Read L byte : 0xBB .

New event occurs Input Capture value updated: 0xEEFF. Read H byte: 0xEE > should have read 0xAA => Result 0xEEBB - with correct coherency should be 0xAABB

### Workaround

With the bug, there is no identified procedure that can prevent reading an incorrect second byte from the Input Capture register. However, there is a way to tell if the 16-bit just read is correct or not.

By using the CHnF flag, it is possible to know if a new Input Capture occurred between the first and second bytes read. If flag is set between reads, the 16-bit just read must be discarded. A subsequent register read will return the newly captured value.

1. Clear CHnF flag.
2. Read H or L of Input Capture register.
3. (...) may have unrelated code executed, including interrupts.
4. Read the complementary IC byte.
5. Check CHnF flag.
6. If reset, then HL read from IC reg is correct as it is.
7. If CHnF set, then discard HL and go to Step 1.

## **How to Reach Us:**

**Home Page:** [www.freescale.com](http://www.freescale.com)

**E-mail:** [support@freescale.com](mailto:support@freescale.com)

### **USA/Europe or Locations Not Listed:**

Freescale Semiconductor  
Technical Information Center, CH370  
1300 N. Alma School Road  
Chandler, Arizona 85224  
+1-800-521-6274 or +1-480-768-2130

### **Europe, Middle East, and Africa:**

Freescale Halbleiter Deutschland GmbH  
Technical Information Center  
Schatzbogen 7  
81829 Muenchen, Germany  
+44 1296 380 456 (English)  
+44 8 52200080 (English)  
+44 80 92103 559 (German)  
+33 1 69 35 48 48 (French)  
[support@freescale.com](mailto:support@freescale.com)

### **Japan:**

Freescale Semiconductor Japan Ltd.  
Headquarters  
ARCO Tower 15F  
1-8-1, Shimo-Meguro, Meguro-ku,  
Tokyo 153-0065  
Japan  
0120 191014 or +81 3 5437 9125  
[support.japan@freescale.com](mailto:support.japan@freescale.com)

### **Asia/Pacific:**

Freescale Semiconductor China Ltd.  
Exchange Building 23F  
No. 118 Jianguo Road  
Chaoyang District  
Beijing 100022  
China  
+86 10 5879 8000  
[support.asia@freescale.com](mailto:support.asia@freescale.com)

### **For Literature Requests Only:**

Freescale Semiconductor Literature Distribution Center  
P.O. Box 5405  
Denver, Colorado 80217  
1-800-441-2447 or 303-675-2140  
Fax: 303-675-2140  
[LDCForFreescaleSemiconductor@hibbertgroup.com](mailto:LDCForFreescaleSemiconductor@hibbertgroup.com)

Information in this document is provided solely to enable system and software implementers to use Freescale Semiconductors products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits or integrated circuits based on the information in this document.

Freescale Semiconductor reserves the right to make changes without further notice to any products herein. Freescale Semiconductor makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale Semiconductor assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in Freescale Semiconductor data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals", must be validated for each customer application by customer's technical experts. Freescale Semiconductor does not convey any license under its patent rights nor the rights of others. Freescale Semiconductor products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which failure of the Freescale Semiconductor product could create a situation where personal injury or death may occur. Should Buyer purchase or use Freescale Semiconductor products for any such unintended or unauthorized application, Buyer shall indemnify Freescale Semiconductor and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claims alleges that Freescale Semiconductor was negligent regarding the design or manufacture of the part.

Freescale™ and the Freescale logo are trademarks of Freescale Semiconductor, Inc. All other product or service names are the property of their respective owners.

© Freescale Semiconductor, Inc.2009. All rights reserved.

RoHS-compliant and/or Pb-free versions of Freescale products have the functionality and electrical characteristics as their non-RoHS-complaint and/or non-Pb-free counterparts. For further information, see

<http://www.freescale.com> or contact your Freescale sales representative.

For information on Freescale's Environmental Products program, go to

<http://www.freescale.com/epp>