

# LPC55S1x/LPC551x

Errata sheet LPC55S1x/LPC551x

Rev. 1.3 — February 25, 2021

Errata sheet

## Document information

Info	Content
<b>Keywords</b>	LPC55S16JBD100, LPC55S16JEV98, LPC55S16JBD64, LPC55S14JBD100, LPC55S14JBD64, LPC5516JBD100, LPC5516JEV98, LPC5516JBD64, LPC5514JBD100, LPC5514JBD64, LPC5512JBD100, LPC5512JBD64
<b>Abstract</b>	LPC55S1x/LPC551x errata



**Revision history**

Rev	Date	Description
1.3	20210225	Added USB.4, <a href="#">Section 3.5 “USB.4: In USB high-speed device mode, device writes extra byte(s) to the buffer if the NBytes is not multiple of 8 for OUT transfer”</a> . Corrected Typo, Revision identifier as A for USB.3 in <a href="#">Table 1</a> .
1.2	20201214	Includes <a href="#">Section 3.4 “USB.3: For the USB high-speed device controller, the detection handshaking fails when certain full-speed hubs are connected”</a> .
1.1	20200827	Adds <a href="#">Section 5.1 “CAN-FD peripheral cannot access secure alias address”</a> .
1.0	20191204	Initial version.

**Contact information**

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

## 1. Product identification

The LPC55S1x/LPC551x VFBGA98 package has the following top-side marking:

- First line: LPC55S1x/LPC551x
- Second line: JEV98
- Third line: xxxxxxxx
- Fourth line: zzzyywwxR
  - yyww: Date code with yy = year and ww = week.
  - xR: Device revision A

The LPC55S1x/LPC551x HLQFP100 package has the following top-side marking:

- First line: LPC55S1x/LPC551x
- Second line: xxxxxxxx
- Third line: zzzyywwxR
  - yyww: Date code with yy = year and ww = week.
  - xR: Device revision A

The LPC55S1x/LPC551x HTQFP64 package has the following top-side marking:

- First line: LPC55S1x/LPC551x
- Second line: JBD64
- Third line: xxxx
- Fourth line: xxxx
- Fifth line: zzzyywwxR
  - yyww: Date code with yy = year and ww = week.
  - xR: Device revision A

## 2. Errata overview

**Table 1. Functional problems table**

Functional problems	Short description	Revision identifier	Detailed description
ROM.1	ROM fails to enter ISP mode when image is corrupted with flash pages in an erased or unprogrammed state.	A	<a href="#">Section 3.1</a>
USB.1	USB HS host fails when connecting to an LS device (mouse).	A	<a href="#">Section 3.2</a>
USB.2	Automatic USB rate adjustment not functional when using multiple hubs.	A	<a href="#">Section 3.3</a>
USB.3	For the USB high-speed device controller, the detection handshaking fails when certain full-speed hubs are connected.	A	<a href="#">Section 3.4</a>
USB.4	In USB high-speed device mode, device writes extra byte(s) to the buffer if the NBytes is not multiple of 8 for OUT transfer	A	<a href="#">Section 3.5</a>

Table 2. AC/DC deviations table

AC/DC deviations	Short description	Product version(s)	Detailed description
n/a	n/a	n/a	n/a

Table 3. Errata notes

Errata notes	Short description	Revision identifier	Detailed description
CAN-FD.1	CAN-FD peripheral cannot access memory space with secure alias address.	A	<a href="#">Section 5.1 “CAN-FD peripheral cannot access secure alias address”</a>

## 3. Functional problems detail

---

### 3.1 ROM.1: ROM fails to enter ISP mode when image is corrupted with flash pages in an erased or unprogrammed state

#### Introduction

On the LPC55S1x/LPC551x, if the image is corrupted with flash pages in an erased or unprogrammed state, the ROM may fail to automatically enter ISP mode.

#### Problem

When secure boot is enabled in CMPA, and the flash memory contains an erased or unprogrammed memory page inside the memory region specified by the image size field in the image header, the device does not automatically enter into ISP mode using the fallback mechanism, as in the case of a failed boot for an invalid image. This problem occurs when the application image is only partially written or erased but a valid image header is still present in memory.

#### Work-around

Perform a mass-erase to remove the incomplete and corrupted image using one of the following methods:

- Execute the erase command using Debug Mailbox. The device will enter directly into ISP mode after exiting the mailbox.
- Enter into ISP mode using the Debug Mailbox command and use the flash-erase command.
- Reset the device and enter into ISP mode using the ISP pin. Use the flash-erase command to erase the corrupted (incomplete) image.

### 3.2 USB.1: HS host fails when connecting with the LS device (mouse)

#### Introduction

The USB1 high-speed controller is available on select LPC55S1x/LPC551x devices and provides a plug-and-play connection of peripheral devices to a host with three different data speeds:

- high-speed with a data rate of 480Mbps.
- full-speed with a data rate of 12 Mbps.
- low-speed with a data rate of 1.5 Mbps.

Many portable devices can benefit from the ability to communicate with each other over the USB interface without intervention of a host PC.

#### Problem

USB HS host fails when connecting with an LS device (mouse).

**Work-around**

To support Full-Speed and Low-Speed applications, it is recommended to use the USB0 Full-Speed port and the USB1 High-speed port for Device or Host. In addition, should an application require support of Low-Speed USB devices with a USB High-Speed Host, this can be accomplished by inserting a USB Hub between the USB1 High-speed port and external USB devices.

**3.3 USB. 2: Automatic USB rate adjustment is not functional when using multiple hubs****Introduction:**

Full-speed and low-speed signaling uses bit stuffing throughout the packet without exception. If the receiver sees seven consecutive ones anywhere in the packet, then a bit stuffing error has occurred, and the packet should be ignored.

The time interval just before an End of Packet (EOP) is a special case. The last data bit before the EOP can become stretched by hub switching skews. This is known as dribble and can lead to a situation where dribble introduces a sixth bit that does not require a bit stuff. Therefore, the receiver must accept a packet where there are up to six full bit times at the port with no transitions prior to the EOP.

**Problem:**

The LPC55S1x/LPC551x devices use the start of an EOP for frequency measurements. This is not functional when going through multiple hubs that introduce a dribble bit because of hub switching skews. For this reason, the start of the EOP cannot be used for frequency measurements for automatic USB rate adjustment (by setting USBCLKADJ in the FRO192M\_CTRL register). The problem does not occur when a single hub is used.

**Work-around:**

Use the FRO calibration library provided in technical note TNxxxxx. This library allows the application to have a crystal-less USB device operation in full-speed mode.

**3.4 USB.3: For the USB high-speed device controller, the detection handshaking fails when certain full-speed hubs are connected****Introduction**

See the USB2.0 specification for details regarding the USB High-speed Detection Handshake protocol.

**Problem**

As a high-speed device, when certain full-speed hubs are connected, the USB device does not detect the HOST KJ sequence correctly and, as a result, does not recognize the speed of the connected host. In this case, the USB device can act erratically due to the wrong speed detection.

**Work-around**

There are two workarounds:

1. The software work-around below can be implemented in `usb_dev_hid_mouse` where API is called `"USB_DeviceHsPhyChirpIssueWorkaround()"`. In event handler in `USB_DeviceCallback()`,
  - On `"kUSB_DeviceEventBusReset"` event, `USB_DeviceHsPhyChirpIssueWorkaround()` should be called to identify the speed of the host connected to. If full-speed host is connected or `"isConnectedToFsHostFlag"` is set, `FORCE_FS` (bit 21) of `DEVCMDSTAT` register should be set to force the device operating in full-speed mode.
  - On `"kUSB_DeviceEventDetach"` event, `FORCE_FS` (bit 21) of `DEVCMDSTAT` register should be cleared.
2. The software workaround below is available in tech note (TN00071) In event handler in `USB_DeviceCallback()`,
  - On `"kUSB_DeviceEventAttach"` event, set `PHY_RX` register trip-level voltage to the highest. `USBPHY->RX &= ~(USBPHY_RX_ENVADJ_MASK);USBPHY->RX |= 2;`
  - On `"kUSB_DeviceEventBusReset"` event, check the `DEVCMDSTAT[SPEED]` to determine the connected bus speed. (`SPEED` are bits 22 and 23). If `DEVCMDSTAT[SPEED]=FS`, `FORCE_FS` (bit 21) of `DEVCMDSTAT` should be set to force the device operating in full-speed mode.
  - On `"kUSB_DeviceEventGetDeviceDescriptor"` event, or first `SETUP` packet has arrived, Set the `USBPHY_RX[ENVADJ]` field back to default 0. Otherwise, `USBPHY_RX[ENVADJ]` field will remains as 2 unless a disconnect event occurs.
  - On `"kUSB_DeviceEventDetach"` event, Clear `FORCE_FS` (bit 21) of `DEVCMDSTAT` register to zero. Reset `USBPHY_RX[ENVADJ]` field back to default 0.

### 3.5 USB.4: In USB high-speed device mode, device writes extra byte(s) to the buffer if the NBytes is not multiple of 8 for OUT transfer

#### Introduction

The LPC55S1x/LPC551x device family include a USB high-speed interface (USB1) that can operate in device mode at high-speed. The `NBytes` value represents the number of bytes that can be received in the buffer.

#### Problem

The LPC55S1x/LPC551x USB device controller writes extra bytes to the receive data buffer if the size of the transfer is not a multiple of 8 bytes since the USB device controller always writes 8 bytes. For example, if the transfer length is 1 bytes, 7 extra bytes will be written to the receive data buffer. If the transfer length is 7 bytes, 1 extra bytes will be written to the receive data buffer.

#### Work-around

Reserve an additional, intermediary buffer along with the buffer used by the application for USB data. After the USB data transfer into the intermediary buffer has been completed, use `memcpy` to move the data from the intermediary buffer into the application buffer, skipping the extraneous extra byte. This software work-around is implemented on the SDK software platform.

## 4. AC/DC deviations detail

---

No known errata.

## 5. Errata notes detail

---

### 5.1 CAN-FD peripheral cannot access secure alias address

CAN-FD.1: CAN-FD peripheral cannot access memory space with secure alias address.



## 6. Contents

---

<b>1</b>	<b>Product identification</b>	<b>3</b>
<b>2</b>	<b>Errata overview</b>	<b>3</b>
<b>3</b>	<b>Functional problems detail</b>	<b>5</b>
3.1	ROM.1: ROM fails to enter ISP mode when image is corrupted with flash pages in an erased or unprogrammed state	5
	Introduction	.5
	Problem	.5
	Work-around	.5
3.2	USB.1: HS host fails when connecting with the LS device (mouse)	5
	Introduction	.5
	Problem	.5
	Work-around	.6
3.3	USB. 2: Automatic USB rate adjustment is not functional when using multiple hubs	6
	Introduction:	.6
	Problem:	.6
	Work-around:	.6
3.4	USB.3: For the USB high-speed device controller, the detection handshaking fails when certain full-speed hubs are connected	6
	Introduction	.6
	Problem	.6
	Work-around	.6
3.5	USB.4: In USB high-speed device mode, device writes extra byte(s) to the buffer if the NBytes is not multiple of 8 for OUT transfer	7
	Introduction	.7
	Problem	.7
	Work-around	.7
<b>4</b>	<b>AC/DC deviations detail</b>	<b>8</b>
<b>5</b>	<b>Errata notes detail</b>	<b>8</b>
5.1	CAN-FD peripheral cannot access secure alias address	8
<b>6</b>	<b>Contents</b>	<b>10</b>

## How To Reach Us

### Home Page:

[nxp.com](http://nxp.com)

### Web Support:

[nxp.com/support](http://nxp.com/support)

**Limited warranty and liability** — Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: [nxp.com/SalesTermsandConditions](http://nxp.com/SalesTermsandConditions).

**Right to make changes** - NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Security** — Customer understands that all NXP products may be subject to unidentified or documented vulnerabilities. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately. Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP. NXP has a Product Security Incident Response Team (PSIRT) (reachable at [PSIRT@nxp.com](mailto:PSIRT@nxp.com)) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, COOLFLUX, EMBRACE, GREENCHIP, HITAG, ICODE, JCOP, LIFE, VIBES, MIFARE, MIFARE CLASSIC, MIFARE DESFire, MIFARE PLUS, MIFARE FLEX, MANTIS, MIFARE ULTRALIGHT, MIFARE4MOBILE, MIGLO, NTAG, ROADLINK, SMARTLX, SMARTMX, STARPLUG, TOPFET, TRENCHMOS, UCODE, Freescale, the Freescale logo, Altivec, CodeWarrior, ColdFire, ColdFire+, the Energy Efficient Solutions logo, Kinetis, Layerscape, MagniV, mobileGT, PEG, PowerQUICC, Processor Expert, QorIQ, QorIQ Qonverge, SafeAssure, the SafeAssure logo, StarCore, Symphony, VortiQa, Vybrid, Airfast, BeeKit, BeeStack, CoreNet, Flexis, MXC, Platform in a Package, QUICC Engine, Tower, TurboLink, EdgeScale, EdgeLock, eIQ, and Immersive3D are trademarks of NXP B.V. All other product or service names are the property of their respective owners. AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro,  $\mu$ Vision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved. Oracle and Java are registered trademarks of Oracle and/or its affiliates. The Power Architecture and Power.org word marks and the Power and Power.org logos and related marks are trademarks

*Table continues on the next page...*

and service marks licensed by Power.org. M, M Mobileye and other Mobileye trademarks or logos appearing herein are trademarks of Mobileye Vision Technologies Ltd. in the United States, the EU and/or other jurisdictions.

© NXP B.V. 2020-2021.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

**Date of release:** 25 Feb 2021

**Document identifier:**

LPC55S1x\_LPC551x

The logo for ARM, consisting of the lowercase letters 'arm' in a blue, sans-serif font.