



Mask Set Errata for Mask 3N96B

This document contains a subset of errata for Kinetis Mask Set 3N96B. Errata for security-related modules are not included in this document and are only available after a nondisclosure agreement (NDA) has been signed.

For more information on obtaining an NDA and viewing the comprehensive errata list for this mask set, please contact your local Freescale sales representative.

Mask Set Errata for Mask

Introduction

This report applies to mask for these products:

- KINETIS_3N96B

Errata ID	Errata Title
6378	Cache: Cache write buffer error enable (MCM_ISCR[CWBEE]) does not work
6939	Core: Interrupted loads to SP can cause erroneous behavior
6940	Core: VDIV or VSQRT instructions might not complete correctly when very short ISRs are used
5243	DDRMC: It is possible for data corruption to occur If the value programmed in RDLATADJ is larger than the CAS latency,
5241	DDRMC: Putting the memory into a power down mode while DDR_CR11[AREFMODE] is set can prevent the DDRMC from providing refreshes to the memory while it is powered down.
5263	DDRMC: While the memory is in a power down state, setting DDR_CR11[AREF] in an attempt to force a refresh command will cause a refresh cycle to be missed.
4588	DMAMUX: When using PIT with "always enabled" request, DMA request does not deassert correctly
6358	ENET: Write to Transmit Descriptor Active Register (ENET_TDAR) is ignored
5861	FTM: FTM2 and FTM3 do not correctly enter BDM mode when a debugger connection is active
4710	FTM: FTMx_PWMLOAD register does not support 8-/16-bit accesses
6484	FTM: The process of clearing the FTMx_SC[TOF] bit does not work as expected under a certain condition when the FTM counter reaches FTM_MOD value.
6573	JTAG: JTAG TDO function on the PTA2 disables the pull resistor
3964	JTAGC: When debug is active a wakeup from STOP or VLPS with interrupt causes a hard fault interrupt.
4553	LCDC: Cursor Color Limited in 24bpp Mode
4569	LCDC: Graphic Window Color Key Limited in 24bpp Mode
4570	LCDC: Graphic Window May Shift Pixel Data
4571	LCDC: LCDC can only use half of internal SRAM for frame buffer
3898	MCG: Setting the MCG_C6[PLLS] bit will enable both OSC0 and OSC1.
4590	MCG: Transitioning from VLPS to VLPR low power modes while in BLPI clock mode is not supported.

Table continues on the next page...



Errata ID	Errata Title
4176	NMI: NMI interrupt service routine (ISR) might not be called when MCU wakes up from VLLSx modes.
3794	NVIC: NMI interrupt does not wakeup MCU from STOP and VLPS
5927	Operating requirements: Change to minimum VDD spec
5667	PMC: When used as an input to ADC or CMP modules, the PMC bandgap 1-V voltage reference is not available in VLPx, LLS, or VLLSx modes
5130	SAI: Under certain conditions, the CPU cannot reenter STOP mode via an asynchronous interrupt wakeup event
3981	SDHC: ADMA fails when data length in the last descriptor is less or equal to 4 bytes
3982	SDHC: ADMA transfer error when the block size is not a multiple of four
4624	SDHC: AutoCMD12 and R1b polling problem
3977	SDHC: Does not support Infinite Block Transfer Mode
4627	SDHC: Erroneous CMD CRC error and CMD Index error may occur on sending new CMD during data transfer
3980	SDHC: Glitch is generated on card clock with software reset or clock divider change
6934	SDHC: Issues with card removal/insertion detection
3983	SDHC: Problem when ADMA2 last descriptor is LINK or NOP
3978	SDHC: Software can not clear DMA interrupt status bit after read operation
3984	SDHC: eSDHC misses SDIO interrupt when CINT is disabled
3941	SIM/DDR: SIM_SOPT2[FBSL] does not determine allowable DDR controller accesses when security is enabled
4218	SIM/FLEXBUS: SIM_SCGC7[FLEXBUS] bit should be cleared when the FlexBus is not being used.
5952	SMC: Wakeup via the LLWU from LLS/VLLS to RUN to VLPR incorrectly triggers an immediate wakeup from the next low power mode entry
7166	SOC: SDHC, NFC, USBOTG, and cache modules are not clocked correctly in low-power modes
3926	TSI: The TSI will run several scan cycles during reference clock instead of scanning each electrode once
2638	TSI: The counter registers are not immediately updated after the EOSF bit is set.
4546	TSI: The counter values reported from TSI increase when in low power modes (LLS, VLLS1, VLLS2, VLLS3)
4181	TSI: When the overrun flag is set, the TSI scanning sequence will exhibit undefined behavior.
4935	UART: CEA709.1 features not supported
7027	UART: During ISO-7816 T=0 initial character detection invalid initial characters are stored in the Rx FIFO
7028	UART: During ISO-7816 initial character detection the parity, framing, and noise error flags can set
6472	UART: ETU compensation needed for ISO-7816 wait time (WT) and block wait time (BWT)
4647	UART: Flow control timing issue can result in loss of characters if FIFO is not enabled
4945	UART: ISO-7816 T=1 mode receive data format with a single stop bit is not supported
3892	UART: ISO-7816 automatic initial character detect feature not working correctly
7029	UART: In ISO-7816 T=1 mode, CWT interrupts assert at both character and block boundaries
7090	UART: In ISO-7816 mode, timer interrupts flags do not clear
7031	UART: In single wire receive mode UART will attempt to transmit if data is written to UART_D
5704	UART: TC bit in UARTx_S1 register is set before the last character is sent out in ISO7816 T=0 mode
7091	UART: UART_S1[NF] and UART_S1[PE] can set erroneously while UART_S1[FE] is set
7092	UART: UART_S1[TC] is not cleared by queuing a preamble or break character

Table continues on the next page...

Errata ID	Errata Title
5928	USBOTG: USBx_USBTRC0[USBRESET] bit does not operate as expected in all cases
6933	eDMA: Possible misbehavior of a preempted channel when using continuous link mode

e6378: Cache: Cache write buffer error enable (MCM_ISCR[CWBEE]) does not work

Errata type: Errata

Description: The CM4 cache contains a one entry write buffer. The one entry write buffer is controlled by the write buffer enable bit in the cache control registers. If enabled, it will buffer all writethrough and non-cacheable writes. Also, if enabled, it will break the direct association between a write bus fault and the processor completing the write (i.e.write fault imprecise).

The processor will then not see this fault. It is possible to enable fault reporting and capture fault information on buffered writes that create bus errors. This logic is in the MCM (Miscellaneous Control Module). The CWBEE (Cache Write Buffer Error Enable) bit in the MCM_ISCR (Interrupt Status and Control Register) enables an interrupt to be generated on buffered writes that fault. There are also registers in the MCM to capture fault information (address, attributes, write data) plus a sticky bit to indicate a write buffer fault or multiple write buffer bus faults have occurred. This interrupt will be imprecise and occur sometime after the write fault.

However, due to a logic error, the CWBEE function is not working. On write buffer accesses that fault, the write fault address, attributes and data are correctly captured in the MCM fault information registers but even if CWBEE is set, no interrupt is generated.

Workaround: 1. If a write buffer is enabled and a write access is being run to an address area that may fault, directly check the Cache Write Buffer Fault indicator in the MCM module.

2. Don't enable the cache write buffers, keeping all writethrough and non-cacheable write faults precise.

e6939: Core: Interrupted loads to SP can cause erroneous behavior

Errata type: Errata

Description: ARM Errata 752770: Interrupted loads to SP can cause erroneous behavior

Affects: Cortex-M4, Cortex-M4F

Fault Type: Programmer Category B

Fault Status: Present in: r0p0, r0p1 Open.

Description

If an interrupt occurs during the data-phase of a single word load to the stack-pointer (SP/ R13), erroneous behavior can occur. In all cases, returning from the interrupt will result in the load instruction being executed an additional time. For all instructions performing an update to the base register, the base register will be erroneously updated on each execution, resulting in the stack-pointer being loaded from an incorrect memory location.

The affected instructions that can result in the load transaction being repeated are:

- 1) LDR SP,[Rn],#imm
- 2) LDR SP,[Rn,#imm]!

3) LDR SP,[Rn,#imm]

4) LDR SP,[Rn]

5) LDR SP,[Rn,Rm]

The affected instructions that can result in the stack-pointer being loaded from an incorrect memory address are:

1) LDR SP,[Rn],#imm

2) LDR SP,[Rn,#imm]!

Conditions

1) An LDR is executed, with SP/R13 as the destination

2) The address for the LDR is successfully issued to the memory system

3) An interrupt is taken before the data has been returned and written to the stack-pointer.

Implications

Unless the load is being performed to Device or Strongly-Ordered memory, there should be no implications from the repetition of the load. In the unlikely event that the load is being performed to Device or Strongly-Ordered memory, the repeated read can result in the final stack-pointer value being different than had only a single load been performed.

Interruption of the two write-back forms of the instruction can result in both the base register value and final stack-pointer value being incorrect. This can result in apparent stack corruption and subsequent unintended modification of memory.

Workaround: Both issues may be worked around by replacing the direct load to the stack-pointer, with an intermediate load to a general-purpose register followed by a move to the stack-pointer.

If repeated reads are acceptable, then the base-update issue may be worked around by performing the stack pointer load without the base increment followed by a subsequent ADD or SUB instruction to perform the appropriate update to the base register.

e6940: Core: VDIV or VSQRT instructions might not complete correctly when very short ISRs are used

Errata type: Errata

Description: ARM Errata 709718: VDIV or VSQRT instructions might not complete correctly when very short ISRs are used

Affects: Cortex-M4F

Fault Type: Programmer Category B

Fault Status: Present in: r0p0, r0p1 Open.

On Cortex-M4 with FPU, the VDIV and VSQRT instructions take 14 cycles to execute. When an interrupt is taken a VDIV or VSQRT instruction is not terminated, and completes its execution while the interrupt stacking occurs. If lazy context save of floating point state is enabled then the automatic stacking of the floating point context does not occur until a floating point instruction is executed inside the interrupt service routine.

Lazy context save is enabled by default. When it is enabled, the minimum time for the first instruction in the interrupt service routine to start executing is 12 cycles. In certain timing conditions, and if there is only one or two instructions inside the interrupt service routine, then the VDIV or VSQRT instruction might not write its result to the register bank or to the FPSCR.

Workaround: A workaround is only required if the floating point unit is present and enabled. A workaround is not required if the memory system inserts one or more wait states to every stack transaction.

There are two workarounds:

- 1) Disable lazy context save of floating point state by clearing LSPEN to 0 (bit 30 of the FPCCR at address 0xE000EF34).
- 2) Ensure that every interrupt service routine contains more than 2 instructions in addition to the exception return instruction.

e5243: DDRMC: It is possible for data corruption to occur if the value programmed in RDLATADJ is larger than the CAS latency,

Errata type: Errata

Description: If DDR_CR56[RDLATADJ] is programmed to be larger than the CAS latency of the device there is the possibility that data corruption may occur because the controller will pre-maturely issue DFI update requests.

Workaround: Do not set DDR_CR56[RDLATADJ] to a value larger than the CAS latency of the device. If a larger delay is required, set the RDLATADJ equal to the CAS latency of the device and use the DDR_CR52[RDDTENBAS] parameter to add any additional delay that is required.

e5241: DDRMC: Putting the memory into a power down mode while DDR_CR11[AREFMODE] is set can prevent the DDRMC from providing refreshes to the memory while it is powered down.

Errata type: Errata

Description: The DDR_CR11[AREFMODE] parameter is used to determine when a refresh command is issued to the memory. The refresh command can either be issued at the next memory command boundary, or it can be held off and issued only at the next system command boundary. One system command may result in many memory commands, depending on how much data the system command is moving.

When the AREFMODE parameter is set, if a refresh is needed the controller will hold off this refresh until the next system command boundary. If the memory is manually placed into power down, and this happens at a memory command boundary but not at a system command boundary the logic holding off the refresh will erroneously continue to hold off the refresh for the duration of time the memory is placed in power down.

If the memory does not receive refreshes while in power down it is possible for the contents of the memory to degrade and become corrupted.

This condition can only occur if the low-power mode entry is done manually. This is not an issue if you are using the LPAUTO parameter to automatically enter low-power modes.

Workaround: Always clear the DDR_CR11[AREFMODE] bit before manually entering a power-down mode. If you wish to have normal operations with the AREFMODE bit set, you can do so, but ensure that you clear it before you manually place the memory into power down. After you bring the memory out of power down you can then set the AREFMODE bit again.

e5263: DDRMC: While the memory is in a power down state, setting DDR_CR11[AREF] in an attempt to force a refresh command will cause a refresh cycle to be missed.

Errata type: Errata

Description: When the DDRMC has the auto refresh mode enabled (DDR_CR11[TREFEN] = 1), it will load a counter with the value in the TREF parameter, count to zero, then issue a refresh to the memory, reload the counter and repeat this cycle. There are several events which use the count value of zero from this counter to function. If a refresh is requested via a write to the AREF parameter, the counter associated with the automatic issuance of refreshes by the DDRMC will automatically be reloaded with the value in the TREF parameter and will not be able to achieve a count of zero.

One of the key pieces of logic which monitors the refresh counter equaling zero is logic associated with bringing the memory out of a power down state to enable the controller to issue a refresh command to the memory. So if the memory is in a power down state and a refresh is requested via a method other than the automatic refresh counter reaching zero the memory will not be able to be brought out of the power down state to allow the refresh to occur. This will result in extra delay before the refresh can be issued to the memory, or will result in the memory never being refreshed while in a power down state if the automatic refresh counter is disabled.

Example

Assume the memory is in a power down state and the automatic refresh mode of the DDRMC is enabled. The counter will be loaded with the value in the TREF parameter and will begin counting down. If, when the counter reaches a value near zero (but not zero), software write to AREF paramter, the counter will be automatically reloaded with the value in the TREF parameter and will then have to count down to 0 before the controller will bring the memory out of the power down state and issue the refresh. In this case the memory will fail to receive one refresh.

Workaround: Do not use the DDR_CR11[AREF] bit to attempt a refresh command to the memory while the memory is in power down mode. Always enable the automatic refresh feature of the DDRMC (set DDR_CR11[TREFEN]) and rely on it to provide refreshes to the memory.

e4588: DMAMUX: When using PIT with "always enabled" request, DMA request does not deassert correctly

Errata type: Errata

Description: The PIT module is not assigned as a stand-alone DMA request source in the DMA request mux. Instead, the PIT is used as the trigger for the DMAMUX periodic trigger mode. If you want to use one of the PIT channels for periodic DMA requests, you would use the periodic trigger mode in conjunction with one of the "always enabled" DMA requests. However, the DMA request does not assert correctly in this case.

Instead of sending a single DMA request every time the PIT expires, the first time the PIT triggers a DMA transfer the "always enabled" source will not negate its request. This results in the DMA request remaining asserted continuously after the first trigger.

Workaround: Use of the PIT to trigger DMA channels where the major loop count is greater than one is not recommended. For periodic triggering of DMA requests with major loop counts greater than one, we recommended using another timer module instead of the PIT.

If using the PIT to trigger a DMA channel where the major loop count is set to one, then in order to get the desired periodic triggering, the DMA must do the following in the interrupt service routine for the DMA_DONE interrupt:

1. Set the DMA_TCDn_CSR[DREQ] bit and configure DMAMUX_CHCFGn[ENBL] = 0
2. Then again DMAMUX_CHCFGn[ENBL] = 1, DMASREQ=channel in your DMA DONE interrupt service routine so that "always enabled" source could negate its request then DMA request could be negated.

This will allow the desired periodic triggering to function as expected.

e6358: ENET: Write to Transmit Descriptor Active Register (ENET_TDAR) is ignored

Errata type: Errata

Description: If the ready bit in the transmit buffer descriptor (TxBD[R]) is previously detected as not set during a prior frame transmission, then the ENET_TDAR[TDAR] bit is cleared at a later time, even if additional TxBDs were added to the ring and the ENET_TDAR[TDAR] bit is set. This results in frames not being transmitted until there is a 0-to-1 transition on ENET_TDAR[TDAR].

Workaround: Code can use the transmit frame interrupt flag (ENET_EIR[TXF]) as a method to detect whether the ENET has completed transmission and the ENET_TDAR[TDAR] has been cleared. If ENET_TDAR[TDAR] is detected as cleared when packets are queued and waiting for transmit, then a write to the TDAR bit will restart TxBD processing.

e5861: FTM: FTM2 and FTM3 do not correctly enter BDM mode when a debugger connection is active

Errata type: Errata

Description: The FTM modules include an FTMxCONF[BDMODE] field that can be configured to control the operation of the FTM when debugging. There is a connection error in the FTM2 and FTM3 integration that prevents those modules from detecting when debug is active. As a result these two modules will operate in normal functional mode even while debugging.

Workaround: The FTMs behave as expected during normal operation (no debugger present). The issue only impacts the ability to control the operation and stop the timers while debugging.

e4710: FTM: FTMx_PWMLOAD register does not support 8-/16-bit accesses

Errata type: Errata

Description: The FTM PWM Load register should support 8-bit and 16-bit accesses. However, the FTMx_PWMLOAD[LDOK] bit is cleared automatically by FTM with these sized accesses, thus disabling the loading of the FTMx_MOD, FTMx_CNTIN, and FTMx_CnV registers.

Workaround: Always use a 32-bit write access to modify contents of the FTMx_PWMLOAD register.

e6484: FTM: The process of clearing the FTMx_SC[TOF] bit does not work as expected under a certain condition when the FTM counter reaches FTM_MOD value.

Errata type: Errata

Description: The process of clearing the TOF bit does not work as expected when `FTMx_CONF[NUMTOF] != 0` and the current TOF count is less than `FTMx_CONF[NUMTOF]`, if the FTM counter reaches the `FTM_MOD` value between the reading of the TOF bit and the writing of 0 to the TOF bit. If the above condition is met, the TOF bit remains set, and if the TOF interrupt is enabled (`FTMx_SC[TOIE] = 1`), the TOF interrupt also remains asserted.

Workaround: Two possible workarounds exist for this erratum and the decision on which one to use is based on the requirements of your particular application.

1) Repeat the clearing sequence mechanism until the TOF bit is cleared.

Below is a pseudo-code snippet that would need to be included in the TOF interrupt routine.

```
while (FTM_SC[TOF]!=0)
{
void FTM_SC() ; // Read SC register
FTM_SC[TOF]=0 ; // Write 0 to TOF bit
}
```

2) With `FTMx_CONF[TOFNUM] = 0` and a variable in the software, count the number of times that the TOF bit is set. In the TOF interrupt routine, clear the TOF bit and increment the variable that counts the number of times that the TOF bit was set.

e6573: JTAG: JTAG TDO function on the PTA2 disables the pull resistor

Errata type: Errata

Description: The JTAG TDO function on the PTA2 pin disables the pull resistor, but keeps the input buffer enabled. Because the JTAG will tri-state this pin during JTAG reset (or other conditions), this pin will float with the input buffer enabled. If the pin is unconnected in the circuit, there can be increased power consumption in low power modes for some devices.

Workaround: Disable JTAG TDO functionality when the JTAG interface is not needed and left floating in a circuit. Modify the `PORTA_PCR2` mux before entering low power modes. Set the mux to a pin function other than ALT7. If set up as a digital input and left unconnected in the circuit, then a pull-up or pull-down should be enabled. Alternatively, an external pull device or external source can be added to the pin.

Note: Enabling the pull resistor on the JTAG TDO function violates the JTAG specification.

e3964: JTAGC: When debug is active a wakeup from STOP or VLPS with interrupt causes a hard fault interrupt.

Errata type: Errata

Description: When exiting STOP or VLPS back into RUN mode with an interrupt a hard fault interrupt is caused when the JTAG debugger is enabled.

The MCU enters a pseudo STOP mode when the debugger is enabled.

The user cannot use the debugger to test code that wakes up from STOP with an interrupt.

Workaround: a. Disable the debugger with a Power off and on cycle before testing code that exits STOP or VLPS with an interrupt.

or

b. From the debugger, while in STOP or VLPS, halt the MCU with the debugger tools before triggering an interrupt.

e4553: LCDC: Cursor Color Limited in 24bpp Mode

Errata type: Errata

Description: The LCCMR register which determines the cursor color has a maximum of 6 bits per color (18bpp). Thus when trying to use the cursor in 24bpp mode, the first two bits of each 8-bit cursor color sent to the LCD are zero.

Workaround: The least significant 6 bits of each color can be used for the cursor color in 24bpp mode.

e4569: LCDC: Graphic Window Color Key Limited in 24bpp Mode

Errata type: Errata

Description: The GWCKR, GWCKG, and GWCKB fields in the LGWCR register determine which color in the graphic window is transparent. These fields are each 6 bits in length (18bpp). This limits the colors that can be used for the color key in 24bpp mode.

Workaround: In 24bpp mode, the color that is being keyed out must have the first two bits be zero for the comparison to work. The lower 6 bits will be compared as usual.

e4570: LCDC: Graphic Window May Shift Pixel Data

Errata type: Errata

Description: When a graphic window is located at location (0,0) or (1,0), the data output to the LCD in the graphic window will be shifted over by one pixel.

This means that the first piece of pixel data in your frame buffer will be the second pixel sent out instead of the first pixel as expected. Then the second piece of data will be the third pixel sent out, and so on. This continues throughout the buffer, so that the first pixel of the graphic window display will come from the very end of the frame buffer data instead of from the very front.

The end result is a pixel-wide line of data that should be on the far right of the graphic window is instead displayed on the far left of the graphic window. The data displayed in the graphic window is also one pixel further to the right than it should be.

Workaround: Ensure your graphic window is not located at either (0,0) or (1,0) or account for this shift in the data being used for the graphic window.

e4571: LCDC: LCDC can only use half of internal SRAM for frame buffer

Errata type: Errata

Description: The LCDC background plane or graphic window requires that its frame buffer be within a 4MB boundary, as address A[31:22] has a fixed value for a picture's image. As the LCDC tries to read data from the internal SRAM, it will loop back to the start of that 4MB boundary, and into invalid memory space, upon reaching address 0x2000_0000.

Thus only half of the available SRAM is available for a frame buffer instead of the entire SRAM.

Workaround: Use the background plane to display data located in the first half of the SRAM, and place the image in RAM so that it will be at the end of a line when it reaches location 0x1FFF_FFFF.

Then use the graphic window to display the data from the other half of SRAM starting at 0x2000_0000, taking care to place the graphic window so as to line up seamlessly with the end of the background plane.

e3898: MCG: Setting the MCG_C6[PLLS] bit will enable both OSC0 and OSC1.

Errata type: Errata

Description: When the PLL is enabled by means of setting the MCG_C6[PLLS] bit, both OSC0 and OSC1 will be enabled. This will only occur when moving the MCG to PBE, BLPE or PEE modes.

Workaround: If an oscillator is not being used and PBE, BLPE or PEE modes are to be used, ensure that the EREFS bit associated with the unused oscillator is cleared. The IO pins associated with that oscillator should also be configured as GPIO outputs driving a logic 0. This will place the IO pads in a consistent state and keep excess current consumption to a minimum level.

e4590: MCG: Transitioning from VLPS to VLPR low power modes while in BLPI clock mode is not supported.

Errata type: Errata

Description: Transitioning from VLPS mode back to VLPR (LPWUI control bit = 0) while using BLPI clock mode only, is not supported. During Fast IRC startup, the output clock frequency may exceed the maximum VLPR operating frequency. This does not apply to the BLPE clock mode.

Workaround: There are two options for workarounds

a) Exit to Run instead of VLPR. Before entering VLPR set the LPWUI bit so that when exiting VLPS mode the MCU exits to RUN mode instead of VLPR mode. With LPWUI set any interrupt will exit VLPR or VLPS back into RUN mode. To minimize the impact of the higher RUN current re-enter VLPR quickly.

or

b) Utilize MCG clock mode BLPE when transitioning from VLPS to VLPR modes.

e4176: NMI: NMI interrupt service routine (ISR) might not be called when MCU wakes up from VLLSx modes.

Errata type: Errata

Description: When MCU wakes up from VLLSx modes via NMI pin the NMI ISR might not be called if the NMI pulse width is lower than 120us..

Workaround: NMI pulse width must be asserted for at least 120usec to ensure NMI ISR is called and entered. Note that a short NMI pulse will still wakeup the part, and the LLWU ISR will still be entered.

e3794: NVIC: NMI interrupt does not wakeup MCU from STOP and VLPS

Errata type: Errata

Description: NMI interrupt does not wakeup MCU from STOP and VLPS when the bits CSYSPWRUPREQ and CDBGPWRUPREQ in the Control/Status Register of the DAP Port are cleared.

Workaround: If a debugger connection is established, the CSYSPWRUPREQ and CDBGPWRUPREQ bits are set by default, so an NMI interrupt will wake up the MCU from STOP and VLPS modes. In the absence of a debug connection and after a POR event, the bits will be cleared and thus an NMI interrupt will not wake the MCU.

e5927: Operating requirements: Change to minimum VDD spec

Errata type: Errata

Description: The minimum operating voltage for VDD is 2.0V.

Workaround: Ensure that VDD is 2.0V or higher. Keep in mind that if VDD_DDR is used, that VDD must also be higher than VDD_DDR as per the original specification.

e5667: PMC: When used as an input to ADC or CMP modules, the PMC bandgap 1-V voltage reference is not available in VLPx, LLS, or VLLSx modes

Errata type: Errata

Description: The Power Management Controller (PMC) bandgap 1-V reference is not available as an input to the Analog-to-Digital Converter (ADC) module (using ADC input channel AD27) or the Comparator (CMP) module (using CMP input IN6) in Very Low Power Run (VLPR), Very Low Power Wait (VLPW), Very Low Power Stop (VLPS), Low Leakage Stop (LLS), Very Low Leakage Stop3 (VLLS3), Very Low Leakage Stop2 (VLLS2), Very Low Leakage Stop1 (VLLS1), or Very Low Leakage Stop0 (VLLS0) modes.

This erratum does not apply to the VREF module 1.2 V reference voltage.

Workaround: Use of the PMC bandgap 1-V reference voltage as an input to the ADC and CMP modules requires the MCU to be in Run, Wait, or Stop modes.

e5130: SAI: Under certain conditions, the CPU cannot reenter STOP mode via an asynchronous interrupt wakeup event

Errata type: Errata

Description: If the SAI generates an asynchronous interrupt to wake the core and it attempts to reenter STOP mode, then under certain conditions the STOP mode entry is blocked and the asynchronous interrupt will remain set.

This issue applies to interrupt wakeups due to the FIFO request flags or FIFO warning flags and then only if the time between the STOP mode exit and subsequent STOP mode reentry is less than 3 asynchronous bit clock cycles.

Workaround: Ensure that at least 3 bit clock cycles elapse following an asynchronous interrupt wakeup event, before STOP mode is reentered.

e3981: SDHC: ADMA fails when data length in the last descriptor is less or equal to 4 bytes

Errata type: Errata

Description: A possible data corruption or incorrect bus transactions on the internal AHB bus, causing possible system corruption or a stall, can occur under the combination of the following conditions:

1. ADMA2 or ADMA1 type descriptor
2. TRANS descriptor with END flag
3. Data length is less than or equal to 4 bytes (the length field of the corresponding descriptor is set to 1, 2, 3, or 4) and the ADMA transfers one 32-bit word on the bus
4. Block Count Enable mode

Workaround: The software should avoid setting ADMA type last descriptor (TRANS descriptor with END flag) to data length less than or equal to 4 bytes. In ADMA1 mode, if needed, a last NOP descriptor can be appended to the descriptors list. In ADMA2 mode this workaround is not feasible due to ERR003983.

e3982: SDHC: ADMA transfer error when the block size is not a multiple of four

Errata type: Errata

Description: Issue in eSDHC ADMA mode operation. The eSDHC read transfer is not completed when block size is not a multiple of 4 in transfer mode ADMA1 or ADMA2. The eSDHC DMA controller is stuck waiting for the IRQSTAT[TC] bit in the interrupt status register.

The following examples trigger this issue:

1. Working with an SD card while setting ADMA1 mode in the eSDHC
2. Performing partial block read
3. Writing one block of length 0x200
4. Reading two blocks of length 0x22 each. Reading from the address where the write operation is performed. Start address is 0x512 aligned. Watermark is set as one word during read. This read is performed using only one ADMA1 descriptor in which the total size of the transfer is programmed as 0x44 (2 blocks of 0x22).

Workaround: When the ADMA1 or ADMA2 mode is used and the block size is not a multiple of 4, the block size should be rounded to the next multiple of 4 bytes via software. In case of write, the software should add the corresponding number of bytes at each block end, before the write is initialized. In case of read, the software should remove the dummy bytes after the read is completed.

For example, if the original block length is 22 bytes, and there are several blocks to transfer, the software should set the block size to 24. The following data is written/stored in the external memory:

- 4 Bytes valid data

4 Bytes valid data
2 Bytes valid data + 2 Byte dummy data
4 Bytes valid data
2 Bytes valid data + 2 Byte dummy data

In this example, 48 (24 x 2) bytes are transferred instead of 44 bytes. The software should remove the dummy data.

e4624: SDHC: AutoCMD12 and R1b polling problem

Errata type: Errata

Description: Occurs when a pending command which issues busy is completed. For a command with R1b response, the proper software sequence is to poll the DLA for R1b commands to determine busy state completion. The DLA polling is not working properly for the ESDHC module and thus the DLA bit in PRSSTAT register cannot be polled to wait for busy state completion. This is relevant for all eSDHC ports (eSDHC1-4 ports).

Workaround: Poll bit 24 in PRSSTAT register (DLSL[0] bit) to check that wait busy state is over.

e3977: SDHC: Does not support Infinite Block Transfer Mode

Errata type: Errata

Description: The eSDHC does not support infinite data transfers, if the Block Count register is set to one, even when block count enable is not set.

Workaround: The following software workaround can be used instead of the infinite block mode:

1. Set BCEN bit to one and enable block count
2. Set the BLKCNT to the maximum value in Block Attributes Register (BLKATTR) (0xFFFF for 65535 blocks)

e4627: SDHC: Erroneous CMD CRC error and CMD Index error may occur on sending new CMD during data transfer

Errata type: Errata

Description: When sending new, non data CMD during data transfer between the eSDHC and EMMC card, the module may return an erroneous CMD CRC error and CMD Index error. This occurs when the CMD response has arrived at the moment the FIFO clock is stopped. The following bits after the start bit of the response are wrongly interpreted as index, generating the CRC and Index errors.

The data transfer itself is not impacted.

The rate of occurrence of the issue is very small, as there is a need for the following combination of conditions to occur at the same cycle:

- The FIFO clock is stopped due to FIFO full or FIFO empty
- The CMD response start bit is received

Workaround: The recommendation is to not set FIFO watermark level to a too small value in order to reduce frequency of clock pauses.

The problem is identified by receiving the CMD CRC error and CMD Index error. Once this issue occurs, one can send the same CMD again until operation is successful.

e3980: SDHC: Glitch is generated on card clock with software reset or clock divider change

Errata type: Errata

Description: A glitch may occur on the SDHC card clock when the software sets the RSTA bit (software reset) in the system control register. It can also be generated by setting the clock divider value. The glitch produced can cause the external card to switch to an unknown state. The occurrence is not deterministic.

Workaround: A simple workaround is to disable the SD card clock before the software reset, and enable it when the module resumes the normal operation. The Host and the SD card are in a master-slave relationship. The Host provides clock and control transfer across the interface. Therefore, any existing operation is discarded when the Host controller is reset.

The recommended flow is as follows:

1. Software disable bit[3], SDCLKEN, of the System Control Register
2. Trigger software reset and/or set clock divider
3. Check bit[3], SDSTB, of the Present State Register for stable clock
4. Enable bit[3], SDCLKEN, of the System Control Register.

Using the above method, the eSDHC cannot send command or transfer data when there is a glitch in the clock line, and the glitch does not cause any issue.

e6934: SDHC: Issues with card removal/insertion detection

Errata type: Errata

Description: SD cards include a 50K pullup that is used to detect when a card is inserted. A weak (500K) pulldown on the line is sufficient to allow for the first card insertion to be detected (the 50K pullup on the card will dominate the pulldown and cause the signal to go high).

The 5 V tolerant I/O cells used on this processor require a pulldown resistor stronger than 50K to ensure that a signal will reach a proper low voltage level after the pin has been high. A stronger pulldown cannot be used on the SD card detect signal because it would prevent the card detection from working correctly. Because of this, the automatic card removal detection will not work reliably.

Workaround: A software workaround can be used to check for card removal or verify that a card is still present by redetecting it.

1. Temporarily change the appropriate PORTx_PCRn to configure the SD card detect pin as a GPIO.
2. Configure the GPIO as an output driving low.

3. Leave the pin in this state for several us. The exact amount of time required can vary depending on pin loading.

4. Change the PORTx_PCRn to switch the pin back to its SDHC function.

When this sequence is complete the SDHC will be ready to detect card insertion again. The sequence above should be run periodically or if an unexpected response is received from the SD card. The procedure will discharge the I/O cell so that the card detect pin is low and an SD card (if present) can be detected.

e3983: SDHC: Problem when ADMA2 last descriptor is LINK or NOP

Errata type: Errata

Description: ADMA2 mode in the eSDHC is used for transfers to/from the SD card. There are three types of ADMA2 descriptors: TRANS, LINK or NOP. The eSDHC has a problem when the last descriptor (which has the End bit '1') is a LINK descriptor or a NOP descriptor.

In this case, the eSDHC completes the transfers associated with this descriptor set, whereas it does not even start the transfers associated with the new data command. For example, if a WRITE transfer operation is performed on the card using ADMA2, and the last descriptor of the WRITE descriptor set is a LINK descriptor, then the WRITE is successfully finished. Now, if a READ transfer is programmed from the SD card using ADMA2, then this transfer does not go through.

Workaround: Software workaround is to always program TRANS descriptor as the last descriptor.

e3978: SDHC: Software can not clear DMA interrupt status bit after read operation

Errata type: Errata

Description: After DMA read operation, if the SDHC System Clock is automatically gated off, the DINT status can not be cleared by software.

Workaround: Set HCKEN bit before starting DMA read operation, to disable SDHC System Clock auto-gating feature; after the DINT and TC bit received when read operation is done, clear HCKEN bit to re-enable the SDHC System Clock auto-gating feature.

e3984: SDHC: eSDHC misses SDIO interrupt when CINT is disabled

Errata type: Errata

Description: An issue is identified when interfacing the SDIO card. There is a case where an SDIO interrupt from the card is not recognized by the hardware, resulting in a hang.

If the SDIO card lowers the DAT1 line (which indicates an interrupt) when the SDIO interrupt is disabled in the eSDHC registers (that is, CINTEN bits in IRQSTATEN and IRQSIGEN are set to zero), then, after the SDIO interrupt is enabled (by setting the CINTEN bits in IRQSTATEN and IRQSIGEN registers), the eSDHC does not sense that the DAT1 line is low. Therefore, it fails to set the CINT interrupt in IRQSTAT even if DAT1 is low.

Generally, CINTEN bit is disabled in interrupt service.

The SDIO interrupt service steps are as follows:

1. Clear CINTEN bit in IRQSTATEN and IRQSIGEN.

2. Reset the interrupt factors in the SDIO card and write 1 to clear the CINT interrupt in IRQSTAT.

3. Re-enable CINTEN bit in IRQSTATEN and IRQSIGEN.

If a new SDIO interrupt from the card occurs between step 2 and step 3, the eSDHC skips it.

Workaround: The workaround interrupt service steps are as follows:

1. Clear CINTEN bit in IRQSTATEN and IRQSIGEN.

2. Reset the interrupt factors in the SDIO card and write 1 to clear CINT interrupt in IRQSTAT.

3. Clear and then set D3CD bit in the PROCTL register. Clearing D3CD bit sets the reverse signal of DAT1 to low, even if DAT1 is low. After D3CD bit is re-enabled, the eSDHC can catch the posedge of the reversed DAT1 signal, if the DAT1 line is still low.

4. Re-enable CINTEN bit in IRQSTATEN and IRQSIGEN.

e3941: SIM/DDR: SIM_SOPT2[FBSL] does not determine allowable DDR controller accesses when security is enabled

Errata type: Errata

Description: On devices that include a DDR controller, the SIM_SOPT2[FBSL] field should determine what FlexBus and DDR accesses are allowed when the device is secure, but currently the FBSL field only controls the allowable FlexBus accesses.

Workaround: Until the feature is corrected customers should be aware that DDR could be used to execute code even when the device is secure. Some applications might want to avoid using DDR when secure and/or use the MPU to restrict the DDR to supervisor access only.

e4218: SIM/FLEXBUS: SIM_SCGC7[FLEXBUS] bit should be cleared when the FlexBus is not being used.

Errata type: Errata

Description: The SIM_SCGC7[FLEXBUS] bit is set by default. This means that the FlexBus will be enabled and come up in global chip select mode.

With some code sequence and register value combinations the core could attempt to prefetch from the FlexBus even though it might not actually use the value it prefetched. In the case where the FlexBus is unconfigured, this can result in a hung bus cycle on the FlexBus.

Workaround: If the FlexBus is not being used, disabled the clock to the FlexBus during chip initialization by clearing the SIM_SCGC7[FLEXBUS] bit.

If the FlexBus will be used, then enable at least one chip select as early in the chip initialization process as possible.

e5952: SMC: Wakeup via the LLWU from LLS/VLLS to RUN to VLPR incorrectly triggers an immediate wakeup from the next low power mode entry

Errata type: Errata

Description: Entering VLPR immediately after an LLWU wakeup event from LLS/VLLS, will cause any subsequent entry into LLS/VLLS to fail if entry into VLPR mode occurs before clearing the pending LLWU interrupt.

Workaround: After an LLWU wakeup event from LLS/VLLS, the user must clear the LLWU interrupt prior to entering VLPR mode.

e7166: SOC: SDHC, NFC, USBOTG, and cache modules are not clocked correctly in low-power modes

Errata type: Errata

Description: The SDHC, NFC, and USBOTG are connected to a single master port on the crossbar switch through a multiplexer. The modules themselves are still clocked in Wait mode, but the multiplexer connecting them to the crossbar switch has its clock shut off immediately during entry into low-power modes. This prevents these three modules from completing bus transactions during any low-power mode entry or starting new bus transactions when the system enters Wait mode (even though the modules themselves remain clocked in Wait).

In addition the cache tag and data RAMs have their clock gated off in Wait mode. This can lead to corruption of cache contents during low-power entry.

Workaround: To resolve the low-power mode entry issue with the SDHC, NFC, and USBOTG, software should ensure that all bus master operations for these three modules are complete before requesting the system entry into any of the low-power modes. In addition, no bus traffic from these modules should be generated while the system is in Wait.

To avoid cache corruption during low-power mode entry, the following code sequence should be used for entry into low-power modes when the cache is enabled:

```
/* The LMEM writes below will perform NOP operations on both of the caches */
LMEM_PCCLCR = 0x09000001;
LMEM_PSCLCR = 0x09000001;
/* Wait for cache command to complete */
While (LMEM_PCCLCR & 1);
/* Wait for cache command to complete */
While (LMEM_PSCLCR & 1);
Asm("DSB");
Asm("WFI");
Asm("NOP");
Asm("NOP");
Asm("NOP");
Asm("NOP");
Asm("NOP");
Asm("NOP");
Asm("NOP");
Asm("NOP");
Asm("NOP");
```

The code sequence above must be executed from a memory location that is not cached (SRAM_L is recommended). In addition, the start of the code sequence through the WFI must execute uninterrupted. If an interrupt occurs between the start of the sequence and the WFI instruction, then the code sequence must be restarted from the beginning. The NOPs in the sequence can be replaced with other code if desired, as long as that code doesn't make reference to any cached addresses.

e3926: TSI: The TSI will run several scan cycles during reference clock instead of scanning each electrode once

Errata type: Errata

Description: The TSI will run several scan cycles during reference clock instead of scanning each electrode once. For each automatic scanning period determined by AMCLKS (clock source), AMPSC (prescaler) and SMOD (period modulo), TSI will scan during one reference clock cycle divided by the AMPSC prescaler.

This does not affect the count result from TSI because TSI counters keep the last scan result.

Workaround: 1. Because counter results are not affected, a simple workaround is to use the smallest prescaler possible and use a bigger SMOD value, this will minimize the number of extra scans, thus also minimizing the amount of average extra current used by the module.

2. If strict control of number of scan cycles is needed, trigger scans with software control (using the SWTS bit) and control time between scans with a separate timer. This solution is only recommended if strict control of scan cycles is needed, if not, recommendation is to use workaround 1.

e2638: TSI: The counter registers are not immediately updated after the EOSF bit is set.

Errata type: Errata

Description: The counter registers are not immediately updated after the end of scan event (EOSF is set). The counter registers will become available 0.25 ms after the EOSF flag is set. This also applies for the end-of-scan interrupt, as it is triggered with the EOSF flag. This behavior will occur both in continuous scan and in software triggered scan modes.

Workaround: Insert a delay of 0.25 ms or greater prior to accessing the counter registers after an end of scan event or an end of scan interrupt that is triggered by the EOSF flag. This delay does not need to be a blocking delay, so it can be executing other actions before reading the counter registers. Notice that the out-of-range flag (OUTRGF) and interrupt occur after the counters have been updated, so if the OUTRGF flag is polled or the out-of-range interrupt is used, the workaround is not necessary.

e4546: TSI: The counter values reported from TSI increase when in low power modes (LLS, VLLS1, VLLS2, VLLS3)

Errata type: Errata

Description: When the MCU goes into LLS or VLLSx modes, with the TSI enabled for wakeup, the counter value reported by the TSI increases with respect to what was reported in active mode. Because the wakeup threshold is calculated in active mode, it is highly likely that MCU will wakeup immediately after going to low power.

Workaround: 1. Use Wait, Stop, or VLPS. These modes do not require any wakeup threshold calibration as TSI remains in active mode and wakes up each end of scan so that normal baseline tracking algorithm can be used.

2. To use LLS or VLLSx modes with the TSI as a wakeup source, calibrate the wakeup threshold using the desired low power mode. During application initialization, configure the TSI to exit low power via the LLWUI (low-leakage wake-up interrupt) with an End of Scan using the desired wakeup electrode. For example enter LLS mode with automatic scanning enabled so that after the first scan the TSI module causes an exit from low power at the end of scan. After the wakeup event, read the TSIX_WUCNTR Register, this register will have the value for the count during low power mode. Use this value to calculate THRS_HLD register value.

e4181: TSI: When the overrun flag is set, the TSI scanning sequence will exhibit undefined behavior.

Errata type: Errata

Description: When the overrun flag is set, the TSI scanning sequence will exhibit undefined behavior, so the results of measurements are invalid at this point. In order to continue reading valid measurements, disable the TSI module and reconfigure it.

Workaround: During development make sure to measure the required scanning time for all the electrodes in your system and configure the scanning time with AMCLKS, AMPSC and SMOD so that an overrun will not happen. Consider adding about 30 to 70% more time as headroom to make sure overrun is not triggered. If scanning time is critical and added scan time is not acceptable, detect the overrun condition either by polling the overrun flag in a loop or through the TSI interrupt. Once overrun is detected, disable the TSI module, clear all flags and reconfigure. During reconfiguration, SMOD can be increased by 10% or more of the current value to reduce the number of overrun occurrences.

e4935: UART: CEA709.1 features not supported

Errata type: Errata

Description: Due to some issues that affect compliance with the specification, the CEA709.1 features of the UART module are not supported. Normal UART mode, IrDA, and ISO-7816 are unaffected.

Workaround: Do not use the UART in CEA709.1 mode.

e7027: UART: During ISO-7816 T=0 initial character detection invalid initial characters are stored in the Rx FIFO

Errata type: Errata

Description: When performing initial character detection (UART_C7816[INIT] = 1) in ISO-7816 T=0 mode with UART_C7816[ANACK] cleared, the UART samples incoming traffic looking for a valid initial character. Instead of discarding any invalid initial characters that are received, the UART will store them in the receive FIFO.

Workaround: After a valid initial character is detected (UART_IS7816[INITD] sets), flush the Rx FIFO to discard any invalid initial characters that might have been received before the valid initial character.

e7028: UART: During ISO-7816 initial character detection the parity, framing, and noise error flags can set

Errata type: Errata

Description: When performing initial character detection (UART_C7816[INIT] = 1) in ISO-7816 mode the UART should not set error flags for any receive traffic before a valid initial character is detected, but the UART will still set these error flags if any of the conditions are true.

Workaround: After a valid initial character is detected (UART_IS7816[INITD] sets), check the UART_S1[NF, FE, and PF] flags. If any of them are set, then clear them.

e6472: UART: ETU compensation needed for ISO-7816 wait time (WT) and block wait time (BWT)

Errata type: Errata

Description: When using the default ISO-7816 values for wait time integer (UARTx_WP7816T0[WI]), guard time FD multiplier (UARTx_WF7816[GTFD]), and block wait time integer (UARTx_WP7816T1[BWI]), the calculated values for Wait Time (WT) and Block Wait Time (BWT) as defined in the Reference Manual will be 1 ETU less than the ISO-7816-3 requirement.

Workaround: To comply with ISO-7816 requirements, compensation for the extra 1 ETU is needed. This compensation can be achieved by using a timer, such as the low-power timer (LPTMR), to introduce a 1 ETU delay after the WT or BWT expires.

e4647: UART: Flow control timing issue can result in loss of characters if FIFO is not enabled

Errata type: Errata

Description: On UART0 and UART1 when /RTS flow control signal is used in receiver request-to-send mode, the /RTS signal is negated if the number of characters in the Receive FIFO is equal to or greater than the receive watermark. The /RTS signal will not negate until after the last character (the one that makes the condition for /RTS negation true) is completely received and recognized. This creates a delay between the end of the STOP bit and the negation of the /RTS signal. In some cases this delay can be long enough that a transmitter will start transmission of another character before it has a chance to recognize the negation of the /RTS signal (the /CTS input to the transmitter).

Workaround: Always enable the Rx FIFO if you are using flow control for UART0 or UART1. The receive watermark should be set to seven or less. This will ensure that there is space for at least one more character in the FIFO when /RTS negates. So in this case no data would be lost.

Note that only UART0 and UART1 are affected. The UARTs that do not have the Rx FIFO feature are not affected.

e4945: UART: ISO-7816 T=1 mode receive data format with a single stop bit is not supported

Errata type: Errata

Description: Transmission of ISO-7816 data frames with single stop bit is supported in T=1 mode. Currently in order to receive a frame, two or more stop bits are required. This means that 11 ETU reception based on T=1 protocol is not supported. T=0 protocol is unaffected.

Workaround: Do not send T=1, 11 ETU frames to the UART in ISO-7816 mode. Use 12 ETU transmissions for T=1 protocol instead.

e3892: UART: ISO-7816 automatic initial character detect feature not working correctly

Errata type: Errata

Description: The ISO-7816 automatic initial character detection feature does not work. The direct convention initial character can be detected correctly, but the inverse convention initial character will only be detected if the S2[MSBF] and S2[RXINV] bits are set. This defeats the purpose of the initial character detection and automatic configuration of the S2[MSBF], S2[RXINV], and C3[TXINV] bits.

Workaround: Use software to manually detect initial characters. Configure the UART with S2[MSBF] and S2[RXINV] cleared. Then check UART receive characters looking for 0x3B or 0x03. If 0x3B is received, then the connected card is direct convention. If 0x03 is received, then the connected card is inverse convention. If an inverse convention card is detected, then software should set S2[MSBF], S2[RXINV], and C3[TXINV].

e7029: UART: In ISO-7816 T=1 mode, CWT interrupts assert at both character and block boundaries

Errata type: Errata

Description: When operating in ISO-7816 T=1 mode and switching from transmission to reception block, the character wait time interrupt flag (UART_IS7816[CWT]) should not be set, only block type interrupts should be valid. However, the UART can set the CWT flag while switching from transmit to receive block and at the start of transmit blocks.

Workaround: If a CWT interrupt is detected at a block boundary instead of a character boundary, then the interrupt flag should be cleared and otherwise ignored.

e7090: UART: In ISO-7816 mode, timer interrupts flags do not clear

Errata type: Errata

Description: In ISO-7816, when any of the timer counter expires, the corresponding interrupt status register bits gets set. The timer register bits cannot be cleared by software without additional steps, because the counter expired signal remains asserted internally. Therefore, these bits can be cleared only after forcing the counters to reload.

Workaround: Follow these steps to clear the UART_IS7816 WT, CWT, or BWT bits:

1. Clear the UART_C7816[ISO_7816E] bit, to temporarily disable ISO-7816 mode.
2. Write 1 to the WT, CWT, or BWT bits that need to be cleared.
3. Set UART_C7816[ISO_7816E] to re-enable ISO-7816 mode.

Note that the timers will start counting again as soon as the ISO_7816E bit is set. To avoid unwanted timeouts, software might need to wait until new transmit or receive traffic is expected or desired before re-enabling ISO-7816 mode.

e7031: UART: In single wire receive mode UART will attempt to transmit if data is written to UART_D

Errata type: Errata

Description: If transmit data is loaded into the UART_D register while the UART is configured for single wire receive mode, the UART will attempt to send the data. The data will not be driven on the pin, but it will be shifted out of the FIFO and the UART_S1[TDRE] bit will set when the character shifting is complete.

Workaround: Do not queue up characters to transmit while the UART is in receive mode. Always write UART_C3[TXDIR] = 1 before writing to UART_D in single wire mode.

e5704: UART: TC bit in UARTx_S1 register is set before the last character is sent out in ISO7816 T=0 mode

Errata type: Errata

Description: When using the UART in ISO-7816 mode, the UARTx_S1[TC] flag sets after a NACK is received, but before guard time expires.

Workaround: If using the UART in ISO-7816 mode with T=0 and a guard time of 12 ETU, check the UARTn_S1[TC] bit after each byte is transmitted. If a NACK is detected, then the transmitter should be reset.

The recommended code sequence is:

```
UART0_C2 &= ~UART_C2_TE_MASK; //make sure the transmitter is disabled at first
UART0_C3 |= UART_C3_TXDIR_MASK; //set the TX pin as output
UART0_C2 |= UART_C2_TE_MASK; //enable TX
UART0_C2 |= UART_C2_RE_MASK; //enable RX to detect NACK
for(i=0;i<length;i++)
{
while(!(UART0_S1&UART_S1_TDRE_MASK)){
UART0_D = data[i];
while(!(UART0_S1&UART_S1_TC_MASK)){//check for NACK
if(UART0_IS7816 & UART_IS7816_TXT_MASK)//check if TXT flag set
{
/* Disable transmit to clear the internal NACK detection counter */
UART0_C2 &= ~UART_C2_TE_MASK;
UART0_IS7816 = UART_IS7816_TXT_MASK;// write one to clear TXT
UART0_C2 |= UART_C2_TE_MASK; // re-enable transmit
}
}
UART0_C2 &= ~UART_C2_TE_MASK; //disable after transmit
```

e7091: UART: UART_S1[NF] and UART_S1[PE] can set erroneously while UART_S1[FE] is set

Errata type: Errata

Description: While the UART_S1[FE] framing error flag is set the UART will discard any received data. Even though the data is discarded, if characters are received that include noise or parity errors, then the UART_S1[NF] or UART_S1[PE] bits can still set. This can lead to triggering of unwanted interrupts if the parity or noise error interrupts are enabled and framing error interrupts are disabled.

Workaround: If a framing error is detected (UART_S1[FE] = 1), then the noise and parity error flags can be ignored until the FE flag is cleared. Note: the process to clear the FE bit will also clear the NF and PE bits.

e7092: UART: UART_S1[TC] is not cleared by queuing a preamble or break character

Errata type: Errata

Description: The UART_S1[TC] flag can be cleared by first reading UART_S1 with TC set and then performing one of the following: writing to UART_D, queuing a preamble, or queuing a break character. If the TC flag is cleared by queuing a preamble or break character, then the flag will clear as expected the first time. When TC sets again, the flag can be cleared by any of the three clearing mechanisms without reading the UART_S1 register first. This can cause a TC flag occurrence to be missed.

Workaround: If preamble and break characters are never used to clear the TC flag, then no workaround is required.

If a preamble or break character is used to clear TC, then write UART_D immediately after queuing the preamble or break character.

e5928: USBOTG: USBx_USBTRC0[USBRESET] bit does not operate as expected in all cases

Errata type: Errata

Description: The USBx_USBTRC0[USBRESET] bit is not properly synchronized. In some cases using the bit can cause the USB module to enter an undefined state.

Workaround: Do not use the USBx_USBTRC0[USBRESET] bit. If USB registers need to be written to their reset states, then write those registers manually instead of using the module reset bit.

e6933: eDMA: Possible misbehavior of a preempted channel when using continuous link mode

Errata type: Errata

Description: When using continuous link mode (DMA_CR[CLM] = 1) with a high priority channel linking to itself, if the high priority channel preempts a lower priority channel on the cycle before its last read/write sequence, the counters for the preempted channel (the lower priority channel) are corrupted. When the preempted channel is restored, it runs past its "done" point instead of performing a single read/write sequence and retiring.

The preempting channel (the higher priority channel) will execute as expected.

Workaround: Disable continuous link mode (DMA_CR[CLM]=0) if a high priority channel is using minor loop channel linking to itself and preemption is enabled. The second activation of the preempting channel will experience the normal startup latency (one read/write sequence + startup) instead of the shortened latency (startup only) provided by continuous link mode.

How to Reach Us:

Home Page:

freescale.com

Web Support:

freescale.com/support

Information in this document is provided solely to enable system and software implementers to use Freescale products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document.

Freescale reserves the right to make changes without further notice to any products herein. Freescale makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in Freescale data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. Freescale does not convey any license under its patent rights nor the rights of others. Freescale sells products pursuant to standard terms and conditions of sale, which can be found at the following address: freescale.com/SalesTermsandConditions.

Freescale, the Freescale logo, AltiVec, C-5, CodeTest, CodeWarrior, ColdFire, ColdFire+, C-Ware, Energy Efficient Solutions logo, Kinetis, mobileGT, PowerQUICC, Processor Expert, QorIQ, Qorivva, StarCore, Symphony, and VortiQa are trademarks of Freescale Semiconductor, Inc., Reg. U.S. Pat. & Tm. Off. Airfast, BeeKit, BeeStack, CoreNet, Flexis, Layerscape, MagniV, MXC, Platform in a Package, QorIQ Qonverge, QUICC Engine, Ready Play, SafeAssure, SafeAssure logo, SMARTMOS, Tower, TurboLink, Vybrid, and Xtrinsic are trademarks of Freescale Semiconductor, Inc. All other product or service names are the property of their respective owners.

© 2013 Freescale Semiconductor, Inc.

