



Order this document by EB312

Motorola Semiconductor Engineering Bulletin

EB312

Replacing 68HC11KA4/KA2 MCUs with 68HC11KS2/KS8 MCUs

By Mario Garcia and Hilario Garza Transportation Systems Group Austin, Texas

Introduction

The information in this engineering bulletin is presented to users of the 68HC11KAx Family (KA4/KA2) microcontrollers (MCUs) who are considering converting to the 68HC11KSx Family MCUs (KS2/KS8).

The 68HC11KSx Family was designed to provide more ROM and RAM for KA4 users. Also, a software selectable slow mode feature to reduce power consumption has been added.

Both device families have the same pinouts in the 68-pin PLCC (plastic leaded chip carrier) and 80-pin TQFP (thin quad flat pack) packages.

The 68HC11KSx MCUs have enhancements requiring special design considerations.

Table 1 lists the major features of each device in the families.





Engineering Bulletin

Table 1, 68HC11KAx and 68HC11KSx Features

Device Number	ROM in Bytes	RAM in Bytes	EEPROM in Bytes	I/O	Slow Mode
68HC11KA4	24 K	768	640	51	No
68HC11KA2	32 K	1 K	640	51	No
68HC11KS2	32 K	1 K	640	51	Yes
68HC11KS8	48 K	1.5 K	640	51	Yes

Basic Question and Answer

Can 68HC11KAx code run on 68HC11KSx without changes?

Most users can run 68HC11KAx code on 68HC11KSx devices without changes to code. However, the system memory configuration and software use of registers and control bits needs to be reviewed to determine if code changes are needed.

Pin Assignments

The 68HC11KAx and 68HC11KSx devices are pin-to-pin compatible.

Converting

Table 2 — showing differences, issues, and changes — describes the extent of analysis required for various 68HC11KAx Family applications. In each case, the version of 68HC11KAx devices affected and the issues involved in converting to 68HC11KSx devices are identified.

Difference: ROM

The 68HC11KS2 has 32 Kbytes of ROM at address locations \$8000–\$FFFF, and 68HC11KS8 has 48 Kbytes of ROM at address locations \$4000–\$FFFF.

The 68HC11KA4 has 24 Kbytes of ROM at address locations \$A000–\$FFFF, and the 68HC11KA2 has 32 Kbytes of ROM at address locations \$8000–\$FFFF.

EB312



Engineering Bulletin
Basic Question and Answer

Case 1

Case: Single-chip mode, custom (masked) 68HC11KA4 ROM devices

Issue: ROM code must be resubmitted.

Change required: Source code must be changed to blank out the extra ROM locations of the 68HC11KS2 (\$8000–\$9FFF) or 68HC11KS8 (\$4000–\$9FFF) and add the current 68HC11KA4 source code to locations \$A000–\$FFFF. Also, no reads and/or writes should occur to the system configuration option 3 register (OPT3, \$002E).

NOTE:

Location \$002E is a reserve register for the 68HC11KAx devices so most users' code should not be addressing this location. Object code (S-records) must be resubmitted to Motorola.

Case 2

Case: Single-chip mode, custom (masked) 68HC11KA2 ROM devices

Issue: ROM code must be resubmitted.

Change required: No source code changes are needed if the 68HC11KA2 is being replaced with the 68HC11KS2 and no reads and/or writes occur to the system configuration option 3 register (OPT3, \$002E).

NOTE:

Location \$002E is a reserve register for the 68HC11KAx devices so most users' code should not be addressing this location. Object code (S-records) must be resubmitted to Motorola.

Source code must be changed if the 68HC11KA2 is being replaced with the 68HC11KS8. Blank out the extra ROM locations of the 68HC11KS8 (\$4000–\$9FFF), and add current 68HC11KA2 source code to locations \$A000–\$FFFF. Also, no reads and/or writes should occur to the system configuration option 3 register (OPT3, \$002E).

NOTE:

Location \$002E is a reserve register for the 68HC11KAx devices so most users' code should not be addressing this location. Object code (S-records) must be resubmitted to Motorola.

EB312

NXP

Freescale Semiconductor, Inc.

Engineering Bulletin

Case 3 Case: Expanded mode, custom (masked) 68HC11KA4 ROM devices

Issue: ROM code must be resubmitted.

Change required: Ensure that address space \$8000– \$9FFF is not used by external devices (memories and/or peripherals) when replacing it with a 68HC11KS2. Or, ensure that address space \$4000–\$9FFF is not used by external devices (memories and/or peripherals) when replacing it with a 68HC11KS8. Source code must be changed to blank out the extra ROM locations of the 68HC11KS2 (\$8000–\$9FFF) or 68HC11KS8 (\$4000–\$9FFF), and add current 68HC11KA4 source code to locations \$A000–\$FFFF. Also, no reads and/or writes should occur to the system configuration option 3 register (OPT3, \$002E).

NOTE: Location \$002E is a reserve register for the 68HC11KAx devices so

most users' code should not be addressing this location. Object code

(S-records) must be resubmitted to Motorola.

Case 4 Case: Expanded mode, custom (masked) 68HC11KA2 ROM devices

Issue: ROM code must be resubmitted.

Change required: No address space conflicts should occur when replacing a 68HC11KA2 with 68HC11KS2. No source code changes are needed if no reads and/or writes occur to the system configuration

option 3 register (OPT3, \$002E).

NOTE: Location \$002E is a reserve register for the 68HC11KAx devices so most users' code should not be addressing this location. Object code

(S-records) must be resubmitted to Motorola.

Ensure that address space \$4000–\$9FFF is not used by external devices (memories and/or peripherals) when replacing it with a 68HC11KS8. Source code must be changed to blank out the extra ROM locations of the 68HC11KS8 (\$4000–\$9FFF), and add current 68HC11KA2 source code to locations \$A000–\$FFFF. Also, no reads and/or writes should occur to the system configuration option 3 register (OPT3, \$002E).

EB312



Engineering Bulletin
Basic Question and Answer

NOTE: Location \$002E is a reserve register for the 68HC11KAx devices so most users' code should not be addressing this location. Object code (S-records) must be resubmitted to Motorola.

Table 2. Summary of Differences

Item	68HC11KAx	68HC11KSx	Issues	
ROM	68HC11KA4 — 24 Kbytes located \$A000 to \$FFFF	68HC11KS2 — 32 Kbytes located \$8000 to \$FFFF	Source code changes; potential address conflicts	
1.0	68HC11KA2 — 32 Kbytes located \$8000 to \$FFFF	68HC11KS8 — 48 Kbytes located \$4000 to \$FFFF	in expanded mode	
RAM	68HC11KA4 — 768 bytes located \$0000 to \$02FF	68HC11KS2 — 1 Kbyte located \$0000 to \$03FF	Potential address conflicts in expanded mode (If 128-byte register block is	
RAM	68HC11KA2 — 1 Kbyte located \$0000 to \$03FF	68HC11KS8 — 1.5 Kbytes located \$0000 to \$05FF	mapped at the same location as RAM, offset RAM locations by \$0080.)	
Bootstrap mode	Download terminates after all 768-RAM bytes (68HC11KA4) or 1-K RAM bytes (68HC11KA2) are written or after receiver detects 4 idle characters	Download terminates after all 1-K RAM bytes (68HC11KS2) or 1.5-K RAM bytes (68HC11KS8) are written or after receiver detects 4 idle characters	Download duration	
Register	Location \$002E is a reserve register	Location \$002E is the system configuration option 3 register	Source code changes; potential of enabling the slow mode option, system clocks will slow down	

Difference: RAM

The 68HC11KS2 has 1 Kbyte of RAM at address locations \$0000–\$03FF (\$0080–\$047F when 128-byte register block is mapped at the same location as RAM), and 68HC11KS8 has 1.5 Kbytes of RAM at address locations \$0000–\$05FF (\$0080–\$067F when 128-byte register block is mapped at the same location as RAM).

The 68HC11KA4 has 768 bytes of RAM at address locations \$0000–\$02FF (\$0080–\$037F when 128-byte register block is mapped at the same location as RAM), and the 68HC11KA2 has 1 Kbyte of RAM at address locations \$0000–\$03FF (\$0080–\$047F when 128-byte register block is mapped at the same location as RAM).

EB312





Engineering Bulletin

Case 1 Case: Single-chip mode, custom (masked) 68HC11KA4/KA2 ROM

devices

Issue: None

Change required: None. However, the user may want to take

advantage of the extra RAM space.

Case: Expanded mode, custom (masked) 68HC11KA4 ROM devices

Issue: Potential conflict with external memories

Change required: Ensure that address space from \$0300-\$03FF (\$037F-\$047F when 128-byte register block is mapped at the same location as RAM) is not used by external devices (memories and/or peripherals) when replacing it with a 68HC11KS2. Or, ensure that address space \$0300-\$05FF (\$037F-\$067F when 128-byte register block is mapped at the same location as RAM) is not used by external devices (memories and/or peripherals) when replacing it with a

68HC11KS8.

Case 3 Case: Expanded mode, custom (masked) 68HC11KA2 ROM devices

Issue: Potential conflict with external memories

Change required: No address space conflicts should occur when

replacing with 68HC11KS2.

Ensure that address space from \$0400–\$05FF (\$047F–\$067F when 128-byte register block is mapped at the same location as RAM) is not used by external devices (memories and/or peripherals) when replacing with a 68HC11KS8.

EB312



Engineering Bulletin Basic Question and Answer

Difference: Bootstrap Mode

The bootloader function on the 68HC11KAx/68HC11KSx devices terminates a serial download to RAM after all 768 locations of RAM have been filled for the 68HC11KA4, 1-K locations for 68HC11KA2 or 68HC11KS2, and 1.5-K locations for 68HC11KS8.

The bootloader will also terminate downloading after four idle characters have been received by the serial unit. Program control then is passed to the RAM.

Case

Case: All 68HC11KA4 and some 68HC11KA2 devices

Issue: Length of download

Change required: None. However, a larger program may now be downloaded if replacing 68HC11KA4 with 68HC11KS2 or 68HC11KS8 and 68HC11KA2 with 68HC11KS8 due to the additional RAM.

Difference: Register

Reads, writes, and compares of the register in **Table 3** may have an effect on the system when switching between the 68HC11KAx and 68HC11KSx Families.

The bold text in **Table 3** represents the register or bit differences.

Table 3. Register Differences

Register	Bit	Register							
Address	7	6	5	4	3	2	1	0	Name
\$002E	_	SM	_	_	_	_	-	-	ОРТ3

OPT3

Bit 6 in the OPT3 enables the slow mode option when software is selected for the 68HC11KSx Family.

The OPT3 register is a reserve byte in the 68HC11KAx Family.

EB312



Engineering Bulletin

Special Section: CONFIG Register Verification and Reprogramming Routine

To guarantee proper operation of EEPROM-based M68HC11 devices, the CONFIG (configuration) register must be programmed correctly.

A CONFIG register verification and reprogramming routine should be included at the beginning of critical M68HC11 programs.

This code is an example of how to verify and, if necessary, reprogram the EEPROM CONFIG register to ensure proper operation. These same results can be accomplished also with less generic, user-specified code.

```
(C) MOTOROLA, INC., 1995 (created 05/01/95)
```

FILENAME: config.asm

- * DESCRIPTION: This code checks the CONFIG register on an EEPROM-based
- * HC11 device and reprograms it with the proper value if necessary.

\$0000 REGBASE equ

;default beginning of HC11KSx registers

* Offsets from the beginning of the register block.

TOC4	equ	\$1C
TCNT	equ	\$0E
TFLG1	equ	\$23
BPROT	equ	\$35
OPTION	equ	\$39
PPROG	equ	\$3B
CONFIG	equ	\$3F

* The following register bit constants are needed.

OC4F	equ	\$10
PTCON	equ	\$10
CME	equ	\$08
BYTE	equ	\$10
ERASE	equ	\$04
EELAT	equ	\$02
EEPGM	equ	\$01

* Fill in the blank that follows with the desired CONFIG register value. Also, choose the appropriate delay based on E frequency.

EB312



Engineering Bulletin Special Section: CONFIG Register Verification and Reprogramming Routine

* Other user constants should follow, including:

MY_CONFIG equ \$__ ;CONFIG should be __

DELAY equ \$9C40 ;\$9C40 = 40,000 counts at 4 MHz ;\$7530 = 30,000 counts at 3 MHz

* Program begins here.

Fill in the program starting address in the following blank.

START org \$____ ;program starts here

lds #\$03FF ;set a valid stack pointer for 68HC11KS2

;\$047F for KS2 with REGBASE located at

;\$0000

;\$05FF for KS8

;\$067F for KS8 with REGBASE located at

;\$0000

ldx #REGBASE ;set beginning of register block

ldaa CONFIG,X ;read CONFIG

cmpa #MY_CONFIG ; check for valid CONFIG

beq NORMAL ;if CONFIG is OK, go on as usual

At this point, 49 cycles remain for modifications to be made to the time protected registers (TMSK2, BPROT, OPTION, and INIT), if necessary, on all HC11 devices.

bclr BPROT, X, PTCON ; clear CONFIG protect bit

* CONFIG erase sequence.

ldaa #BYTE + #ERASE + #EELAT

staa PPROG,X

The EEPROM erase sequence requires that some data be stored to the byte being erased. The actual data stored and instructions used are irrelevant; it is only necessary to complete a memory write cycle to the location in question.

staa CONFIG,X ;store something to CONFIG

ldaa #BYTE + #ERASE + #EELAT + #EEPGM

staa PPROG,X

jsr EEDELAY ;wait 10 ms

clr PPROG,X ;finish erase sequence

EB312



Engineering Bulletin

* CONFIG program sequence.

ldaa #ERASE + #EELAT staa PPROG,X #MY CONFIG ;desired CONFIG value ldaa staa CONFIG, X #ERASE + #EELAT + #EEPGM ldaa PPROG, X staa jsr EEDELAY ;wait 10 ms

clr PPROG,X ;finish program sequence * Now allow clock monitor to reset the HC11 and latch the new CONFIG

* register value.

stop ;enter stop mode and allow reset

* User program resumes normally here.

NORMAL etc.

* This EEPROM delay subroutine may be used for any EEPROM programming

* or erase operations.

EEDELAY ldd TCNT,X ;get current time

The #DELAY term used for program and erase operations is calculated as follows:

DELAY = ECLK 100

Typical decimal values for DELAY are 30000 at 3 MHz, 20000 at 2 MHz, and 10000 at 1 MHz. Note that these values apply when the timer prescale is divide-by-1.

addd #DELAY ;add delay
std TOC4,X ;allow match at end of delay
ldaa #OC4F ;clear last OC4 match
staa TFLG1,X

* Wait for OC4 match (end of 10 ms delay) to occur.

DELAYLOOP brclr TFLG1,X,OC4F,DELAYLOOP

rts ;end of delay loop

EB312





Engineering Bulletin Special Section: CONFIG Register Verification and Reprogramming Routine

EB312



Engineering Bulletin

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended to surgical implant into the body, or other application instended to support or sustini life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and (A) are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

How to reach us:

USA/EUROPE/Locations Not Listed: Motorola Literature Distribution, P.O. Box 5405, Denver, Colorado 80217.

1-800-441-2447 or 1-303-675-2140. Customer Focus Center, 1-800-521-6274

JAPAN: Motorola Japan Ltd.: SPD, Strategic Planning Office, 141, 4-32-1 Nishi-Gotanda, Shinagawa-Ku, Tokyo, Japan, 03-5487-8488

ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd., Silicon Harbour Centre, 2 Dai King Street, Tai Po Industrial Estate,

Tai Po, New Territories, Hong Kong, 852-26629298

Mfax™, Motorola Fax Back System: RMFAX0@email.sps.mot.com; http://sps.motorola.com/mfax/;

TOUCHTONE, 1-602-244-6609; US and Canada ONLY, 1-800-774-1848

HOME PAGE: http://motorola.com/sps/

Mfax is a trademark of Motorola, Inc.

© Motorola, Inc., 1999

EB312/D

