



## 68836 FCG (1F14B) ERRATA

(March 30, 1995)

The 1F14B mask set (Rev B) conforms with the full specification of the 68836, with the following exception.

### 1. **TTL Output Drivers Out of Specification:**

Under certain circumstances, after the TS pin has been at a logic "low", the TTL output drivers consume excess current. This appears as distorted waveforms on the TTL output pins.

*Workaround:* It is recommended that the TS pin be connected to Vcc to ensure that TS not be brought to a logic "low".

## **Notice**

Specifications and information herein are subject to change without notice. Motorola reserves the right to make changes to any products described herein to improve functioning or design. Although the information in this document has been carefully reviewed and is believed to be reliable, Motorola does not assume any liability arising out of the application or use of any product, program, or circuit described herein; neither does it convey any license under its patent right nor the rights of others.

Motorola Inc.'s general policy does not recommend the use of its components in life support applications wherein a failure or malfunction of the component may directly threaten life or injury. Per Motorola Terms and Conditions of Sale, the user of Motorola components in life support applications assumes all risk of such use and indemnifies Motorola against all damages.