Document Number: WCT15W1CFFPDCE
Rev. 0, 05/2019

Errata for the WCT-15W1CFFPD

This document details all known errata for the WCT-15W1CFFPD. This table provides a revision history for this document.

Table 1. Document revision history

Rev. number	Date	Substantive change(s)
0	05/09/2019	Initial release.

Description:

The U7 and U8 power stages are not the same chip with the SCH MP86901D.

Workaround:

The function and performance is similar, so you can use the demo board to evaluate all features of the WCT-15W1CFFPD.



Figure 1.

How to Reach Us:

Home Page:
nxp.com

Web Support:
nxp.com/support

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. “Typical” parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including “typicals,” must be validated for each customer application by customer’s technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: nxp.com/SalesTermsandConditions.

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer’s applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

Document Number: WCT15W1CFFPDCE
Rev. 0
05/2019