Freescale Semiconductor, Inc.

MOTOROLA

Chip Errata
DSP56001 Digital Signal Processor
Mask: B38E/B39P

ERRATA

Errata Description	Applies to Mask
1. The DSP will stop fetching instructions and will not resume operation until power is cycled if an illegal instruction (i. e. an unrecognized op code) is executed.	B38E B39P B77G

**For More Information On This Product,
Go to: www.freescale.com**

NOTES

1. An over-bar (i.e. $\overline{xxxx}$) indicates an active-low signal.
2. The letters seen to the right of the errata tell which DSP56002 mask numbers apply.

-end-