

# Motorola Semiconductor Engineering Bulletin

# EB187

# Programming MC68HC711E9 Devices with PCbug11 and the M68HC11EVB

By John Bodnar Austin, Texas

#### Introduction

The PCbug11 software, needed along with the M68HC11EVB to program MC68HC711E9 devices, is available from the download section of the Microcontroller Worldwide Web site www.mcu.motsps.com.

Retrieve the file pcbug342.exe (a self-extracting archive) from the MCU11 directory.

Some Motorola evaluation board products also are shipped with PCbug11.

**NOTE:** For specific information about any of the PCbug11 commands, see the appropriate sections in the PCbug11 User's Manual (part number M68PCBUG11/D2), which is available from the Motorola Literature Distribution Center, as well as the Worldwide Web at www.mcu.motsps.com. The file is also on the software download system and is called pcbug11.pdf.





#### **Engineering Bulletin**

#### To Execute the Program

Once you have obtained PCbug11, use this step-by-step procedure to program your MC68HC711E9 part. This procedure has been tested only on M68HC11EVB revision C boards and may not work properly on earlier revision A and revision B boards.

Step 1

Before applying power to the M68HC11EVB, the MODA and MODB pins on the MC68HC11 must be grounded . To do this, connect pins 1, 2, and 3 on the EVB's P1 connector.

Grounding MODA and MODB will force the EVB into special bootstrap mode on power-up.

Also take note of P1 connector pin 18. In step 5, you will connect a +12volt (at most +12.5 volts) programming voltage through a 100- $\Omega$  current limiting resistor to the XIRQ pin. Do not connect this programming voltage until you are instructed to do so in step 2.

- Remove the resident MC68HC11A1 from socket U10 on the EVB. Place a MC68HC711E9 in the open socket with the notched corner of the part aligned with the notch on the PLCC socket.
- Connect the EVB host port (the DB25 connector nearest to the EVB power supply connector) to one of your PC COM ports through a null modem cable or a serial cable with a null modem adapter. Null modem adapters and cables can be purchased from computer hardware vendors and specialized cable manufacturers. The null modem connection is required because the EVB host port swaps the transmit (TxD) and receive (RxD) connections so that the resident MC68HC11 can communicate with a remote computer via a modem. To communicate with a personal computer via a COM port, these connections must be reversed.
- Apply -12 volts to -12, ground to GND, +5 volts to +5, and +12 volts to +12 on the power connector P4 of your EVB.

Semiconductor, Inc

eescale



Engineering Bulletin To Execute the Program

Step 2	From a DOS command line prompt, start PCbug11 like this:
	C:\PCBUG11\ > PCBUG11 –E PORT = 1
	with the EVB connected to COM1
	or
	C:\PCBUG11\> PCBUG11 -E PORT = 2
	with the EVB connected to COM2
	PCbug11 only supports COM ports 1 and 2.
Step 3	PCbug11 defaults to base 10 for its input parameters.
	Change this to hexadecimal by typing: CONTROL BASE HEX
Step 4	You must declare the addresses of the EPROM array to PCbug11.
	To do this, type: EPROM D000 FFFF.
Step 5	You are now ready to download your program into the EPROM. Connect +12 volts (at most +12.5 volts) through a 100- $\Omega$ current limiting resistor to P1 connector pin 18, the XIRQ* pin.
	At the PCbug11 command prompt. type:
	LOADS C:\MYPROG\ISHERE.S19
	Substitute the name of your program into the command above. Use a full path name if your program is not located in the same directory as PCbug11.
Step 6	After the programming operation is complete, PCbug11 will display this message:
	Total bytes loaded: \$xxxx
	Total bytes programmed: \$yyyy

EB187



**Engineering Bulletin** 

You should now remove the programming voltage from P1 connector pin 18, the XIRQ\* pin.

Each ORG directive in your assembly language source will cause a pair of these lines to be generated. For this operation, \$yyyy will be incremented by the size of each block of code programmed into the EPROM of the MC68HC711E9.

PCbug11 will display the above message whether or not the programming operation was successful.

As a precaution, you should have PCbug11 verify your code.

At the PCbug11 command prompt type:

VERF C:\MYPROG\ISHERE.S19.

Substitute the name of your program into the command above. Use a full path name if your program is not located in the same directory as PCBug11. If the verify operation fails, a list of addresses which did not program correctly is displayed. Should this occur, you probably need to erase your part more completely. To do so, allow the MC68HC711E9 to sit for at least 45 minutes under an ultraviolet light source. Attempt the programming operation again. If you have purchased devices in plastic packages (one-time programmable parts), you will need to try again with a new, unprogrammed device.

To restore normal operation of the EVB after you are finished programming your MC68HC711E9 devices:

- Disconnect all voltages from power connector P4
- Disconnect the programming voltage from P1 connector pin 18 (XIRQ)
- Disconnect the null modem assembly from the host port
- Reinstall the MC68HC11A1 in socket U10
- Disconnect pins 1, 2, and 3 on the EVB's P1 connector

Step 7



Engineering Bulletin To Execute the Program

The EVB will now operate normally under the control of the BUFFALO monitor. You do not need the null modem assembly for normal operation, and you will connect your personal computer to the EVB via the terminal port, not the host port.

EB187

MOTOROLA



**Engineering Bulletin** 

EB187



Engineering Bulletin To Execute the Program

EB187

MOTOROLA



**Engineering Bulletin** 

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights or the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

#### How to reach us:

USA/EUROPE/Locations Not Listed: Motorola Literature Distribution, P.O. Box 5405, Denver, Colorado 80217, 1-800-441-2447 or 1-303-675-2140. Customer Focus Center, 1-800-521-6274

JAPAN: Nippon Motorola Ltd. SPD, Strategic Planning Office 4-32-1, Nishi-Gotanda Shinagawa-ku, Tokyo 141, Japan, 81-3-5487-8488 ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd., 8B Tai Ping Industrial Park, 51 Ting Kok Road, Tai Po, N.T., Hong Kong, 852-26629298 Mfax<sup>™</sup>, Motorola Fax Back System: RMFAX0@email.sps.mot.com; http://sps.motorola.com/mfax/;

TOUCHTONE, 1-602-244-6609; US and Canada ONLY, 1-800-774-1848

HOME PAGE: http://motorola.com/sps/



Mfax is a trademark of Motorola, Inc.

© Motorola, Inc., 1998