
Mask Set Errata for Mask 3L50P

Introduction

This report applies to mask 3L50P for these products:

- MC68HC908GR60A
- MC68HC908GR48A
- MC68HC908GR32A

The mask set is identified by a 5-character code consisting of a version number, a letter, two numerical digits, and a letter, for example 0J27F. All standard devices are marked with a mask set number and a date code.

Device markings indicate the week of manufacture and the mask set used. The date is coded as four numerical digits where the first two digits indicate the year and the last two digits indicate the work week. For instance, the date code "0301" indicates the first week of the year 2003.

Some MCU samples and devices are marked with an SC, PC, or XC prefix. An SC prefix denotes special/custom device. A PC prefix indicates a prototype device which has undergone basic testing only. An XC prefix denotes that the device is tested but is not fully characterized or qualified over the full range of normal manufacturing process variations. After full characterization and qualification, devices will be marked with the MC or SC prefix.

SE91-LIN_Break: LIN Break Delimiter Recognition

Description: Under specific timing conditions, the ESCI module will fail to properly detect the break delimiter character in a LIN message. When this occurs, the falling edge that marks the beginning of the actual START bit of the synch 0x55 character is not properly seen by the ESCI. Therefore, the next falling edge to appear on the receive pin after that time (beginning of bit 1 of 0x55 character in LIN) is incorrectly interpreted to be the beginning of a START bit of a new byte.

The timing conditions which cause this to occur are when both:

1. The break character is observed at the receive pin to end approximately on a half bit boundary (about 11.5 bits, 12.5 bits, 13.5 bits, etc.) according to the ESCI local receive clock.
2. The break delimiter received appears to be shorter than one bit time, as measured by the ESCI local receive clock.

The length of the break character as observed by the ESCI at the receive pin (See 1. above) is affected by all of the following:

- The length of the actual transmitted character
- The frequency drift in the local slave clock due to temperature and voltage variations
- Ground shift and edge slew effects in the physical layer

These factors can combine to cause a break character that was transmitted by a master to be nominally 13 bits (as measured by the master clock) to be observed by the slave device as ending on a half bit boundary (13.5 bits as measured by the slave clock, for example).

The break delimiter character only needs to be two or more clock cycles shorter than one bit time to cause the break delimiter to not be detected. (See 2. above)

This situation can occur without violating LIN timing specifications or microcontroller oscillator specifications.

Workaround:

One way to properly sample the BREAK delimiter is to switch off the receiver after the rising edge of the delimiter is detected by the arbiter, wait a clock cycle and switch back on the receiver. This will reset the internal sampling clock and will insure accurate recognition of the delimiter.

To implement this solution, in the break symbol interrupt (error interrupt when BKF is set):

1. Set up the arbiter to measure falling- to rising-edge pulse
2. Poll AFIN until set to indicate edge of break delimiter
 - To minimize this polling time, ensure that the LINR bit is set to move the break detection interrupt to the 11th-bit of the break character.
3. Clear RE to disable receiver, execute a NOP, then set RE to re-enable receiver
 - The purpose of the NOP instruction is to prevent a C compiler optimization from deleting this step.
4. Clear FE interrupt by reading data register then exit ISR.

This solution uses polling of the AFIN bit to detect the rising edge of the delimiter. As this is a polling method, the user must evaluate impact of this method to system timing performance.

A non-polling solution can also be implemented using an additional input capture or keyboard interrupt input to detect the rising edge at the end of the break symbol.

The input used must be both:

- Physically connected to the ESCI receive pin
- Able to generate an interrupt upon detection of a rising edge on that pin

To implement this solution, in the break symbol interrupt (error interrupt when BKF is set):

1. Set up the appropriate module to detect rising edge on the receive pin and generate an interrupt
2. Clear the FE and BKF flags by reading the data register, and then exit the ISR

In the rising edge detection interrupt:

1. Clear RE to disable the receiver, execute a NOP, then set RE to re-enable the receiver
 - The purpose of the NOP instruction is to prevent a C compiler optimization from deleting this step.
2. Clear appropriate flags if needed and exit the ISR.

A combination of both previous methods could also be implemented to reduce CPU polling impact. For instance, a periodic interrupt could execute some code during the polling and then return to polling, or the user could put some application code in the polling loop.

The time between when the rising edge actually appears on the receive pin and when the receiver is switched back on is finite and is governed by the timing of the falling edge of the delimiter. The receiver must be switched back on no later than 9/16th of a bit time before the end of the delimiter. See figure below.




Figure 1. Maximum Time for Other Execution

From this figure, we also see that the “Maximum Reaction Time” is 7/16th slave bit-time.

Translating that into an example LIN system yields:

One bit time at 19200 bps is 52.1 μs.

The LIN 1.3 specification indicates the slave can run at ±14% and the master at ±0.5% of the nominal baudrate. The smallest bit-time the slave might observe is (accounting for accumulated timing errors of a slow slave and fast master):

$$(100\% - 14.5\%) \times (52.1 \mu\text{s}) = (0.855) \times (52.1 \mu\text{s}) = 44.5 \mu\text{s}$$

The Maximum Reaction Time for this example system is 7/16 x (44.5 μs) = 19.47 μs.

From the instant the rising edge appears on the receive pin (detected via the arbiter AFIN bit or a timer interrupt), the software has to switch the receiver OFF and back ON within 19.47 μs.

Because ground shift in the physical layer might also affect the timing of the falling edge of the START bit of the 0x55 synch byte (i.e., the end of the delimiter), best design practices suggest that the switching of the receiver should be done as quickly as possible after the rising edge is detected. The maximum reaction time calculated above should be treated as a guideline only.

Another workaround which may be used is to temporarily increase the baud rate of the slave device during the reception of the break delimiter. This helps to ensure that the break delimiter appears to the ESCI receiver as greater than one bit time, eliminating timing condition 2 under most operating conditions.

To implement this solution:

1. In the break symbol interrupt (error interrupt when BKF is set), increase the bit rate of the ESCI by a maximum of 9%
2. Remove the 9% speed increase when calculating the baud rate adjustment for that message frame. Only remove the portion of the 9% adjustment that is implemented in the enhanced prescaler (PD+PDFA), as this is the prescaler stage that affects the arbiter measurement of bit time.

The value of 9% allows for differences in clock speeds between master and slave (< 5.5%) and partially compensates for possible effects of a positive ground shift and slew rate effects in the physical layer. These physical layer effects can shorten the length of a recessive pulse (e.g., the break delimiter) by as much as 20.8% ($-10.4 \mu\text{s}$ at 20 kbps) of its nominal value and remain within the LIN specification. (Refer to the LIN Physical Layer Specification for more information).

This method is not 100% effective in removing timing condition 2, as the LIN specification does allow enough ground or battery shift to reduce the break delimiter by as much as 20.8%. This means that under absolute worst case conditions in a LIN system, this workaround will not guarantee that a delimiter can be seen.

Ground shift effects cannot be fully compensated for as you would need to increase baud rate by as much as 27%. However, 9% is the maximum safe value to increase baud rate, as it fully compensates for the 5.5% maximum clock difference between master and slave and partially compensates for smaller ground shift effects. If these factors combine, an effective difference of 14.5% in baud rate may be seen with this workaround.

In a LIN system, since the 0x55 character is known to be the next character to be received, the typical guideline of 4.5% difference between two UART devices can be stretched to a little more than 15%. This is because the greatest distance between two falling edges in a 0x55 character is only two bit-times and the UART will resynch on those edges and guarantee reception of the character if both devices are within around 15% of each other's speeds.

SE51-OPCODE: Illegal opcode reset

Description: If the stop enable bit, STOP, in the CONFIG1 register is 0, the MCU treats the STOP instruction as an illegal opcode. A race condition with 2 signals between the CPU and SIM causes this illegal opcode to recover improperly. The CPU will execute code as if in a runaway condition (Program Counter disrupted). In most cases this improper code execution will generate an additional reset due to a COP timeout, another illegal opcode, or an illegal address fetch. Other behaviors can occur depending on the execution of the code accessed by the CPU.

Workaround: Use another illegal opcode, for instance \$32, instead of STOP to force an illegal opcode reset.

How to Reach Us:

Home Page:

www.freescale.com

Web Support:

<http://www.freescale.com/support>

USA/Europe or Locations Not Listed:

Freescale Semiconductor
Technical Information Center, EL516
2100 East Elliot Road
Tempe, Arizona 85284
+1-800-521-6274 or +1-480-768-2130
www.freescale.com/support

Europe, Middle East, and Africa:

Freescale Halbleiter Deutschland GmbH
Technical Information Center
Schatzbogen 7
81829 Muenchen, Germany
+44 1296 380 456 (English)
+46 8 52200080 (English)
+49 89 92103 559 (German)
+33 1 69 35 48 48 (French)
www.freescale.com/support

Japan:

Freescale Semiconductor Japan Ltd.
Headquarters
ARCO Tower 15F
1-8-1, Shimo-Meguro, Meguro-ku,
Tokyo 153-0064
Japan
0120 191014 or +81 3 5437 9125
support.japan@freescale.com

Asia/Pacific:

Freescale Semiconductor China Ltd.
Exchange Building 23F
No. 118 Jianguo Road
Chaoyang District
Beijing 100022
China
+86 10 5879 8000
support.asia@freescale.com

For Literature Requests Only:

Freescale Semiconductor Literature Distribution Center
1-800-441-2447 or +1-303-675-2140
Fax: +1-303-675-2150
LDCForFreescaleSemiconductor@hibbertgroup.com

Information in this document is provided solely to enable system and software implementers to use Freescale Semiconductors products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits or integrated circuits based on the information in this document.

Freescale Semiconductor reserves the right to make changes without further notice to any products herein. Freescale Semiconductor makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does Freescale Semiconductor assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in Freescale Semiconductor data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals", must be validated for each customer application by customer's technical experts. Freescale Semiconductor does not convey any license under its patent rights nor the rights of others. Freescale Semiconductor products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which failure of the Freescale Semiconductor product could create a situation where personal injury or death may occur. Should Buyer purchase or use Freescale Semiconductor products for any such unintended or unauthorized application, Buyer shall indemnify Freescale Semiconductor and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claims alleges that Freescale Semiconductor was negligent regarding the design or manufacture of the part.

RoHS-compliant and/or Pb-free versions of Freescale products have the functionality and electrical characteristics as their non-RoHS-compliant and/or non-Pb-free counterparts. For further information, see <http://www.freescale.com> or contact your Freescale sales representative.

For information on Freescale's Environmental Products program, go to <http://www.freescale.com/epp>.

Freescale™ and the Freescale logo are trademarks of Freescale Semiconductor, Inc. All other product or service names are the property of their respective owners.

© 2010 Freescale Semiconductor.