

LPCXpresso USB Link 2 Driver Release History

Release History

v2.0.2

Removed un-necessary files that were installed as part of v2.01

Removed conditional checks - all drivers are installed on all machines (ARM, 32-bit, 64-bit, all OSes). File restructuring and installer cleanup.

v2.0.1

Fixed an issue where the VCOM driver in this package would not be used if an older package installed it first

Added more drivers with this installer. Other applications can now use this single installer.

v2.0.0

Internal release only, not released publicly

v1.0.2

Fix an issue with the VCOM driver not enumerating correctly. Tested on Win7x64, Win8x64, and WinXP (emulated) platforms.

v1.0.1

Installer update only - publisher verification

v1.0.0



How to Reach Us

Home Page: www.nxp.com

Web Support: www.nxp.com/support

USA/Europe or Locations Not Listed:

NXP Semiconductor

Technical Information Center, EL516

2100 East Elliot Road

Tempe, Arizona 85284

+1-800-521-6274 or +1-480-768-2130

www.nxp.com/support

Europe, Middle East, and Africa:

NXP Halbleiter Deutschland GmbH

Technical Information Center

Schatzbogen 7

81829 Muenchen, Germany

+44 1296 380 456 (English)

+46 8 52200080 (English)

+49 89 92103 559 (German)

+33 1 69 35 48 48 (French)

www.nxp.com/support

Japan:

NXP Semiconductor

ARCO Tower 15F

1-8-1, Shimo-Meguro, Meguro-ku,

Tokyo 153-0064, Japan

0120 191014 or +81 3 5437 9125

support.japan@nxp.com

Asia/Pacific:

NXP Semiconductor Hong Kong Ltd.

Technical Information Center

2 Dai King Street

Tai Po Industrial Estate

Tai Po, N.T., Hong Kong

+800 2666 8080

support.asia@nxp.com
