

2017 Product Discontinuation - 201701040DN

NXP Semiconductors

Jan. 31, 2017

| Discontinued Orderable Part Number | Discontinued Part 12NC | Discontinued Part Number | Discontinued Part Description | Package Outline | Package Name | Discontinuation Type | Availability | Source | Last Time Buy Date | Last Time Delivery Date | Replacement Orderable Part# | Replacement 12NC | Replacement Part Number | Replacement Part Description | Remarks |
|------------------------------------|------------------------|--------------------------|--------------------------------|-----------------|--------------|----------------------|----------------------|-------------|--------------------|-------------------------|-----------------------------|------------------|-------------------------|------------------------------|---|
| "BFG403W,115" | 934047450115 | BFG403W | NPN 17 GHz wideband transistor | SOT343R | DFP4 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | "BFU610F,115" | 934064608115 | BFU610F | "6TH GEN WB TRS, SIGEC" | |
| "BFG410W,115" | 934047460115 | BFG410W | NPN 22 GHz wideband transistor | SOT343R | DFP4 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | "BFU610F,115" | 934064608115 | BFU610F | "6TH GEN WB TRS, SIGEC" | |
| "BFG410W,135" | 934047460135 | BFG410W | NPN 22 GHz wideband transistor | SOT343R | DFP4 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | "BFU610F,115" | 934064608115 | BFU610F | "6TH GEN WB TRS, SIGEC" | |
| MC08XS6421EK | 934070679574 | MC08XS6421EK | Quad High Side Switch | | HSOP32 | Version Withdrawal | Standard End of Life | Sole Source | 30-Jan-2018 | 30-Jan-2019 | MC08XS6421BEK | 934070614574 | MC08XS6421BEK | Quad High Side Switch | Part number MC08XS6421EK (D08D21) is obsolete and is replaced by MC08XS6421BEK |
| MC08XS6421EKR2 | 934070679518 | MC08XS6421EK | Quad High Side Switch | | HSOP32 | Version Withdrawal | Standard End of Life | Sole Source | 30-Jan-2018 | 30-Jan-2019 | MC08XS6421BEKR2 | 934070614518 | MC08XS6421BEK | Quad High Side Switch | Part number MC08XS6421EKR2 (D08D21) is obsolete and is replaced by MC08XS6421BEKR2 |
| MC17XS6400EK | 934070669574 | MC17XS6400EK | Quad High Side Switch | | HSOP32 | Version Withdrawal | Standard End of Life | Sole Source | 30-Jan-2018 | 30-Jan-2019 | MC17XS6400BEK | 934070559574 | MC17XS6400BEK | Quad High Side Switch | Part number MC17XS6400EK (Q17) is obsolete and is replaced by MC17XS6400BEK |
| MC17XS6400EKR2 | 934070669518 | MC17XS6400EK | Quad High Side Switch | | HSOP32 | Version Withdrawal | Standard End of Life | Sole Source | 30-Jan-2018 | 30-Jan-2019 | MC17XS6400BEKR2 | 934070559518 | MC17XS6400BEK | Quad High Side Switch | Part number MC17XS6400EKR2 (Q17) is obsolete and is replaced by MC17XS6400BEKR2 |
| MC40XS6500EK | 934070672574 | MC40XS6500EK | Penta High Side Switch | | HSOP32 | Version Withdrawal | Standard End of Life | Sole Source | 30-Jan-2018 | 30-Jan-2019 | MC40XS6500BEK | 934070564574 | MC40XS6500BEK | Penta High Side Switch | Part number MC40XS6500EK (P40) is obsolete and is replaced by MC40XS6500BEK |
| MC40XS6500EKR2 | 934070672518 | MC40XS6500EK | Penta High Side Switch | | HSOP32 | Version Withdrawal | Standard End of Life | Sole Source | 30-Jan-2018 | 30-Jan-2019 | MC40XS6500BEKR2 | 934070564518 | MC40XS6500BEK | Penta High Side Switch | Part number MC40XS6500EKR2 (P40) is obsolete and is replaced by MC40XS6500BEKR2 |
| MC8640DHX1067NE | 935314127557 | MC8640DHX1067NE | "G8,REV3.0,0.95V,105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640DTHJ1067NE | 935343654557 | MC8640DTHJ1067NE | G8,REV3.0,0.95V,105C | Replacement is lead free die bump with lead spheres |
| MC8640DHX1250HE | 935324318557 | MC8640DHX1250HE | "G8,REV 3.0,1.05V,105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640DTHJ1250HE | 935343655557 | MC8640DTHJ1250HE | G8,REV 3.0,1.05V,105C | Replacement is lead free die bump with lead spheres |
| MC8640DTHX1067NE | 935317136557 | MC8640DTHX1067NE | "G8,REV3.0,0.95V,-40/105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640DTHJ1067NE | 935343656557 | MC8640DTHJ1067NE | G8,REV3.0,0.95V,-40/105C | Replacement is lead free die bump with lead spheres |
| MC8640DTHX1250HE | 935324328557 | MC8640DTHX1250HE | "G8,REV3.0,0.95V,-40/105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640DTHJ1250HE | 935343657557 | MC8640DTHJ1250HE | G8,REV3.0,1.05V,105C | Replacement is lead free die bump with lead spheres |
| MC8640DTHX1000HE | 935319524557 | MC8640DTHX1000HE | "G8,REV3.0,1.05V,-40/105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640DTVJ1000HE | 935323666557 | MC8640DTVJ1000HE | "G8,REV3.0,0.95V,-40/105C" | Due to low volume for lead spheres, these devices are replaced with RoHS compliant lead free versions |
| MC8640HX1067NE | 935317138557 | MC8640HX1067NE | "G8,REV3.0,0.95V,105C" | | CFBGA994 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640HJ1067NE | 935343658557 | MC8640HJ1067NE | G8,REV3.0,0.95V,105C | Replacement is lead free die bump with lead spheres |
| MC8640HX1250HE | 935310305557 | MC8640HX1250HE | "G8,REV3.0,1.05V,105C" | | CFBGA994 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640HJ1250HE | 935343659557 | MC8640HJ1250HE | G8,REV 3.0,1.05V,105C | Replacement is lead free die bump with lead spheres |

2017 Product Discontinuation - 201701040DN

NXP Semiconductors

Jan. 31, 2017

| | | | | | | | | | | | | | | | |
|------------------|--------------|------------------|--------------------------------|----------|----------|--------------------|----------------------|-------------|-------------|-------------|------------------|--------------|------------------|----------------------------|---|
| MC8640THX1067NE | 935310147557 | MC8640THX1067NE | "G8,REV3.0,0.95V,-40/105C" | | CFBGA994 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640THJ1067NE | 935343661557 | MC8640THJ1067NE | G8,REV3.0,0.95V,-40/105C | Replacement is lead free die bump with lead spheres |
| MC8640THX1250HE | 935314246557 | MC8640THX1250HE | "G8,REV3.0,1.05V,-40/105C" | | CFBGA994 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8640THJ1250HE | 935343662557 | MC8640THJ1250HE | G8,REV3.0,1.05V,-40/105C | Replacement is lead free die bump with lead spheres |
| MC8641DTHX1333JE | 935310153557 | MC8641DTHX1333JE | "G8,REV3.0,0.95V,-40/105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8641DTVJ1333JE | 935318396557 | MC8641DTVJ1333JE | "G8,REV3.0,0.95V,-40/105C" | Due to low volume for lead spheres, these devices are replaced with RoHS compliant lead free versions |
| MC8641DHX1333JE | 935310139557 | MC8641DHX1333JE | "G8,REV 3.0,1.05V,105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8641DVJ1333JE | 935322181557 | MC8641DVJ1333JE | "G8,REV 3.0,1.05V,105C" | Due to low volume for lead spheres, these devices are replaced with RoHS compliant lead free versions |
| MC8641DHX1500KE | 935314128557 | MC8641DHX1500KE | "G8, REV 3,1.1V,105C" | | CBGA1023 | Version withdrawal | Non-Manufacturable | Sole Source | 1-Jun-2017 | 31-Dec-2017 | MC8641DVJ1500KE | 935323625557 | MC8641DVJ1500KE | "G8,REV 3.0,1.1V,105C" | Due to low volume for lead spheres, these devices are replaced with RoHS compliant lead free versions |
| "BSR56,215" | 933410740215 | BSR56 | N-channel FET | SOT23 | TO-236AB | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | | | | | |
| "PMBF4392,215" | 933773800215 | PMBF4392 | N-channel FET | SOT23 | TO-236AB | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | | | | | |
| "BFQ149,115" | 933897220115 | BFQ149 | PNP 5 GHz wideband transistor | SOT89 | MPT3 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | | | | | |
| "BFG31,115" | 934000180115 | BFG31 | PNP 5 GHz wideband transistor | SOT223 | SC-73 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | | | | | |
| "BFG21W,115" | 934047480115 | BFG21W | NPN 18 GHz wideband transistor | SOT343R | DFP4 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jun-2017 | 31-Dec-2017 | | | | | |
| BUK9213-60EJ | 934069869118 | BUK9213-60E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| BUK9223-60EJ | 934069871118 | BUK9223-60E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| BUK9214-80EJ | 934069872118 | BUK9214-80E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| BUK9230-80EJ | 934069873118 | BUK9230-80E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| BUK9216-100EJ | 934069874118 | BUK9216-100E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| BUK9234-100EJ | 934069875118 | BUK9234-100E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| BUK929R1-60EJ | 934069876118 | BUK929R1-60E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| BUK9222-100EJ | 934069877118 | BUK9222-100E | Jamie Dyer BL24 | SOT428 | DPAK | Full Withdrawal | Non-Manufacturable | Multiple | 31-Jan-2017 | 31-Jan-2017 | | | | | Not released |
| 74LVT1403DR,112 | 935262846112 | 74LVT1403DR | 74LVT1403 | SOT487-1 | TSSOP32 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74LVT1403DR,118 | 935262846118 | 74LVT1403DR | 74LVT1403 | SOT487-1 | TSSOP32 | Full Withdrawal | Standard End of Life | Sole Source | 30-Jul-2017 | 30-Jan-2018 | | | | | |

2017 Product Discontinuation - 201701040DN

NXP Semiconductors

Jan. 31, 2017

| | | | | | | | | | | | | | | | |
|----------------------|--------------|------------------|-----------------------------------|-----------|-------------|--------------------|----------------------|-------------|-------------|-------------|--|--|--|--|----------------------------|
| CBT16211DGG,112 | 935269707112 | CBT16211DGG | 24BIT BUS SWITCH | SOT364-1 | TSSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| CBT16211DGG,118 | 935269707118 | CBT16211DGG | 24BIT BUS SWITCH | SOT364-1 | TSSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| CBT16211DL,512 | 935269708512 | CBT16211DL | 24BIT BUS SWITCH | SOT371-1 | SSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| CBT16211DL,518 | 935269708518 | CBT16211DL | 24BIT BUS SWITCH | SOT371-1 | SSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| CBTD16211DGG,112 | 935269751112 | CBTD16211DGG | 24BIT BUS SWITCH | SOT364-1 | TSSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| CBTD16211DGG,118 | 935269751118 | CBTD16211DGG | 24BIT BUS SWITCH | SOT364-1 | TSSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| CBTD16211DL,512 | 935269752512 | CBTD16211DL | 24BIT BUS SWITCH | SOT371-1 | SSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| CBTD16211DL,518 | 935269752518 | CBTD16211DL | 24BIT BUS SWITCH | SOT371-1 | SSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| "SAA7709H/N105,518" | 935271156518 | SAA7709H/N105 | DIRAC-2 | SOT318-2 | QFP80 | Version Withdrawal | Standard End of Life | Sole Source | 31-Oct-2017 | 31-Jan-2018 | | | | | Please contact Marketing |
| "SAA7709H/N105,557" | 935271156557 | SAA7709H/N105 | DIRAC-2 | SOT318-2 | QFP80 | Version Withdrawal | Standard End of Life | Sole Source | 31-Oct-2017 | 31-Jan-2018 | | | | | Please contact Marketing |
| 74CBTLV16211DGG,11 | 935284846112 | 74CBTLV16211DGG | 74CBTLV16211DGG | SOT364-1 | TSSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74CBTLV16211DGG,11 | 935284846118 | 74CBTLV16211DGG | 74CBTLV16211DGG | SOT364-1 | TSSOP56 | Full Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| "SAA7709H/N107S,518" | 935289021518 | SAA7709H/N107S | DIRAC-2 | SOT318-2 | QFP80 | Version Withdrawal | Standard End of Life | Sole Source | 31-Oct-2017 | 31-Jan-2018 | | | | | Please contact Marketing |
| "SAA7709H/N107S,557" | 935289021557 | SAA7709H/N107S | DIRAC-2 | SOT318-2 | QFP80 | Version Withdrawal | Standard End of Life | Sole Source | 31-Oct-2017 | 31-Jan-2018 | | | | | Please contact Marketing |
| 74LVC244ABX,115 | 935289828115 | 74LVC244ABX | 3.3V Buf/Drvr Non-Invert 3-State | SOT1045-2 | DHXQFN20(U) | Version Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74LVC245ABX,115 | 935289829115 | 74LVC245ABX | 3.3V Xceiver w/dir pin Non-Invert | SOT1045-2 | DHXQFN20(U) | Version Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74LVCH244ABX,115 | 935289934115 | 74LVCH244ABX | 3.3V Buf/Drvr Non-Invert 3-State | SOT1045-2 | DHXQFN20(U) | Version Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74LVCH245ABX,115 | 935289935115 | 74LVCH245ABX | 3.3V Xceiver w/dir pin Non-Invert | SOT1045-2 | DHXQFN20(U) | Version Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74LVC573ABXX | 935300601115 | 74LVC573ABX | D-latch w/ 5 V tolt I/O's | SOT1045-2 | DHXQFN20(U) | Version Withdrawal | Standard End of Life | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74AHC2G08GD-Q100H | 935307859125 | 74AHC2G08GD-Q100 | Dual 2-input AND gate | SOT996-2 | XSON8(U) | Version Withdrawal | Standard End of Life | Sole Source | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| 74AHC2G32GD-Q100H | 935307861125 | 74AHC2G32GD-Q100 | dual 2-input OR gate | SOT996-2 | XSON8(U) | Version Withdrawal | Standard End of Life | Sole Source | 30-Jul-2017 | 30-Jan-2018 | | | | | |
| S912ZVML64F1MKHR | 935312248528 | S912ZVML64F1MKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |

2017 Product Discontinuation - 201701040DN

NXP Semiconductors

Jan. 31, 2017

| | | | | | | | | | | | | | | | |
|------------------|--------------|-----------------|----------------------------|--|---------|-----------------|--------------------|----------|-------------|-------------|--|--|--|--|----------------------------|
| S912ZVML64F1MKH | 935312248557 | S912ZVML64F1MKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F1MKHR | 935312564528 | S912ZVML12F1MKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F1MKH | 935312564557 | S912ZVML12F1MKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F1VKHR | 935312588528 | S912ZVML12F1VKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F1VKH | 935312588557 | S912ZVML12F1VKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML32F1WKHR | 935312636528 | S912ZVML32F1WKH | "S12Z core, 32K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML32F1WKH | 935312636557 | S912ZVML32F1WKH | "S12Z core, 32K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML64F2VKH | 935313143557 | S912ZVML64F2VKH | "S12Z core, 64K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC64F1MKHR | 935315244528 | S912ZVMC64F1MKH | "S12Z core,64K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC64F1MKH | 935315244557 | S912ZVMC64F1MKH | "S12Z core,64K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC12F1WKH | 935316283557 | S912ZVMC12F1WKH | "S12Z core,128K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F2MKHR | 935316305528 | S912ZVML12F2MKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F2MKH | 935316305557 | S912ZVML12F2MKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC12F1MKHR | 935317949528 | S912ZVMC12F1MKH | "S12Z core,128K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC12F1MKH | 935317949557 | S912ZVMC12F1MKH | "S12Z core,128K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F1WKHR | 935318052528 | S912ZVML12F1WKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F1WKH | 935318052557 | S912ZVML12F1WKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML64F2MKHR | 935318489528 | S912ZVML64F2MKH | "S12Z core, 64K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML64F2MKH | 935318489557 | S912ZVML64F2MKH | "S12Z core, 64K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC64F1VKH | 935318547557 | S912ZVMC64F1VKH | "S12Z core,64K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML64F1WKHR | 935320389528 | S912ZVML64F1WKH | "S12Z core, 64K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML64F1WKH | 935320389557 | S912ZVML64F1WKH | "S12Z core, 64K Flash" | | HLQFP64 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |

2017 Product Discontinuation - 201701040DN

NXP Semiconductors

Jan. 31, 2017

| | | | | | | | | | | | | | | | |
|------------------|--------------|-----------------|-------------------------------|--|---------|--------------------|----------------------------|----------|-------------|-------------|--|--|--|--|----------------------------|
| S912ZVML64F2WKHR | 935320695528 | S912ZVML64F2WKH | "S12Z core, 64K Flash" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML64F2WKH | 935320695557 | S912ZVML64F2WKH | "S12Z core, 64K Flash" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F2WKHR | 935320718528 | S912ZVML12F2WKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML12F2WKH | 935320718557 | S912ZVML12F2WKH | "S12Z core, 128K Flash" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC64F1WKH | 935323664557 | S912ZVMC64F1WKH | "S12Z core,64K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC12F2WKHR | 935323729528 | S912ZVMC12F2WKH | "S12Z core,128K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVMC12F2WKH | 935323729557 | S912ZVMC12F2WKH | "S12Z core,128K Flash,CAN" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML32F1MKHR | 935323865528 | S912ZVML32F1MKH | "S12Z core, 32K Flash" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |
| S912ZVML32F1MKH | 935323865557 | S912ZVML32F1MKH | "S12Z core, 32K Flash" | | HLQFP64 | Full Withdrawal | Non- Manufacturab le | Multiple | 30-Jul-2017 | 30-Jan-2018 | | | | | Replace by Carcassonne 3.3 |